

Trans-cab Auto Services Pte Ltd
 No. 2 Ang Mo Kio Street 63 Singapore 569111
 Tel No.: 6287 6666 Fax No.: 6257 1330
 CO./GST Reg. No. 201019626G
SHD23T

Not Authorized AAD2110-076
Return B4 paid

Vehicle No.:
 Chassis No.:
 Vehicle Make:
 Vehicle Model:
 Date of Accident :
 Third Party Insurer :
 Date of Registration:

19 OCT 2021

SHD23T
 JTDKB3FU103092491
 TOYOTA
 PRIUS GEN 4
 15/10/2021
 CHINA
 30/09/2021

PART	LIST
1 COVER, FRONT BUMPER	\$ <i>R</i> 521.00 ✓
1 MOULDING, FRONT BUMPER SIDE, RH	\$ <i>CM</i> 95.60 ✓
1 GRILLE, RADIATOR, LOWER NO.1	\$ <i>Sn</i> 178.60 X
1 BRACKET, FRONT BUMPER EXTENSION MOUNTING	\$ <i>R</i> 110.50 X
1 REINFORCEMENT SUB-ASSY, FRONT BUMPER	\$ <i>R</i> 716.60 X
1 ABSORBER, FRONT BUMPER ENERGY	\$ <i>Sn</i> 80.20 X
1 SUPPORT, FRONT BUMPER SIDE, RH	\$ <i>ori</i> 80.10 ✓
1 EXTENSION, FRONT BUMPER, RH	\$ <i>Sn</i> 120.10 X
1 UNIT ASSY, HEADLAMP, RH	\$ <i>CM</i> 2,637.60 ✓
1 JAR ASSY, WINDSHIELD WASHER	\$ <i>Sn</i> 219.10 X
1 FENDER SUB-ASSY, FRONT RH	\$ <i>Sn</i> 977.80 ✓
1 LINER, FRONT FENDER, RH	\$ <i>Sn</i> 202.50 X
1 EMBLEM, SIDE PANEL	\$ <i>na</i> 54.60 ✓
1 PILLAR, FRONT BODY, UPPER OUTER RH	\$ <i>R</i> 350.00 X
TOTAL	\$ 6,344.30
25%	\$ 1,586.08
	\$ 4,758.23

Special Nett

1SET BUMPER CLIP FRT	\$ <i>na</i> 95.00 <i>50sn</i>
1 FRONT FENDER CLIP	\$ <i>na</i> 85.00 X
1SET CLIP, FRONT FENDER LINER	\$ <i>na</i> 85.00 X
1SET FRNT BUMPER RETAINER CLIP	
TOTAL	\$ 265.00
TOTAL PARTS	\$ 5,023.23

LABOUR

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

AAD2110-076

SHD23T

To remove and refit interior fittings, trimmings, garnish, fittings and other, to enable repair.	\$	nn 380.00	X
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	2,200.00	400/
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	nn 380.00	X
To remove and refit electrical wiring, battery and other necessary items to facilitate bodywork repair.	\$	nn 480.00	X
To transfer of Fender fittings, attachments and perform water seepage test.	\$	nn 480.00	X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	nn 380.00	X
To check steering geometry and computer wheel alignment	\$	nn 220.00	X
To Rust-Proofing and apply undercoat Of The Affected Areas.	\$	250.00	30/
Putty And Spray Painting Of The Affected Portion.	\$	2,200.00	660/
To reinstall rear bumper parking sensor.	\$	nn 170.00	X
To Check Electrical Lighting Concerned.	\$	170.00	20/
To transfer of luggage floor panel fittings, attachment and perform water seepage test.	\$	nn 380.00	X
To transfer of tire, rim and on wheel balancing.	\$	nn 220.00	X
To remove and refit radiator support cross-member and other necessary items to enable bodywork repair.	\$	nn 380.00	X

Trans-cab Auto Services Pte Ltd**AAD2110-076**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD23T

To conduct and perform a comprehensive vehicle diagnostic check
and reset vehicle warning indicators.

	\$	380.00	X
TOTAL	\$	8,670.00	

Over All Total	\$	13,693.23
-----------------------	----	------------------

(PART-BY-PART) Repair Days**25-DAYS****2 1/2 days****LKK Auto Consultants hence notify
the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer**Signature:****Date:**

Make/Model

Toyota

Model

Pro

Variant

SOF HATCHBACK (AUTO)

Exact purpose for which vehicle was being used at time of

Private use

accident

Are you claiming under your own insurance policy for repair to your vehicle?

No - Repairing only

Damage Category

Taxi

Program Book

No

ID

1967

Additional Comments

Name of Insurance Company

AXA Insurance Pte Ltd

Type of Coverage

Third Party

Excess Policy

Yes

Policy Number

VWZ/17241200

Cover Start Number

1967