

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Reg. No: 19960/198R GST Reg. No. 19-960/198-R					
Affiliated to Federation Internationale Des Experts En Automobile					
	AUTO & GENERA	L INSURANCE (S) PL	Ref:	CS/AGI21010804/Dtf3n2	
		TINSURANCE) U AVENUE #03-01 PPING CENTRESINGAPORE	Date:	01/06/2022	
			Code	AGI	
1.	Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SJP 5102D	Veh. Inspected	SHC 8473E	
	Policy No.		Coverage (\$)	0.00	
	Claim No.	C10012135/EE	Excess (\$)	0.00	
	Assign From	FRAULEINE KHOO	Assign Date	21/10/2021	
2.	2. Vehicle Particulars & Condition				
	Make & Model	HYUNDAI 140	c.c	1685	
	Engine No.	HIDDEN	Year of Reg.	2015	
	Chassis No.	KMHLB41UMGU080668	Colour	BLUE	
	Odometer	689452 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	NIL	
	General	GOOD			
3. Conditions of Tyres					
		Size	Make	Balance	
	R/H Front Tyre	205/60 R16	WEST LAKE	5 mm	
	L/H Front Tyre	205/60 R16	WEST LAKE	5 mm	
	R/H Rear Tyre	205/60 R16	WEST LAKE	5 mm	
	L/H Rear Tyre	205/60 R16	WEST LAKE	5 mm	
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION.				
	DAMAGES SEE DETAILS.				
5.	5. General Information				
	Accident Date	18/10/2021	Inspection Date	21/10/2021	
	Survey held at	BLK 9 SECTOR C #01-42, SIN MING INDUSTRIAL ESTATE			
	Repairer	BIFROST AUTO PTE LTD			
5a.	Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	D)III ACCONDAIN	Estimate Days of Repair			

5 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR: