

# EFFICIENT MOTOR & ENGINEERING WORKS PTE LTD

56 LOYANG WAY # 06-07 ENTERPRISE BUILDING SINGAPORE 508775

VEHICLE NO : SKX9490C  
 MAKE & MODEL : TOYOTA COROLLA ALTIS 1.6 AUTO  
 CHASSIS NO : MR053ZEE106126771

DATE : 20/10/2021  
 CLAIM TYPE : TP CLAIM  
 D.O.A : 19/10/2021

TO : AXA INSUARANCE PTE LTD

## ADJUSTMENT ON REPAIR COST & REPLACEMENT OF PARTS

S/No.	QTY	DESCRIPTION	CONDITION / REMARKS	UNIT LIST PRICE	TOTAL LIST PRICE
1	1	REAR BUMPER / RR		\$ 612.00	\$ 612.00 ✓
2	2	REAR BUMPER REFLECTOR LH / RH X nn		\$ 50.60	\$ 101.20 ✓
3	2	REAR BUMPER SIDE RETAINER LH/RH / RR		\$ 61.70	\$ 123.40 ✓
4	2	REAR BUMPER SIDE RETAINER NO. 2 LH/RH / RR		\$ 38.60	\$ 77.20 ✓
5	2	REAR BUMPER UPPER RETAINER LH / RH / RR		\$ 60.30	\$ 120.60 ✓
6	1	REAR BUMPER SPONGE / RR		\$ 142.60	\$ 142.60 ✓
7	2	REAR REINFORCEMENT BRACKET LH / RH / DD		\$ 92.00	\$ 184.00 ✓
8	1	BOOTLID / DD		\$ 873.60	\$ 773.60 ✓
9	2	BOOTLID HINGE LH / RH X nn		\$ 78.60	\$ 157.20 ✓
10	1	BOOTLID LOCK ASSY / nn		\$ 111.80	\$ 111.80 ✓
11	2	BOOTLID REFLECTOR LH / RH / CRA		\$ 225.80	\$ 451.60 ✓
12	1	BOOTLID CHROME MOULDING X nn		\$ 269.30	\$ 269.30 ✓
13	1	BOOTLID EMBLEM 1.6 / ncc		\$ 45.80	\$ 45.80 ✓
14	1	BOOTLID EMBLEM ALTIS / nn		\$ 49.10	\$ 49.10 ✓
15	1	BOOTLID EMBLEM COROLLA / ncc		\$ 48.20	\$ 48.20 ✓
16	1	BOOTLID EMBLEM LOGO / ncc		\$ 60.50	\$ 60.50 ✓
17	1	BOOTLID WEATHERSTRIP / TM		\$ 194.20	\$ 194.20 ✓
18	2	TAILLAMP LH / RH / CVT		\$ 250.10	\$ 500.20 ✓
19	1	TAILLAMP PANEL LH X R		\$ 87.30	\$ 87.30 ✓
20	1	TAILLAMP PANEL RH X R		\$ 87.30	\$ 87.30 ✓
21	1	REAR END PANEL / DD		\$ 670.00	\$ 670.00 ✓
22	1	REAR END PANEL GARNISH / CRA		\$ 213.80	\$ 213.80 ✓
23	1	SPARE WHEEL PANEL / DD		\$ 818.10	\$ 818.10 ✓
24	1	SPARE WHEEL TOP BOARD / TM		\$ 291.50	\$ 291.50 ✓
25	1	REAR FENDER LH X R		\$ 1,082.80	\$ 1,082.80 ✓
26	1	REAR FENDER RH X R		\$ 1,082.80	\$ 1,082.80 ✓
				\$ 7,598.40	\$ 8,456.10

5488.20  
 - 25%  
 4116.15

TOTAL PRICE	\$ 8,456.10
LESS 25%	\$ 2,114.03
SUB TOTAL PRICE	\$ 6,342.08

S/No.	QTY	DESCRIPTION	CONDITION / REMARKS	UNIT S/NETT	TOTAL S/NETT
1	1	REAR BUMPER CLIP SET / ncc		\$ 50.00	\$ 50.00 ✓
2	1	REVERSE SENSOR / RR		\$ 200.00	\$ 200.00 ✓
3	1	REAR NO. PLATE / CVT		\$ 50.00	\$ 50.00 ✓

TOTAL S/NETT \$ 300.00 \$ 300.00

265

**Labour Charges**

1	To cut/weld, panel beat & align Rear portion, to remove & replace damaged parts.	\$	1,500.00	1700
2	To apply anti rust coat and Tuff Kote repaired areas.	\$	100.00	30
3	To check and rectify lighting & wiring.	\$	80.00	30
4	To remove & replace reverse sensor.	\$	100.00	50
5	To remove & refit spare tyre, interior trims to facilitate the repair.	\$	100.00	
6	To putty, spray painting rear bumper, rear end panel, bootlid, spare wheel panel, rear fender lh/rh & other affected areas.	\$	1,600.00	1000
7	To transfer bootlid components to new bootlid.	\$	150.00	50
8	To remove & refit exhaust system to assist workload.	\$	100.00	30

TOTAL LABOUR **24.20**  
 Total Cost of Repairs  
 (Total parts + Total S/Nett + Total Labour Cost)  
 \$ 3,730.00  
**\$ 10,372.08**

Steve (LKK)  
26/10/21, 10:00am

Wm RL  
L/S  
My AL sy  
10 days

L/S - Auto Consultants hence notify the Repairer of the following:  
 • To resurvey before/after spray painting  
 • To display damaged part(s) during resurvey  
 • Part prices are subject to confirmation  
 • The survey is on a "Without Prejudice" basis  
 • A total modification(s) is allowed  
 • Any ancillary item(s) must be resurveyed and is subject to final approval from Insurance Company  
 Acknowledged by Repairer  
 Signature  
 Date

6801-15  
L/S - 5440.92  
= 5400