

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/EG121010808/NQF3E2

Date: 09/03/2022

REFERENCE

Handling Insurer: ERGO Insurance Pte. Ltd. Policy No:
Claimant Vehicle No : SJP4291Y **Insured Vehicle No :** GBB5623K
Date of Loss: 30/03/2021 Nature of Claim: TP Claim No: CDMCG21000660

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJP4291Y**
Make & Model: MITSUBISHI LANCER, 1.5 MIVEC GLS 4A/T (A) Engine No: 4A910125164
Reg. Date: 25/03/2009 (Man. Year: 2009) Chassis No: JMYSRCY2A9U004079
Colour: Black Odometer: 181064 km
Engine Capacity: 1499 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/60R16 Rear Tyre Size: 205/60R16
Front Left Side: Michelin 8 mm Rear Left Side: Michelin 8 mm
Front Right Side: Michelin 8 mm Rear Right Side: Michelin 8 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|-------------------------------|-----------------|---------------|---------------|--------------|
| Parts | 730.40 | 462.00 | 268.40 | 36.75 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 404.78 | 404.78 | 0.00 | 0.00 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Gross Total (S\$) | 1,135.18 | 866.78 | 268.40 | 23.64 |
| + GST 7.00/7.00% (S\$) | 79.46 | 60.67 | 18.79 | 23.65 |
| Nett Amount (S\$) | 1,214.64 | 927.45 | 287.19 | 23.64 |

INSPECTION

Date of Assignment: 21/10/2021
Date Inspected: 17/11/2021 Inspected At: Mova Automotive Pte Ltd (Bukit Merah)
Blk 1008, #01-04/06/08/94, Bukit Merah Lane 3
Singapore 159722
Estimated Period of Repair: 3.0 days

Adjuster: Muhammad Nazril Bin Abdullah

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

THE VEHICLE HAS NOT SEND IN FOR REPAIRS.

(REPAIR COST NOT CONCLUDE)

(EXCLUDE CHECK ITEMS S\$26.40 NETT)

REPAIR DETAILS

| | | |
|---------------|--|--|
| Reference | | |
| Part Source: | MRM-SG | Version: 1.0 (Last Synchronised: 09 Mar 2022) |
| Parts: | 143 | mitsubishi LANCER 1.5 MIVEC GLS 4A/T (A) (Catalogue:Merimen Singapore 1.0) |
| Labour: | Repairer's | (Price-denominated Standard List) |
| Print Code: | (Unsubmitted, no print-code for SJP4291Y) | |
| Validity: | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page | |
| Further Info: | Items/values not in reference catalogue are prefixed with an asterisk *. | |

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|---|-----|----------|----------------------------|---------------|------------|-------------------|
| 1 | 1 | | *FRONT BUMPER COVER (WCP) | Deformed | 420.00 F | *420.00 F |
| 2 | 1 | | *GRILLE (WCP) | Not Necessary | 160.00 F | *- F |
| 3 | 1 | | *L/F BUMPER BRACKET (WCP) | * Check | 12.00 F | *- F |
| 4 | 1 | | *LWR RADIATOR GRILLE (WCP) | Not Necessary | 60.00 F | *- F |
| 5 | 1 | | *R/F BUMPER BRACKET (WCP) | * Check | 12.00 F | *- F |
| | | | | | | F=Franchise part. |
| Sub Total (\$\$) | | | | | 664.00 | 420.00 |
| + Margin on L,N Items 10.00/10.00% (\$\$) | | | | | 66.40 | 42.00 |
| Total Parts (\$\$) | | | | | 730.40 | 462.00 |

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|---------------------------------|-----------------------------------|----------|---------------|---------------|
| Labour Items | | | | |
| 1 | AUDATEX FEE | New | 40.00 | 40.00 |
| 2 | TOTAL 22.0 WU X 45.00 SGD/H | New | 99.00 | 99.00 |
| 3 | LABOUR COST 36.0 WU X 45.00 SGD/H | New | 162.00 | 162.00 |
| 4 | MATERIAL COST | New | 103.78 | 103.78 |
| Gross Labour Cost (\$\$) | | | 404.78 | 404.78 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >