

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SME 4433C

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	TAILGATE LID B160 BADGE (N)	NOT NECESSARY	80.00	-
1	TAILGATE LID CENTRE LOGO STAR BADGE (N)	NOT NECESSARY	50.00	-
1	REAR BUMPER (N)	TO REPAIR SEE LABOUR	1,610.00	-
2	REAR BUMPER CHROME MOULDING @\$125.00 (N)	NOT FITTED	250.00	-
2	REAR BUMPER REFLECTOR @\$195.00 (N)	NOT FITTED	390.00	-
1	REAR BUMPER LOWER DIFFUSER (N)	GRAZED	200.00	200.00
2	REAR BUMPER SIDE RETAINER @\$60.00 (N)	NOT NECESSARY	120.00	-
1	REAR BUMPER TOP SKID PLATE (N)	NOT FITTED	285.00	-
4	REAR BUMPER CLIP @\$7.00 (N)	NOT NECESSARY	28.00	-
1	REAR BUMPER REINFORCEMENT (N)	NOT NECESSARY	660.00	-
1	REAR END PANEL (N)	TO REPAIR SEE LABOUR	780.00	-
	LESS 10% DISCOUNT		-445.30	-20.00
			4,007.70	180.00
	SPECIAL NETT ITEMS			
1	SET REAR BUMPER PARKING SENSOR (SN)	NOT FITTED	550.00	-
			550.00	-
	<u>LABOUR</u>			
	TO REINSTALL OF REAR BUMPER PARKING SENSOR.	NOT NECESSARY	120.00	-
	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMMINGS,GARNISH AND OTHER,TO ENABLE REPAIR.	NOT NECESSARY	60.00	-
	TO CHECK ELECTRICAL LIGHTING CONCERNED.		60.00	20.00
	PANEL BEATING,KNOCKING AND STRAIGHTEN THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME.INCLUSIVE OF THE REPAIR OF REAR BUMPER AND REAR END PANEL.		750.00	500.00
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		750.00	400.00
			1,740.00	920.00
	GRAND TOTAL		6,297.70	1,100.00

Report Ref No. CS/AGI21010821/Utf3n2



Page No.:2 of 2

RECOMMENDED COST OF REPAIRS		1,100.00
-----------------------------	--	----------

Report Ref No. CS/AGI21010821/Utf3n2

CHUA KANG SENG
Licensed Appraiser