

SIN HWEE MOTOR PTE LTD

ESTIMATE

*** Main Workshop ***

Blk 3023A Ubi Road 1 #01-59 S(408717)

*** Spray Paint Workshop @ Autobay ***

1 Kaki Bukit Avenue 6, #01-25 S(417883)

REG NO: 201327079M

TAY JIA JIA REGINA

HS. AOTong

not AOTong
21/10/21
Edyheh Behu paly.
32yrs. --- L/S #2700

DATE	20/10/2021
VEHICLE NO:	SMF 7559 Z
MAKE:	MAZDA
MODEL:	CX 5

QUANTITY	DESCRIPTION	UNIT	AMOUNT
1 PC	REAR BUMPER		1,287.10
1 PC	TOW HOOK COVER		38.44
1 PC	BUMPER REINFORCEMENT		675.87
1 PC	REVERSE SENSOR		264.77
1 PC	END PANEL		664.18
1 PC	END PANEL TOP GARNISH		151.24
1 PC	WEATHER STRIP		265.77
1 PC	CENTER LOGO		45.78
1 PC	SKYACTIVE LOGO		46.41
1 PC	CX5 LOGO		47.95
1 pc	Lock sensor		271.41
	SUBTOTAL		3,487.51
LESS 20%	LESS 20%	-20.00%	-697.50

-	TO REMOVE AND REFIX INNER TRIMS, BOARDS AND FITTINGS TO FACILITATE REPAIR WORK	180.00	180.00
-	TO ALIGN AND INSTALL REVERSE SENSORS	120.00	120.00
-	TO REPLACE END PANEL INCLUDE KNOCKING AND WELDING TO KNOCK REAR BOOTLID	800.00	800.00
-	TO REPLACE, INSTALL AND ALIGN AFFECTED PARTS TO SYMMETRICAL SPEC		
-	TO SPRAY PAINT END PANEL, REAR BUMPER, BOOTLID AND FLOORBOARD	850.00	850.00
-	TO SUPPLY AND TUFF KOTE	120.00	120.00
-	TO CARRY OUT WIRE CHECKING	120.00	120.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Tel: 6745 5783 Fax: 6744 9582

Email: sinhwemotor@gmail.com

Website: www.sinhwemotor.com

TOTAL \$4,980.01

P-2267.01
202
P-181360
L-1570
3383.6=2706.