

FASTECH AUTO PTE LTD
 1 Kaki Bukit Ave 6 #01-48 Autobay
 Singapore 417883
 Tel No: 67452063/ 67467158 Fax No: 67458520
 Tax Reg No : 200006262D

Wu Hsiao Long

Not Authorized
 Lue
 21/10/21
 1/5 \$5000/
 4 days

VEHICLE No: SLZ 5999G

1PC	REAR BUMPER TOP	De/4wi	1907	\$2,850.00	✓
1PC	REAR BUMPER LOWER	De/7wi	1196	\$1,680.00	✓
2PCS	REAR BUMPER REFLECTORS @\$145.00	n1		\$290.00	X
4PCS	REAR BUMPER PDC SENSORS @\$242.00	shoked	484	\$968.00	2pcs
1SET	REAR BUMPER PDC SENSOR WIRE	SVC		\$288.00	X
1PC	REAR BUMPER INNER RETAINER	CNA		\$205.00	✓
1PC	REAR BUMPER BEAM	Bent	981	\$981.00	✓
2PCS	REAR BUMPER SIDE HOLDERS @\$150.00	n1		\$300.00	X
1SET	REAR BUMPER CLIPS	new		\$50.00	✓
1PC	REAR END PANEL OUTER	R		\$298.00	X
1PC	REAR EXHAUST	n1		\$1,850.00	X
1PC	REAR EXHAUST HEAT SHIELD	Bent	285	\$366.00	✓
				\$10,126.00	

TO CHECK WIRING
 TO DISMANTLE & REPLACED REAR PDC SENSOR
 TO RESET & REPROGRAMME DIAGNOSIS SYSTEM
 TO SPRAY RUST PROOFING
 TO DISMANTLE & REFIX CUSHION UPHOLSTERY
 LABOUR FOR PANEL BEATING & REPLACED PARTS
 TO PUTTY & SPRAY PANITING

\$50.00 20
 \$80.00 50
 \$180.00 100
 n1 \$60.00 X
 \$120.00 80
 \$880.00 550
 \$1,080.00 600
 TOTAL \$12,576.00

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

2- \$108
 52
 4852.6
 1400
 6252.6
 202
 5002