

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21010827/T1QY3N2**Date:** 30/11/2021**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNW00119502000

Claimant Vehicle No : FBB817B **Insured Vehicle No :** GBG9830B

Date of Loss: 08/10/2021 Nature of Claim: TP Claim No: SNM21D205769/C02/LEWLC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **FBB817B**

Make & Model: YAMAHA T150, 150cc Engine No: G3P3E0001084

Reg. Date: 13/01/2020 (Man. Year: 2019) Chassis No: MH3UG131000001100

Colour: Black Odometer: 0 km

Engine Capacity: 150 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 70/90 R17 Rear Tyre Size: 90/80 R17

Front Left Side: Dunlop 5 mm Rear Left Side: Dunlop 5 mm

Front Right Side: 0 mm Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,425.00	895.50	529.50	37.16
Miscellaneous Items	0.00	0.00	0.00	
Labour	580.00	200.00	380.00	65.52
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	2,005.00	1,095.50	909.50	45.36

INSPECTION

Date of Assignment: 21/10/2021

Date Inspected: 26/10/2021 Inspected At: Hkl Lim Team Motorsport (HQ)
BLK 1008 #01-24 BUKIT MERAH LANE 3
Singapore 159722

Estimated Period of Repair: 3.0 days

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 29 Nov 2021)	
Parts:	N/A	YAMAHA T150 150cc (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBB817B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*PILOT LIGHT PANEL	Cut	70.00 F	*70.00 FL
2	1		*FRONT SIGNALS LH	Cut	80.00 F	*80.00 FL
3	1		*HANDLE BAR	Bent	120.00 F	*120.00 FL
4	1		*HANDLE BAR BALANCER LH	Cut	30.00 F	*20.00 FL
5	1		*CLUTCH LEVER	Bent	25.00 F	*25.00 FL
6	1		*SIDE MIRROR	Cut	45.00 F	*45.00 FL
7	1		*GEAR PEDAL	Bent	60.00 F	*60.00 FL
8	1		*FRONT FOOT REST LH	Dented	55.00 F	*55.00 FL
9	1		*FRONT FOOT REST BRACKET	Bent	95.00 F	*95.00 FL
10	1		*TAILBOARD LH	Cracked	150.00 F	*150.00 FL
11	1		*HEAD COWLING	Cut	130.00 F	*130.00 FL
12	1		*REAR SUSPENSION (RCB)	Not Necessary	420.00 F	*- FL
13	1		*COVER SET STICKER	Necessary	120.00 F	*120.00 FL
14	1		*HANDLE GRIP	Cut	25.00 F	*25.00 FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	1,425.00	995.00
- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	99.50
Total Parts (\$\$)	1,425.00	895.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR	New	580.00	200.00
Gross Labour Cost (\$\$)			580.00	200.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >