

ASS. REC. BY:

Taufik

REF:

CS/CT121060827/T. q y3

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____


Claims No. **SNM21D205769/C02**

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of Inspection.Bal. or Market Value: **\$10K**

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: **3** days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS **WP**Date: _____ Person Contacted: **James** Vehicle: IN / OUT

Veh No:

FBB817B

Yr Regn:

2020, Jan.

Type: M.Gar / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Yamaha T150c.c. **150**

Colour

Black

A/C: Insured / Std / NI / NA

Sp. Reading

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

MH346131000.0110

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

70/90 R17

R:

90/80 R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

5 mm

R/Bal.

5 mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

D.O.I.

26/10/21

Survey held at

AKL Bm.

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

27/10/21 @ 3.56pm revised to Jenny Lew via Merimen.

25/11/21 @ 5.01pm Taufikh finalised final fig \$1095.50, 3 days. (Red \$909.50, 45%)

Date/Time, File Pass to?



: Preli. Report

1) 26/11 Typist



: Final Report

Date/Time, File Return to?

2)

Report Format:

MER-TP

Lump Sum / L.B.A. (P)

1095.50Days Of Repair: **3**Resurvey No. of Trip: **1**

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech. Invs (\$



: Weekend (\$

Survey Fee:

Transportation:

S + RS. \$

Photos

Others

TOTAL



HKL LIM
TEAM MOTORSPORT

Blk 1008 #01-24, Bukit Merah Lane 3, Singapore 159722 Tel: 6275 6656, 6275 6566, 62727292 Fax: 6272 9291
Email: support@hklimmotorsport.com.sg Website: www.hklimmotorsport.com.sg

FBB817B

- | | | |
|----|---|--|
| 1 | PILOT LIGHT PANEL | |
| 2 | FRONT SIGNALS LH | |
| 3 | HANDLE BAR | |
| 4 | HANDLE BAR GRP Balancer LH. \$20 | |
| 5 | CLUTCH LEVER | |
| 6 | SIDE MIRROR | |
| 7 | GEAR PEDAL | |
| 8 | FRONT FOOT REST LH | |
| 9 | FRONT FOOT REST BRACKET | |
| 10 | TAILBOARD LH | |
| 11 | HEAD COWLING | |
| 12 | REAR SUSPENSION (RCB) | |
| 13 | COVER SET STICKER | |
| 14 | LABOUR | |

\$70^{int} ✓
\$80^{int} ✓
\$120 ³?
\$30 20^{int} ✓
\$25^{ht} ✓
\$45 ^{int} ✓
\$60 ^{bt} ✓
\$55 ²⁴ ✓
\$95 ^{bt} ✓
\$150 ^{cm} ✓
\$130 ^{int} ✓
420^x ✓
120 ^{ng} ✓
580 200 ✓

TOTAL AMOUNT:

\$1,980

Taufik 97495749
'WP' 26/10/21 @ 230 pm
new parts
p/p Resurvey after repair
Taufik @ 11hant.com
3-4 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: