

國際汽車維修 KT MOTORWERK

Blk 3012 Bedok Ind. Park E #01-2020 Singapore 489978.
(Bedok North Ave. 4) Tel: 98287487 Fax: 6448 5177
Email: ktmotorwerk@hotmail.com
Reg. No.: 53373462B

Vehicle Number : SLF7626A
Vehicle Model : TOYOTA ESTIMA HYBRID
Accident Date : 27.07.2021
Original Reg Date : 23.03.2011

Date : 25.10.2021
Chassis : AHR207053429
TP Ins. : FIRST CAPITAL

Xiao Tong.

ESTIMATE

1	1 pc	Bonnet		698.70	+
2	1 pc	Bonnet Inner Lock		126.80	+
3	1 pc	Front Wiper Garnish		198.70	+
4	1 set	Front Wiper Garnish Clip		30.00	+
5	1 pc	Front Grille		595.60	+
6	1 pc	Front Grille Outer Garnish		298.80	+
7	1 set	Front Grille Clips		30.00	+
8	1 pc	Front Grille Top Rubber		86.20	+
9	1 pc	Front Grille Badge		98.70	+
10	1 pc	Headlamp (HID)		1,345.60	✓
11	1 sets	Headlamp Clips		30.00	✓
12	1 pc	Front Bumper		1,793.80	✓ 1350
13	1 pc	Front Bumper Side Retainers		98.70	✓
14	1 set	Front Bumper Clips		50.00	✓ 30
15	1 pc	Front Bumper Reinforcement		387.50	+
16	1 pc	Front Bumper reinforcement bracket		198.70	✓ 161
17	1 pc	Front Bumper Lower Grille		272.20	+
18	1 pc	Front Bumper Tow Cover		50.70	+
19	1 pc	Front Bumper Fog Lamp RH		468.50	+
20	1 pc	Front Bumper Fog Lamp Cover RH		95.60	+
21	1 pc	Front Bumper Fog Lamp Bracket RH		125.50	✓
22	1 pc	Front Bumper Bottom Cover		156.10	+
23	1 set	Front Bumper Bottom Cover Clips		30.00	+
24	1 pc	Support Panel		897.50	+
25	1 pc	Support Panel Top Garnish		325.70	+
26	1 set	Support Panel Top Garnish Clips		40.00	+
27	1 pc	Wiper Tank		157.30	✓
28	1 pc	Wiper Tank Neck		42.60	+
29	1 pc	Wiper Tank Cap		30.20	+
30	1 pc	Wiper Tank Motor		195.90	+
31	1 pc	Front Fender RH		563.20	✓
32	2 pc	Front Fender Inner Shield RH	198.60	397.20	✓ 198.60
33	2 set	Front Fender Inner Shield Clips	30.00	60.00	✓ 30
34	1 pc	Front Door Protector RH		497.50	+
35	1 pc	Front Absorber RH		497.90	+
36	1 pc	Front Absorber Top Mounting RH		186.70	+

37	1 pc	Front Lower Arm RH			589.30	+
38	1 pc	Front Knuckle Arm RH			474.30	+
39	1 pc	Front Wheel Bearing RH			427.90	+
40	1 pc	Front Anti Roll Bar RH	Nol		397.60	+
41	2 pcs	Front Anti Roll Bar Bush	Nel	48.00	96.00	+
42	1 pc	Front Anti Roll Bar Link RH			187.50	+
43	1 pc	Front Drive Shaft RH			1,378.20	+
44	1 pc	Steering Rack and Pinion			1,757.90	+

16,466.80

4089.90

Less 25% 4,116.70

12,350.10

3067.42

Special Nett

1	1 pc	Front Sport Rim RH	Cat		950.00	580
2	1 pc	Front Sport Rim Tyre RH	Nol Nel		250.00	120

1 set front fender sound proof Nel 700

Labour charge

Panel Beating		1,600.00	600
Spray painting		1,600.00	500
Check Wiring on headlamp		120.00	30
Anti rust		100.00	40
Remove and install front undercarriage.		250.00	1250
To perform computerize wheel alignment.		120.00	80

\$ 17,340.10

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Adrian L
1/s 26/10/21

04 Days

Total 5017.42
1/s : 4K

4K