

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Vimimala

Date: 25 Oct 2021

Preliminary Advice

Vehicle No	: SMQ1205B	Accident Date	: 19/10/2021
Make	: BMW X1	Policy No.	: 80481333QMY
Assignment Date	: 21/10/2021	Excess	: S\$500.00
Date of Inspection	: 22/10/2021	Est. Duration of Repair	: 6
Inspection At	: FALCON-AIR AUTO SERVICES PTE LTD (TAMPINES) BLK 9006 #01-200 TAMPINES ST 93 SINGAPORE		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	16,717.98
Revised Amount	:S\$	8,106.40
Check Items (Estimated)	:S\$	5,882.00
Total	:S\$	13,988.40

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	124,000.00
COE / PARF Rebate	:S\$	63,425.00
Salvage Value	:S\$	
Margin for Repair	:S\$	60,575.00

Remarks

- (X) The vehicle is economical for repair
 () The vehicle is not economical for repair
 (X) Part-by-Part repair
 () Lump Sum repair
- (X) The above survey was conducted on a 'without prejudice' basis.