

國際汽車維修
KT MOTORWERK
 Blk 3012 Bedok Ind. Park E #01-2020 Singapore 489978.
 (Bedok North Ave. 4) Tel: 98287487 Fax: 6448 5177
 Email: ktmotorwerk@hotmail.com
 Reg. No.: 53373462B

Vehicle Number : SLJ9653L
 Vehicle Model : MAZDA 2 SEDAN
 Accident Date : 20.10.2021
 Original Reg Date : 30.12.2016

Date : 21.10.2021
 Chassis : MM6DL2SAAGW197169
 TP INS. BUDGET DIRECT

Denise

ESTIMATE

1	1 pc	Boot Lid <i>Regis</i>			964.50	+
2	1 pc	Boot Lid Badge <i>Neu</i>			96.70	✓
3	1 pc	Boot Lid Emblem MAZDA	2	nec	96.20	✓
4	1 pc	Boot Lid Emblem 2			90.70	✓
5	1 pc	Boot Lid Emblem SKYACTIV	1	nn	92.30	+
6	2 pcs	Boot Lid Lamps	2		285.60	+
7	2 pcs	Boot Lid Lamps Inner Sealer	1		38.00	+
8	2 set	Boot Lid Lamp Clips	1		25.00	+
9	2 pcs	Boot Lid Stopper	1		18.00	+
10	1 pc	Boot Lid Inner Lock	2		183.20	+
11	1 pc	Boot Lid SMART KEY SENSOR	1	rem	185.60	+
12	1 pc	Boot Lid Lock Catch	1		46.20	+
13	1 pc	Boot Lid Weatherstrip	1	let	198.60	✓
14	1 pc	Boot Lid Insulator	3	let	292.30	+
15	1 set	Boot Lid Insulator Clips	1		40.00	+
16	2 pcs	Boot Lid Hinges	1	Not nec	125.90	+
17	1 pc	Rear Bumper	1	Defect	956.30	✓
18	2 pcs	Rear Bumper Side Retainers	1	Neu	65.90	✓
19	1 set	Rear Bumper Clips	1	Neu	50.00	30
21	2 pcs	Rear Bumper Reflector	1	Neu	70.40	+
22	2 pcs	Taillamps	1	RT Cracked	398.50	398.50
23	2 pcs	Taillamps Inner Sealer	1	Neu	38.00	76.00
24	2 set	Taillamps Clips	1	Neu	25.00	50.00
26	1 pc	End Panel	1	Defected	695.50	✓
27	1 pc	End Panel Top Trim	1	Defect	135.70	✓
28	1 set	End Panel Top Trim Clips	1	Neu	30.00	10
29	1 pc	Spare Tyre Panel Top Board	1	Neu	352.00	+
30	1 pc	Spare Tyre Panel Top Tool Sponge	1	Not nec	168.90	+

Subtotal 6,855.30

PARTS DISC LESS 20% 5,484.24

2870

2296

Special Nett

1	1 set	Body Panel Joint Sealant <i>new</i>		120.00	<i>60</i>
2	1 set	Reverse Sensor <i>Damaged</i>		250.00	<i>20</i>

260

Labour charge

Panel Beating		1,200.00	<i>600</i>
Spray painting		1,200.00	<i>600</i>
Check Wiring on tailamps		120.00	<i>30</i>
Anti rust		120.00	<i>60</i>
Remove and install interior upholstery		120.00	<i>60</i>
Remove and install reverse sensor		120.00	<i>50</i>

1400

TOTAL

8,734.24

Adrian Lj
L/S 22/10/21
04 days

total: 3956
L/S: 3.1K ✓

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____