

國際汽車維修 KT MOTORWERK

Blk 3012 Bedok Ind. Park E #01-2020 Singapore 489978.
(Bedok North Ave. 4) Tel: 98287487 Fax: 6448 5177
Email: ktmotorwerk@hotmail.com
Reg. No.: 53373462B

Vehicle Number : SLJ9653L
Vehicle Model : MAZDA 2 SEDAN
Accident Date : 20.10.2021
Original Reg Date : 30.12.2016

Date : 21.10.2021
Chassis : MM6DL2SAAGW197169
TP INS. BUDGET DIRECT

Denise

ESTIMATE

| | | | | | | |
|----------------------------|-------|---|--|--------|-----------------|--------|
| 1 | 1 pc | Boot Lid <i>Regr</i> | | | 964.50 | + |
| 2 | 1 pc | Boot Lid Badge <i>Neu</i> | | | 96.70 | ✓ |
| 3 | 1 pc | Boot Lid Emblem MAZDA | | | 96.20 | ✓ |
| 4 | 1 pc | Boot Lid Emblem 2 | | | 90.70 | ✓ |
| 5 | 1 pc | Boot Lid Emblem SKYACTIV | | | 92.30 | + |
| 6 | 2 pcs | Boot Lid Lamps | | 285.60 | 571.20 | + |
| 7 | 2 pcs | Boot Lid Lamps Inner Sealer | | 38.00 | 76.00 | + |
| 8 | 2 set | Boot Lid Lamp Clips | | 25.00 | 50.00 | + |
| 9 | 2 pcs | Boot Lid Stopper | | 18.00 | 36.00 | + |
| 10 | 1 pc | Boot Lid Inner Lock | | | 183.20 | + |
| 11 | 1 pc | Boot Lid SMART KEY SENSOR | | | 185.60 | + |
| 12 | 1 pc | Boot Lid Lock Catch | | | 46.20 | + |
| 13 | 1 pc | Boot Lid Weatherstrip <i>let</i> | | | 198.60 | ✓ |
| 14 | 1 pc | Boot Lid Insulator | | | 292.30 | + |
| 15 | 1 set | Boot Lid Insulator Clips | | | 40.00 | + |
| 16 | 2 pcs | Boot Lid Hinges <i>Neu Neu</i> | | 125.90 | 251.80 | + |
| 17 | 1 pc | Rear Bumper <i>Rehnd</i> | | | 956.30 | ✓ |
| 18 | 2 pcs | Rear Bumper Side Retainers <i>Neu</i> | | 65.90 | 131.80 | ✓ |
| 19 | 1 set | Rear Bumper Clips <i>Neu</i> | | | 50.00 | 30 |
| 21 | 2 pcs | Rear Bumper Reflector <i>Neu Neu</i> | | 70.40 | 140.80 | + |
| 22 | 2 pcs | Taillamps <i>RH Grubd</i> | | 398.50 | 797.00 | 398.50 |
| 23 | 2 pcs | Taillamps Inner Sealer <i>Neu</i> | | 38.00 | 76.00 | 20 |
| 24 | 2 set | Taillamps Clips <i>Neu</i> | | 25.00 | 50.00 | 10 |
| 26 | 1 pc | End Panel <i>Dented</i> | | | 695.50 | ✓ |
| 27 | 1 pc | End Panel Top Trim <i>Rehnd</i> | | | 135.70 | ✓ |
| 28 | 1 set | End Panel Top Trim Clips <i>Neu</i> | | | 30.00 | 10 |
| 29 | 1 pc | Spare Tyre Panel Top Board <i>Neu Neu</i> | | | 352.00 | + |
| 30 | 1 pc | Spare Tyre Panel Top Tool Sponge <i>Neu Neu</i> | | | 168.90 | + |
| Subtotal | | | | | 6,855.30 | |
| PARTS DISC LESS 20% | | | | | 5,484.24 | |

2870

2296

Special Nett

| | | | | |
|---|-------|-------------------------------------|--------|-----------|
| 1 | 1 set | Body Panel Joint Sealant <i>new</i> | 120.00 | <i>60</i> |
| 2 | 1 set | Reverse Sensor <i>Damaged</i> | 250.00 | <i>20</i> |

260

Labour charge

| | | |
|--|----------|------------|
| Panel Beating | 1,200.00 | <i>600</i> |
| Spray painting | 1,200.00 | <i>600</i> |
| Check Wiring on tailamps | 120.00 | <i>30</i> |
| Anti rust | 120.00 | <i>60</i> |
| Remove and install interior upholstery | 120.00 | <i>60</i> |
| Remove and install reverse sensor | 120.00 | <i>50</i> |

1400

TOTAL

8,734.24

*Adrian Lij
L/S 22/10/21
04 days*

*total: 3956
L/S: 3.1K ✓*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: