

ASS. REC. BY:

REF:

A/G/ 210108391ke

C

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s Tans Cab

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 04 days Res.: Yes or NoLum Sum: 1-B.1 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: Smx 3929X Yr Regn: 01, 21Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Traller or

Make: Toy Pirus c.c. 1788Colour: M.P. White A/C: Insured / Std / NI / NASp. Reading: 36855 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JTDKCB3FU 903 092853Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModl: Nil / S/Rlm / STD / Rlm orTyre Size: F: 195/65R15

R: _____

BS DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

R/Bal. 5 mmL/Bal. 5 mmD.O.A. 15/10/21

Rear

R/Bal. 4 mmL/Bal. 4 mmD.O.I. 18/10/2021

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

4,825.90

27/10

8

~~4,825.90~~

Cash

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trlp: _____

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

S + RS. SI

Fees

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$

Not Notional
Reserve B4 pricing

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SMX3929X

LAD2110-005

~~8 1270-10~~

\$ 4,825.90

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

15 OCT 2021

SMX3929X

JTDKB3FU903092853

TOYOTA

PRIUS **GEN 4**

15/10/2021

AIG

11/01/2021

PART		LIST	
1	COVER, REAR BUMPER	\$	B 485.60 ✓
1	REINFORCEMENT SUB-ASSY, REAR BUMPER	\$	B 332.70 ✓
1	GUARD, REAR BUMPER, CENTER	\$	B 374.50 ✓
1	COVER, REAR BUMPER, LOWER	\$	Sm 22.00 X
1	RETAINER, REAR BUMPER SIDE, LH	\$	Sm 132.60 X
1	RETAINER, REAR BUMPER SIDE, RH	\$	Sm 132.60 X
1	PANEL SUB-ASSY, BODY LOWER BACK	\$	R 651.00 X
1	COVER, DECK TRIM, REAR	\$	Sm 126.70 X
1	COVER, FLOOR UNDER, NO.2 (RH)	\$	Sm 241.90 X
1	COVER, FLOOR UNDER, NO.1 (LH)	\$	Sm 175.10 X
1	COVER, REAR FLOOR (CTR)	\$	Sm 229.90 ✓
1	PANEL SUB-ASSY, BACK DOOR	\$	B 1,147.80 ✓
1	GARNISH SUB-ASSY, BACK DOOR, OUTSIDE	\$	CM 913.60 ✓
1	STAY ASSY, BACK DOOR, LH	\$	Sm 242.50 X
1	STAY ASSY, BACK DOOR, RH	\$	Sm 242.50 X
1	HINGE ASSY, BACK DOOR, LH	\$	R 61.00 X
1	HINGE ASSY, BACK DOOR, RH	\$	R 61.00 X
1	ORNAMENT SUB-ASSY, BACK DOOR	\$	Sm 47.90 ✓
1	PLATE, LUGGAGE COMPARTMENT DOOR NAME, NO.2	\$	Sm 54.60 ✓
1	PLATE, BACK DOOR NAME, NO.1	\$	Sm 54.60 ✓
TOTAL		\$	5,730.10
25%		\$	1,432.53
		\$	4,297.58

Special Nett

Trans-cab Auto Services Pte Ltd**LAD2110-005**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SMX3929X

- 1SET PARKING AID
 1SET REAR BUMPER CLIP
 1 REAR NUMBER PLATE WITH MOULDING
 1 REAR FLOOR UNDERCOVER CLIP
 1 REAR SPOILER CLIP
 1 BUMPER CENTRE GUARD CLIP
 1 REAR BUMPER PROTECTOR
 1 REAR BUMPER RETAINER CLIP
 2 WINDSCREEN SEALANT
 1 WINDSCREEN MOULDING
 1 WINDSCREEN INNER SPONGE SEAL

\$	<i>Pull Shan</i>	700.00	<i>2205a</i>
\$	<i>nn</i>	85.00	<i>505a</i>
\$	<i>B</i>	200.00	<i>455a</i>
\$	<i>nn</i>	180.00	X
\$	<i>nn</i>	70.00	X
\$	<i>nn</i>	80.00	X
\$	<i>nn</i>	180.00	X
\$	<i>nn</i>	75.00	X <i>80</i>
\$	<i>nn</i>	150.00	<i>805a</i>
\$	<i>nn</i>	200.00	—
\$	<i>nn</i>	130.00	<i>305a</i>
TOTAL		\$	1,570.00

TOTAL PARTS	\$	5,867.58
--------------------	-----------	-----------------

LABOUR

To Rust-Proofing and apply undercoat Of The Affected Areas.	\$	<i>nn</i>	240.00	X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$		380.00	<i>601</i>
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$		2,000.00	<i>5001</i>
To transfer of rear end panel fittings, attachment to facilitate bodywork repair.	\$	<i>nn</i>	380.00	X
Putty And Spray Painting Of The Affected Portion.	\$		1,600.00	<i>6601</i>
To Remove And Refit Rear Big & Small W/Screen Glass To Facilitate Bodywork Repair.	\$		300.00	<i>1801</i>
To reinstall rear bumper parking sensor.	\$		170.00	<i>501</i>

Trans-cab Auto Services Pte Ltd

LAD2110-005

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SMX3929X

To Check Electrical Lighting Concerned.

\$ 170.00 *201***TOTAL** \$ 5,240.00**Over All Total** \$ 11,107.58**(PART-BY-PART) Repair Days**~~20 Days~~*4 days***LKK Auto Consultants hence notify
the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: