



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2207939

3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV Date 23/12/2022
Reference CC6/CTI21010844/Apa3q2
Code CTI

PROFESSIONAL SERVICE FEE

Vehicle No. SML 9922M
Insured Veh. SKP 7175T
Claim No. SNM21D206032/C02
Policy No. DMPCSNA00022092108
Accident Date 13/10/2021
Inspection Date 18/10/2021

Description	Total
Survey Inspection	350.00
Resurvey Inspection	
Digital Photographs	
Transportation	
Subtotal	350.00
GST (7%)	24.50
Grand Total	374.50

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909			Ref: CC6/CTI21010844/Apa3q2	
			Date: 23/12/2022	
			Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SKP 7175T	Veh. Inspected	SML 9922M	
Policy No.	DMPCSN00022092108	Coverage (\$)	0.00	
Claim No.	SNM21D206032/C02	Excess (\$)	0.00	
Assign From		Assign Date	18/10/2021	
2. Vehicle Particulars & Condition				
Make & Model	MAZDA MX-5	c.c	1998	
Engine No.	HIDDEN	Year of Reg.	2019	
Chassis No.	JM6ND2E7AK0300057	Colour	GREEN	
Odometer	29474 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/45 R17	BRIDGESTONE	6 mm	
L/H Front Tyre	215/45 R17	BRIDGESTONE	6 mm	
R/H Rear Tyre	215/45 R17	BRIDGESTONE	6 mm	
L/H Rear Tyre	215/45 R17	BRIDGESTONE	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	13/10/2021	Inspection Date	18/10/2021	
Survey held at	HUA MENG SPRAY PAINTING WORKSHOP 1 KAKI BUKIT AVE 6 #01-61 AUTOBAY SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			2 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SML 9922M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT BUMPER	DEFORMED	1,230.30	1,230.30
2	FRONT BUMPER SIDE HOLDER @\$13.70	NECESSARY	27.40	27.40
1	FRONT BUMPER CENTRE GRILLE	NOT NECESSARY	257.90	-
2	FRONT BUMPER SIDE LAMP @\$858.10	NOT NECESSARY	1,716.20	-
1	FRONT BUMPER REINFORCEMENT	NOT NECESSARY	997.40	-
2	FRONT HEADLAMP @\$4761.50	CRACKED	9,523.00	6,000.00
1	FRONT SUPPORT PANEL	NOT NECESSARY	455.20	-
1	FRONT SUPPORT PANEL TOP COVER	NOT NECESSARY	221.40	-
2	FRONT FENDER INNER SHIELD @\$191.10	NOT NECESSARY	382.20	-
1	FRONT ENGINE LOWER COVER	NOT NECESSARY	377.70	-
	LESS 20% DISCOUNT		-3,037.74	-1,451.54
			12,150.96	5,806.16
<u>SPECIAL NETT ITEMS</u>				
1	FRONT NUMBER PLATE (SN)	NOT NECESSARY	50.00	-
1	SET FRONT BUMPER CLIPS (SN)	NECESSARY	50.00	30.00
2	FRONT FENDER INNER SHIELD CLIPS @\$30.00 (SN)	NOT NECESSARY	60.00	-
1	SET BUMPER STICKER (SN)	NOT NECESSARY	800.00	-
			960.00	30.00
<u>LABOUR</u>				
	TO CHECK WIRING.		50.00	30.00
	REMOVE & REINSTALL AIR CON FILL IN GAS.	NOT NECESSARY	150.00	-
	REMOVE, REPLACE & REPAIR CONSISTENT TO THE ACCIDENT.		1,000.00	200.00
	RESPRAY PAINTING.		500.00	200.00
			1,700.00	430.00
GRAND TOTAL			14,810.96	6,266.16



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			3,100.00
---	--	--	-----------------

Report Ref No. CC6/CTI21010844/Apa3q2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd


51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SML 9922M

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SML 9922M

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

