

HUA MENG SPRAY PAINTING WORKSHOP

1, Kaki Bukit Avenue 6, Blk C #01-61 / 01-34, Singapore 417883

Autobay @ Kaki Bukit

Tel: 6747 8064, 6746 5519 / 9666 9680 Fax: 6743 4896

TP ching.
Asher

ESTIMATE JM6ND2E7AK0300057

Name : LOH YU JUN

Make/Model : MAZDA MX 5

Vehicle No : SML 9922 M

Accident date : 13.10.2021

No	DESCRIPTION	Qty	Amount (\$\$)
List Items			
1	Front bumper <i>behind</i>	1	\$ 1230.30 ✓
2	Front bumper side holder @ \$ 13.70 <i>new</i>	2	\$ 27.40 ✓
3	Front bumper centre grille <i>new</i>	1	\$ 257.50 X
4	Front bumper side lamp @ \$ 858.10 <i>new</i>	2	\$ 1716.20 X
5	Front bumper reinforcement <i>new</i>	1	\$ 997.40 X
6	Front headlamp @ \$ 4761.50 <i>cracked</i>	2	\$ 9523 6000
7	Front support panel <i>new</i>	1	\$ 455.20 X
8	Front support panel top cover <i>new</i>	1	\$ 221.40 X
9	Front fender inner shield @ \$ 191.10 <i>new</i>	2	\$ 382.20 X
10	Front engine lower cover <i>new</i>	1	\$ 377.70 X
			\$
	Less 20% Disc		\$
	Total		\$

Special Nett Items

1	Front number plate <i>new</i>	1	\$ 50.00 X
2	Front bumper clips (1 set) <i>new</i>	1	\$ 30 30
3	Front fender inner shield clips (1 set) <i>new</i>	2	\$ 60 X
4	Bumper sticker (1 set) <i>new</i>	1	\$ 800.00 X
	Total		\$

Labour Cost

1	To check wiring	\$ 50.00 30
2	Remove & reinstall air con fill in gas	\$ 150.00 X
3	Remove ,replace & repair consistent to the accident	\$ 1,000.00 2w
4	Respray painting	\$ 500.00 2w
	Total	\$ 1,700.00

Grand Total

\$

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SK

total: 6266.16

L/S: 5K
02 days