

BODYFIX

NO 10 ANG MO KIO INDUSTRIAL PARK 2A #04-06

AMK AUTOPOINT SINGAPORE 568047

Tel No. : 62571289 Fax No. : 64837432

E-Mail : bodyfix@singnet.com.sg

Tax Reg. No. : 53010635C Buss. Reg. No. : 53010635C

AXA INSURANCE PTE LTD
8 SHENTON WAY #27-01
AXA TOWER SINGAPORE 068811

Attention : Motor Claim Department
Contact : 3387288 Fax No. : 8804838

Estimate : ES211023

Date : 21/10/2021

Vehicle Num. : SMK 947 G

Make/Model : LEXUS IS 250-2009

Chassis/Eng# : JTHBK262502094998/4GR0602174

Accident Date : 21/10/2021

Claim No. :

Reference :

Policy No. :

*Not Notarise
11 Lyr @ 3500k
Penny After Pain
6 days*

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

LIST ITEMS :				
1.	1PC	FRONT DOOR (RH)		
2.	1PC	FRONT DOOR HINGE TOP RH		
3.	1PC	FRONT DOOR HINGE BOTTOM RH		
4.	1PC	FRONT DOOR REGULATOR (RH)		
5.	1PC	FRONT DOOR REGULATOR MOTOR (RH)		
6.	1PC	FRONT DOOR RUBBER (RH)		
7.	1PC	FRONT DOOR CHECKER RH		
8.	RIGHT	FRONT DOOR OUTER MOULDING		
9.	1PC	FRONT DOOR INNER LOCK (RH)		
10.	1PC	WING MIRROR (RH)		
11.	1PC	FRONT FENDER (RH)		
12.	1PC	FRONT FENDER INNER SHEILD (RH)		
13.	10PCS	FRONT FENDER INNER SHIELD CLIPS		
14.	1PC	SIDE SKIRT (RH)		
List TotalS\$:				

LABOUR :

LABOUR TO REPLACE ABOVE PARTS, PANEL BEAT, REPAIR &
RE-ALIGN DAMAGE PARTS

TO PUTTY & SPRAY PAINT FRONT DOOR RIGHT, FRONT FENDER
RIGHT, WING MIRROR COVER RIGHT, SIDESKIRT RIGHT & OTHER
AFFECTED AREAS

Labour Total S\$:

SingDollars : Ten Thousand Three Hundred Forty-Two & Cents Forty Only

E. & O.E.

Total S\$: 10,342.40


for BODYFIX

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: