

MODERN AUTOMOTIVE PTE LTD
BLK 3023A UBI ROAD 1 # 01-61
SINGAPORE 408717

Tel : 6748 4422 / 6745 4422 Fax : 6747- 6720 REG NO 200501102H

MSIG INSURANCE (S) PTE LTD

4 Shenton Way # 21 - 01

SGX Centre 2

Singapore 068807

Hot line : 6827 - 7660

Fax : 6225- 7402 (CLAIM)

Quotation

DATE : 25.10.2021

VEH NO : SJD1593J

MODEL : Suzuki Vitara

D O A : 20.10.2021

YR REF : SMZ7834Z

Denise

Attn : Motor Claim Dept

(pls arrange vehicle survey & check liability)

RE : ESTIMATE FOR ACCIDENT REPAIR SJD1593J (SUZUKI VITARA)

<u>Item</u>	<u>Description</u>	<u>Qty</u>	<u>Amt</u>
NO LIST ITEMS			
1	Rear Bumper <i>Distorted</i>	1	669.10 ✓
2	Rear Bumper Side Holder - LH & RH <i>Neu</i>	2	78.60 ✓
3	Rear End Panel <i>Reis</i>	1	445.00 x
4	Rear End Panel Top Garnish <i>Neu neu</i>	1	170.20 x
5	Tail Lamp - LH & RH <i>Neu neu</i>	2	496.00 x
6	Tailgate <i>Distorted</i>	1	858.10 ✓
7	Tailgate Lock <i>Neu neu</i>	1	125.60 x
8	Tailgate Weatherstripe <i>Neu neu</i>	1	105.40 x
9	Tailgate Glass Moulding <i>Neu</i>	1	75.40 ✓
10	Suzuki Wording <i>3 Neu</i>	1	39.40 ✓
11	Grand Vitara Wording <i>Neu</i>	1	52.50 ✓
12	Spare Tyre Outer Cover <i>Could</i>	1	597.90 ✓
13	Spare Tyre Outer Cover Suzuki Wording <i>Neu</i>	1	120.40 ✓
14	Spare Tyre Inner Cover <i>Could</i>	1	364.20 ✓
15	Spare Tyre Bracket <i>Neu neu</i>	1	196.40 x
16	Rear Exhaust Pipe <i>Reis</i> bt	1	528.70 80(SW)
17	Rear Exhaust Pipe Mounting <i>Neu neu</i>	1	35.00 x
			\$ 4,957.90
			(495.79)
			\$ 4,462.11

Less 10% *15%*

S/NET ITEMS

1	Rear Number Plate <i>3 Neu neu</i>	1	30.00 x
2	Rear Number Plate Holder <i>Neu neu</i>	1	30.00 x
3	Rear Bumper Clips <i>Neu</i>	1	30.00 ✓
4	Reverse Sensor <i>Damaged</i>	1	280.00 200
5	Rear End Panel Sealant <i>Neu neu</i>	1	60.00 x
6	Tailgate Glass Sealant <i>Neu</i>	1	60.00 ✓

290

RE : ESTIMATE FOR ACCIDENT REPAIR SJD1593J (SUZUKI VITARA)

\$ 490.00

Total parts

\$ 4,952.11

LABOUR CHARGE

1	To knocking & pull out rear portion & renew above parts	\$ 1,200.00	650
2	To putty and spray up paint works	\$ 1,000.00	750
3	To check wiring system	\$ 50.00	30
4	To srpay tuff coat	\$ 150.00	80
5	To transfer tailgate fittings	\$ 150.00	80
6	To remove tailgate glass	\$ 180.00	120
7	To remove reverse sensor	\$ 100.00	50
8	To remove exhaust pipe	\$ 150.00	80
		\$ 2,980.00	

GRAND TOTAL

\$ 7,932.11

GST Will be reflected in the final bills

NOTE : -

PLEASE INFORM US WITHIN 14 DAYS, FROM THE DATE OF THIS LETTER, IN THE EVENT THAT THE OWNER/DRIVER IS IN BREACH OF ITS POLICY WITH YOUR COMPANY, FAILING WHICH WE SHALL HOLD YOUR COMPANY LIABLE FOR ALL COSTS OF REPAIRS, LOSS OF USE AND STORAGE.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total: 4617.26

H/S: 3.7K

05 Days