



Rico 60 Auto Services Pte Ltd
 Blk 8 , Kaki Bukit Avenue 4 , #02-24
 Premier @ Kaki Bukit Singapore 415875
 Email: claims@rico60.com
 Tel: 6286 6060 Fax : 6286 7060

TP Chinn
 Veron.

RICO Office Use Only

Parts -%10	
SN	
Labour	
TOTAL	
LUMSUM	
ERV	26K

TO: ~~NTUC~~ CT.
 Vehicle No : SKK 6858 P
 Make & Model : MERCEDES E200 212
 DATE: 21/10/2021

Lfk Abram.

No.	DESCRIPTION - PARTS	QTY	UNIT PRICE	PRICE
1	BOOTLID <i>dented</i>	1	\$ 2,730.00	\$ 2,730.00
2	BOOTLID LOGO <i>Not</i>	1	\$ 125.00	\$ 125.00
3	BOOTLID EMBLEM (E200) <i>2</i>	1	\$ 95.70	\$ 95.70
4	BOOTLID EMBLEM (7 G TRONIC) <i>Not</i>	1	\$ 110.00	\$ 110.00
5	BOOTLID EMBLEM (C&C)	1	\$ 76.00	\$ 76.00
6	BOOTLID LAMP <i>RT cracked</i>	2	\$ 956.00	\$ 1,912.00
7	BOOTLID CHROME MOULDING <i>Not</i>	1	\$ 268.20	\$ 268.20
8	BOOTLID CAR PLATE LAMP GARNISH <i>Not</i>	1	\$ 256.00	\$ 256.00
9	BOOTLID CAR PLATE LAMP LED <i>Not</i>	2	\$ 142.00	\$ 284.00
10	BOOTLID REVERSE CAMERA <i>Not</i>	1	\$ 1,254.00	\$ 1,254.00
11	BOOTLID OPENER SWITCH <i>Not</i>	1	\$ 241.00	\$ 241.00
12	BOOTLID INNER LOCK <i>Not</i>	1	\$ 685.00	\$ 685.00
13	BOOTLID INNER LOCK COVER <i>Not</i>	1	\$ 256.00	\$ 256.00
14	BOOTLID LOCK CATCH GEAR <i>Not</i>	1	\$ 254.00	\$ 254.00
15	BOOTLID LOWER LOCK WITH MOTOR <i>Not</i>	1	\$ 746.00	\$ 746.00
16	BOOTLID WEATHER STRIP <i>Not</i>	1	\$ 298.00	\$ 298.00
17	BOOTLID INNER TRIM <i>Not</i>	1	\$ 379.00	\$ 379.00
18	BOOTLID HINGE <i>Bent</i>	2	\$ 265.70	\$ 531.40
19	BOOTLID HINGE COVER <i>Not</i>	2	\$ 128.00	\$ 256.00
20	BOOTLID HINGE MOTOR ASSY <i>Not</i>	1	\$ 1,548.00	\$ 1,548.00
21	REAR BUMPER <i>Distorted</i>	1	\$ 2,245.00	\$ 2,245.00
22	REAR BUMPER SIDE BRACKET <i>Damaged</i>	2	\$ 167.00	\$ 334.00
23	REAR BUMPER SIDE RETAINER <i>Damaged</i>	2	\$ 178.20	\$ 356.40
24	REAR BUMPER SIDE VENT <i>Not</i>	2	\$ 78.00	\$ 156.00
25	REAR BUMPER CENTER RETAINER <i>Not</i>	1	\$ 256.00	\$ 256.00
26	REAR BUMPER LOWER BRACKET <i>Not</i>	2	\$ 45.00	\$ 90.00
27	REAR BUMPER REINFORCEMENT <i>Dented</i>	1	\$ 790.00	\$ 790.00

✓

✓

✓

✓

✓

390.

x

x

x

+

+

x

+

+

+

+

+

✓

+

+

1380.

-

✓

+

+

+

29	REAR BUMPER DIFFUSER	Deformed	1	\$ 658.00	\$ 658.00	351
30	REAR BUMPER TOW COVER	Not new	1	\$ 67.00	\$ 67.00	+
31	REAR BUMPER PARKING SENSOR	1 piece damaged	6	\$ 389.00	\$ 2,334.00	260.
32	REAR BUMPER PARKING SENSOR HODER	New	6	\$ 55.00	\$ 330.00	150.
33	REAR PARKING SENSOR WIRE HARNESS	Not new	1	\$ 689.00	\$ 689.00	x
34	REAR BLINK SPOT SENSOR	Not new	2	\$ 1,589.00	\$ 3,178.00	+
35	TAIL LAMP	RH Smashed	2	\$ 1,245.00	\$ 2,490.00	790.
36	TAIL LAMP PANEL	Distorted.	2	\$ 122.00	\$ 244.00	✓
37	TAIL LAMP LOWER BRACKET	RH Smashed	2	\$ 185.00	\$ 370.00	45.
38	TAIL LAMP RAILING GARNISH	RH Deformed	2	\$ 199.00	\$ 398.00	121
39	REAR FENDER	Distorted	2	\$ 2,450.00	\$ 4,900.00	✓
40	REAR FENDER INNER HOUSING	RH Distorted	2	\$ 877.50	\$ 1,755.00	877.50
41	REAR FENDER INNER TRIM	torn	2	\$ 689.00	\$ 1,378.00	✓
42	REAR FENDER INNER TRIM DOOR LAMP	Not new	1	\$ 89.00	\$ 89.00	+
43	REAR FENDER COWLING	torn	2	\$ 198.00	\$ 396.00	✓
44	FUEL LID COVER	Distorted	1	\$ 112.50	\$ 112.50	✓
45	FUEL LID COVER BRACKET	Distorted	1	\$ 277.50	\$ 277.50	✓
46	FUEL LID COVER LOCK		1	\$ 320.00	\$ 320.00	✓
47	REAR WINDSCREEN WITH MOULDING	Not new	1	\$ 1,689.00	\$ 1,689.00	+
48	REAR WINDSCREEN INNER SEAL	New	1	\$ 60.00	\$ 60.00	✓
49	REAR ABSORBER	Bent	2	\$ 674.50	\$ 1,349.00	✓
50	REAR UPPER ARM	Bent	2	\$ 378.00	\$ 756.00	✓
51	REAR LOWER ARM	Bent	2	\$ 514.00	\$ 1,028.00	✓
52	REAR CONTROL ARM	Bent	2	\$ 219.50	\$ 439.00	✓
53	REAR ADJUST ARM	Bent	2	\$ 614.00	\$ 1,228.00	✓
54	REAR KNUCKLE ARM	Damaged	2	\$ 1,215.30	\$ 2,430.60	✓
55	REAR WHEEL BEARING		2	\$ 496.40	\$ 992.80	✓
56	REAR DRIVE SHAFT	Not new	2	\$ 2,800.00	\$ 5,600.00	+
57	REAR CROSSMEMBER	Bent	1	\$ 1,775.40	\$ 1,775.40	✓
58	REAR ANTI ROLL BAR	Not new	1	\$ 477.50	\$ 477.50	+
59	REAR ANTI ROLL BAR LINK	Bent	2	\$ 198.40	\$ 396.80	✓
60	REAR WHEEL SPEED SENSOR	Not new	2	\$ 344.90	\$ 689.80	+
61	REAR RIM ORIGINAL	cut	2	\$ 1,245.00	\$ 2,490.00	2000.
62	REAR END PANEL	Regis	1	\$ 1,450.00	\$ 1,450.00	+
63	REAR END PANEL TOP GARNISH	Not new	1	\$ 386.00	\$ 386.00	+
64	REAR FLOOR PANEL	Buckled	1	\$ 845.00	\$ 845.00	✓
65	REAR FLOOR PANEL UNDER COVER SIDE	Not new	2	\$ 124.00	\$ 248.00	+
66	REAR FLOOR PANEL FLOOR MAT	Not new	1	\$ 422.80	\$ 422.80	+
67	REAR FLOOR PANEL TOP BOARD	Not new	1	\$ 698.00	\$ 698.00	+
68	REAR EXHAUST PIPE		2	\$ 1,522.00	\$ 3,044.00	+
69	REAR EXHAUST MOUNTING	Not new	4	\$ 65.00	\$ 260.00	+
70	REAR EXHAUST SUPPORT BRACKET	New	2	\$ 42.00	\$ 84.00	+
71	REAR EXHAUST INSULATOR		2	\$ 256.00	\$ 512.00	+

LABOUR (REAR)	PRICE
PANEL BEATING, REMOVAL AND REPLACING PARTS	\$ 3,200.00 2200
TO SPRAY PAINT AFFECTED AREA	\$ 2,400.00 2000
TUFF COAT	\$ 150.00 ✓
WIRING CHECK	\$ 600.00 300
REMOVE AND REFIX CUSHION SEAT/ UPHOLSTRY AND ROOF LINNING TO FACILITATE REPAIR	\$ 550.00 350
TRANFER BOOTLID MECHANISM	\$ 200.00 80
REMOVE AND INSTALL REAR EXHAUST	\$ 300.00 80
REMOVE , INSTALL AND CHECK REVERSE SENSOR FUCTION	\$ 200.00 50
REMOVE , INSTALL AND CHECK REVERSE CAMERA FUCTION	\$ 200.00 50
REMOVE , INSTALL AND CHECK FOOT SCAN SENSOR FUCTION	\$ 150.00 x.
REMOVE AND INSTALL REAR WINDSCRFEEN	\$ 200.00 120
CONDUCT WATER LEAKAGE TEST	\$ 100.00 x.
REAR CHASSIS ALIGNMENT	\$ 500.00 x.
TO RESET AND REPROGRAM AIR BAG FUCYION AND FAULT CODE	\$ 600.00 200
TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS,RESET MEMORIES TO SPECIFICATION ETC.	\$ 650.00 x.
LABOUR TOTAL	\$ 10,000.00

	Total Parts Cost	\$ 71,325.94
	Total Labour Cost	\$ 10,000.00
	Total Repair Cost	\$ 81,325.94

APPROVED DETAILS

NO. OF WORKING DAYS
PART BY PART OR LUMP SUM
DATE & TIME OF SURVEY
SURVEYED BY
CONTACT NUMBER
FAX NUMBER

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total: 33057.44
4/s: 19.5K-
(Nett Value)
18 Days