

# Vin's

**Vin's Motor Pte Ltd**  
160 Sin Ming Drive  
#03-03 Sin Ming Autocity  
Singapore 575722  
Tel : 6453 2121 Fax : 6459 9795  
GST Registration No. 199906067G

## Estimated Cost of Repair

**Attention To :** China Taiping Insurance  
(Singapore) Pte Ltd  
3 Anson Road  
#15-00 Springleaf Tower  
Singapore 079909

### Claim Details

**Case Ref. No. :** TP/102021/5035  
**Date :** 21-10-2021  
**Accident Date :** 20-10-2021

### Vehicle Details

**Make & Model :** Honda VEZEL HYBRID 1.5 AUTO  
**Chassis No :** RU31272512  
**Registration No :** SNA9274X

### Third Party Vehicle Details

**Registration No :** GBL2158D

| S/N | Description                        | Qty   | Amount (\$\$)              |
|-----|------------------------------------|-------|----------------------------|
| 1   | REAR TAILGATE                      | 1.00  | 953 \$1,100.90 <i>bt</i>   |
| 2   | REAR TAILGATE GLASS MOULDING       | 1.00  | \$120.30 <i>ner</i>        |
| 3   | REAR TAILGATE OUTER GARNISH        | 1.00  | 193.60 \$225.70 <i>de</i>  |
| 4   | REAR TAILGATE OUTER GARNISH EMBLEM | 1.00  | \$20.70 <i>alg</i>         |
| 5   | REAR TAILGATE "VEZEL" EMBLEM       | 1.00  | \$43.20 <i>alg</i>         |
| 6   | REAR TAILGATE "HYBRID" EMBLEM      | 1.00  | \$75.50 <i>alg</i>         |
| 7   | REAR TAILGATE RH REFLECTOR         | 1.00  | \$424.30 <i>aut</i>        |
| 8   | REAR TAILGATE LH REFLECTOR         | 1.00  | \$424.30 <i>aut</i>        |
| 9   | REAR TAILGATE RUBBER               | 1.00  | \$101.30 <i>pu</i>         |
| 10  | REAR TAILGATE LOCK                 | 1.00  | \$256.30 <i>bt</i>         |
| 11  | REAR TAILGATE INNER TRIMBOARD      | 1.00  | \$153.40 <i>ing</i>        |
| 12  | REAR TAILGATE PULL HANDLE COVER    | 1.00  | \$36.20 <i>X nn</i>        |
| 13  | REAR RH TAILLAMP                   | 1.00  | 474.60 \$586.70 <i>aut</i> |
| 14  | REAR LH TAILLAMP                   | 1.00  | 474.60 \$586.70 <i>aut</i> |
| 15  | REAR BUMPER                        | 1.00  | 751 \$829.60 <i>de</i>     |
| 16  | REAR BUMPER RH REFLECTOR           | 1.00  | \$178.50 <i>X nn</i>       |
| 17  | REAR BUMPER LH REFLECTOR           | 1.00  | \$178.50 <i>X nn</i>       |
| 18  | REAR BUMPER CLIPS @ \$3.90         | 10.00 | \$39.00 <i>alg</i>         |
| 19  | REAR BUMPER RH SIDE RETAINER       | 1.00  | \$17.50 <i>X nn</i>        |
| 20  | REAR BUMPER LH SIDE RETAINER       | 1.00  | \$17.50 <i>X nn</i>        |
| 21  | REAR BUMPER ANTENNA SENSOR         | 1.00  | \$68.10 <i>alg</i>         |
| 22  | REAR BUMPER BUZZIE SENSOR          | 1.00  | \$81.20 <i>X nn</i>        |
| 23  | REAR END PANEL                     | 1.00  | \$411.90 <i>Rp</i>         |
| 24  | REAR END PANEL TOP TRIM            | 1.00  | \$98.20 <i>de</i>          |
| 25  | REAR SPARE TYRE TOP COVER          | 1.00  | \$430.30 <i>X nn</i>       |
| 26  | REAR LUGGAGE COMPARTMENT BOX       | 1.00  | \$243.20 <i>alg</i>        |
| 27  | REAR RH FENDER INNER TRIMBOARD     | 1.00  | \$320.10 <i>de</i>         |
| 28  | REAR LH FENDER INNER TRIMBOARD     | 1.00  | \$320.10 <i>X nn</i>       |

*Supp* wiper motor \$205 *bt*

5439.70 \$7,389.20 7594.2  
Discount: -20% 4351.76 (\$1,477.84) 6075.36

# Vin's

**Vin's Motor Pte Ltd**  
 160 Sin Ming Drive  
 #03-03 Sin Ming Autocity  
 Singapore 575722  
 Tel : 6453 2121 Fax : 6459 9795  
 GST Registration No. 199906067G

|    |                                     |      |                         |
|----|-------------------------------------|------|-------------------------|
|    |                                     |      | \$5,911.36              |
| 29 | REAR TAILGATE REVERSE CAMERA        | 1.00 | 280 \$380.00 <i>dis</i> |
| 30 | REAR BUMPER PARKING SENSOR          | 1.00 | \$280.00 <i>200mm</i>   |
| 31 | REAR WINDSCREEN GUM                 | 1.00 | \$60.00 <i>nt</i>       |
| 32 | REAR NO. PLATE                      | 1.00 | \$40.00 <i>ann</i>      |
| 33 | TO REMOVE AND REFIX REAR WINDSCREEN | 1.00 | \$150.00 <i>120</i>     |
| 34 | TO REPAIR REAR DAMAGES              | 1.00 | \$780.00 <i>600</i>     |
| 35 | TO SPRAY PAINTING                   | 1.00 | \$880.00 <i>700</i>     |

Subtotal w/o GST:

\$8,481.36 8645.36  
 1960

Tanfilm 97495749  
 'WP' 22/10/21 @ 1700  
 1/1 *Resurvey before repair* new & old part  
 tanfilm @ 11hant.com  
 6 days  
 4351.76  
 1960  
 6311.76  
 06 days #

**LKK Auto Consultants** hence notify  
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

# Vin's

## Estimated Cost of Repair (Supplementary)

Attention To : China Taiping Insurance  
(Singapore) Pto Ltd  
3 Anson Road  
#15-00 Springleaf Tower  
Singapore 079909

### Claim Details

Case Ref. No. : TP/102021/5035  
Date : 21-10-2021  
Accident Date : 20-10-2021

### Vehicle Details

Make & Model : Honda VEZEL HYBRID 1.5 AUTO  
Chassis No : RU31272512  
Registration No : SNA9274X

### Third Party Vehicle Details

Registration No : GBL2158D

| S/N | Description               | Qty  | Amount (\$\$) |
|-----|---------------------------|------|---------------|
| 1   | REAR TAILGATE WIPER MOTOR | 1.00 | bt ✓ \$205.00 |

Discount: -20%

\$205.00

(\$41.00)

\$164.00

Subtotal w/o GST:

\$164.00