

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0861/2021/ZK
DATE : 20-Oct-21
WIP : 44486

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 22/10/2021

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

Hi Steve

17 days exclude 2 Sundays and 1 PH

Johnny Boo - 22 Dec 21

OWNER'S NAME : MR GHARIWALA AJAYKUMAR JASHVANTAL
ADDRESS : 9 SENGKANG SQUARE
#12-06
SINGAPORE 545075
TELEPHONE : HP +65 98427772
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 1800080689-03
VEHICLE NO : **SMC 6242 J**
MODEL CODE : A5 SPORTBACK 2.0 TFSI S
MODEL YEAR : 12/7/2018
ENGINE NO : CVK 061956
CHASSIS NO : WAUZZZF56JA101878
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 20-Oct-21
PLACE OF ACCIDENT : SLIP ROAD INTO CTE TO MOULMEIN ROAD

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMC 6242 J

S/N	NATURE OF JOBS		ESTIMATED CHARGES		SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE,CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEDLIGHTS,HORNS,OUTSIDE TEMPERATURE SENSOR,HEADLIGHT WASHER ASSY AND FRONT PARKING AID	S/N \$	480.00	\$	480.00
2	TO REMOVE AND TRANSFER RHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$	400.00	\$	250.00
3	TO RENEW AND RENEW AIRCON CONDENSER , CHARGED AIR COOLER AND RADIATOR. TO RENEW ADDITIONAL RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM.TO CARRY OUT VACUUM AND REGAS.	S/N \$	1,700.00	\$	1,700.00
4	TO REMOVE AND REINSTALL RHS FRONT DOOR PANEL TRIM. TO REMOVE AND REINSTALL RHS WING MIRROR ASSY TO FACILITATE RESPRAY OF RHS FRONT DOOR	S/N \$	280.00	\$	280.00
5	TO DISMANTLE AND RENEW FRONT BUMPER , RHS FRONT FENDER , BONNET AND RHS HEADLIGHT. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION.RE-ORGANIZE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	\$	5,600.00	\$	3,000.00
SUB LABOUR CHARGES		:	\$ 8,460.00	\$	5,710.00

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMC 6242 J

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
		<i>C/F</i>		\$ 5,710.00
6	TO RESPRAY FRONT BUMPER , RHS FRONT FENDER , BONNET , HINGES AND RHS FRONT DOOR	\$	4,500.00	\$ 2,200.00
7	TO CARRY OUT PRE/POST DIAGNOSTIC CHECK	S/N \$	384.00	\$ 384.00
8	Added labour - see attached	\$	3,880.00	\$ 2,430.00
9	HEADLIGHT STICKER		TBC	not done
TOTAL LABOUR CHARGES		:	\$ 17,224.00	\$ 10,724.00

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG
MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMC 6242 J

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
1	FRONT BUMPER	1	\$ 2,941.00	\$	2,352.80
2	FRONT BUMPER GRILLE	1	\$ 511.00		
3	FRONT BUMPER AIR GUIDE GRILLE - RH	1	\$ 519.00		
4	FRONT BUMPER AIR GUIDE TRIM - RH	1	\$ 48.00		
5	FRONT BUMPER SENSOR SUPPORT - RH	1	\$ 51.00		
6	FRONT BUMPER AIR GUIDE - RH	1	\$ 63.00		
7	FRONT RADIATOR GRILLE	1	\$ 1,493.00	\$	1,194.40
8	FRONT BUMPER SECURING STRIP	2	\$ 71.00	\$	28.16
9	FRONT BUMPER GUIDE SECTION - RH	1	\$ 36.00	\$	28.72
10	FRONT BUMPER FOAM FILLER PIECE	1	\$ 124.00	\$	99.20
11	FRONT BUMPER CARRIER	1	\$ 845.00	\$	675.60
12	FRONT BUMPER BRACKET - RH	1	\$ 214.00	\$	171.20
13	FRONT BUMPER TOP COVER	1	\$ 127.00	\$	101.60
14	CAUTION STICKER	1	\$ 14.00	\$	10.88
15	AIR - CONDITIONER STICKER	1	\$ 8.00	\$	5.68
16	FRONT BUMPER LOCK CARRIER BRACKET	1	\$ 137.00	\$	109.60
17	FRONT BUMPER SUPPORT - LH / RH	1	\$ 58.00	\$	44.96
18	FRONT PARKING AID SENSOR - INNER / OUTER	2	TBC		
19	FRONT PARKING AID SENSOR SEAL	4	\$ 9.00	\$	7.04
20	HORN - RH	1	\$ 126.00		
SUB TOTAL SPARE PARTS		:	\$ 7,395.00	\$	4,829.84

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMC 6242 J

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
		<i>c/f</i>		<i>\$</i>	<i>4,829.84</i>
21	HORN BRACKER - RH	1	\$ 29.00		
22	FRONT FENDER - RH	1	\$ 1,060.00	<i>\$</i>	<i>848.00</i>
23	FRONT FENDER ATTACHEMENT PART	1	\$ 53.00		
24	FRONT FENDER CLOSING ELEMENT - RH	1	\$ 74.00	<i>\$</i>	<i>59.04</i>
25	FRONT FENDER BRACKET - RH	1	\$ 35.00	<i>\$</i>	<i>27.92</i>
26	FRONT FENDER BRACE - RH	1	\$ 118.00	<i>\$</i>	<i>94.40</i>
27	FRONT FENDER CENTER BRACKET - RH	1	\$ 49.00		
28	FRONT FENDER CHORME TRIM - RH	1	\$ 164.00	<i>\$</i>	<i>130.80</i>
29	FRONT WHEEL HOUSING LINER - RH	1	\$ 275.00		
30	FRONT WHEEL HOUSING LINER ATTACHMENT PARTS	1	\$ 169.00		
31	FRONT WHEEL SPOLIER	1	\$ 73.00		
32	FRONT BUMPER SPOLIER - RH	1	\$ 36.00		
33	FRONT FENDER LEDGE COVER	1	\$ 36.00	<i>\$</i>	<i>28.24</i>
34	FRONT FENDER COVER - RH	1	\$ 16.00	<i>\$</i>	<i>12.24</i>
35	FRONT BONNET	1	\$ 3,312.00	<i>\$</i>	<i>2,649.60</i>
36	FRONT BONNET RETAINING CLIP	3	\$ 4.00	<i>\$</i>	<i>2.64</i>
37	CAP NUT	6	\$ 24.00	<i>\$</i>	<i>19.20</i>
38	FRONT BONNET ATTACHMENT PART	1	\$ 123.00		
39	FRONT BONNET HINGE - LH / RH	2	\$ 838.00		
40	FRONT BONNET IMPACT PROTECTION - CENTER / LH / RH	3	\$ 84.00	<i>\$</i>	<i>65.68</i>
SUB TOTAL SPARE PARTS		:	\$ 6,572.00	<i>\$</i>	<i>8,767.60</i>

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMC 6242 J

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
		<i>c/f</i>		\$ 8,767.60
41	FRONT BONNET INSULATION PAD	1 \$	343.00	\$ 274.40
42	FRONT BONNET STRICKER - RH	1 \$	50.00	\$ 39.92
43	FRONT BONNET LOCK	1 \$	214.00	\$ 170.80
44	FRONT BOWDEN CABLE	2 \$	116.00	\$ 92.00
45	FRONT BOWDEN CABLE COVER	1 \$	10.00	
46	FRONT BONNET RELEASE LEVER	1 \$	14.00	\$ 10.48
47	HEADLIGHT - RH	1 \$	7,902.00	\$ 6,321.60
48	HEADLIGHT POWER MODULE	1 \$	758.00	
49	HEADLIGHT CONTROL UNIT	1 \$	751.00	
50	HEADLIGHT HEAT SINK - RH	1 \$	1,153.00	\$ 922.40
51	HEADLIGHT LIFT CYLINDER - RH	1 \$	198.00	\$ 158.40
52	HEADLIGHT LIFT CYLINDER BRACKET - RH	1 \$	15.00	\$ 11.76
53	HEADLIGHT CORRUGATED PIPE	1 \$	86.00	
54	FRONT RADIATOR LOCK CARRIER	1 \$	1,016.00	\$ 812.80
55	FRONT RADIATOR CORE SUPPORT	1 \$	38.00	\$ 30.32
56	FRONT TEMPERATURE SENSOR BRACKET	1 \$	19.00	\$ 14.56
57	AIR COOLER	1 \$	587.00	
58	AIR COOLER SEAL	1 \$	92.00	
59	AIR COOLER PRESSURE HOSE	1 \$	357.00	
60	AIR CON CONDENSER	1 \$	622.00	\$ 497.60
SUB TOTAL SPARE PARTS			\$ 14,341.00	\$ 18,124.64

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMC 6242 J


			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
		<i>c/f</i>		\$	18,124.64
61	FRONT RADIATOR	1	\$ 904.00	\$	722.80
62	COOLANT	6	\$ 142.00	\$	113.28
63	FAN RING	1	\$ 267.00	\$	213.20
64	RADIATOR FAN WITH CONTROL UNIT	1	\$ 2,318.00		
65	FRONT RADIATOR AIR GUIDE - INNER RH	1	\$ 31.00	\$	24.64
66	FRONT RADIATOR AIR GUIDE - OUTER RH	1	\$ 16.00	\$	12.80
67	FRONT RADIATOR AIR GUIDE - LOWER	1	\$ 22.00		
68	INTAKE AIR DUCT - RH	1	\$ 22.00	\$	17.20
69	ENGINE AIR GUIDE	1	\$ 53.00	\$	42.40
70	AIR FILTER	1	\$ 386.00		
71	AIR INTAKE HOSE	1	\$ 95.00		
72	AIR MASS METER	1	\$ 567.00		
73	NOISE INSULATION	1	\$ 572.00		
74	FRONT DOOR CHROME TRIM - RH	1	\$ 164.00	\$	130.80
75	FRONT NO PLATE (<i>Owner invoice attached</i>)	S/N	\$ 100.00	\$	80.00
76	Added parts - see atatched		\$ 9,184.00	\$	7,271.52
77	Added parts - see atatched			\$	190.40
78	SUNDRIES		\$ 450.00	\$	94.64
TOTAL SPARE PARTS			:	\$ 43,601.00	\$ 27,038.32
TOTAL LABOUR CHARGES			:	\$ 17,224.00	\$ 10,724.00
GRAND TOTAL			:	\$ 60,825.00	\$ 37,762.32

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED

SPARE PARTS ARE SPECIAL NETT.

BL-21/12/21




Supplementary Estimate-1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 / Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0861/2021/ZK 3-Nov-21 CHANG 1 of 1 SMC 6242 J AUDI A5 2.0 TFSI
Quantity	Description	Unit Price	Amount
<u>Labours</u>			
1	TO REMOVE AND TRANSFER LHS HEADLIGHT'S S/N CONTROL UNIT AND POWER MODULE.	\$ 400.00	\$ 250.00
2	TO REPAIR BOTH UPPER A-PILLAR.	\$ 800.00	\$ 250.00
3	TO RESPRAY BOTH UPPER A-PILLAR AMD LHS FRONT DOOR.	\$ 2,400.00	\$ 1,650.00
4	TO REMOVE AND REINSTALL LHS FRONT DOOR S/N PILLAR TRIM. TO REMOVE AND REINSTALL LHS WING MIRROR ASSY TO FACILITATE RESPRAY OF LHS FRONT DOOR.	\$ 280.00 \$ 3,480.00	\$ 280.00 \$ 2,430.00
<u>Parts</u>			
1	FRONT BUMPER WIRING SET	\$ 510.00	\$ 408.00
2	BONNET STRIKER - LH	\$ 50.00	\$ 39.92
3	BONNET LOCK CABLE	\$ 74.00	\$ 58.64
4	FRONT REINFORCEMENT BEAM BRACKET - LH	\$ 214.00	\$ 171.20
5	RADIATOR AIR GUIDE - LH INNER	\$ 32.00	\$ 24.88
6	RADIATOR AIR GUIDE - LH OUTER	\$ 16.00	\$ 12.80
7	RADIATOR AIR GUIDE - CENTER	\$ 16.00	
8	RADIATOR SUPPORT - LH	\$ 76.00	
9	LED HEADLIGHT - LH	\$ 7,902.00	\$ 6,321.60
10	BONNET LOCK - LH	\$ 214.00	\$ 170.80
11	HEADLIGHT COMPENSATING PIECE	\$ 80.00	\$ 63.68
		2	
		Materials	\$ 9,184.00 \$ 7,271.52
		Labour	\$ 3,480.00 \$ 2,430.00
		GRAND TOTAL	\$ 12,664.00 \$ 9,701.52

For Premium Automobiles Pte Ltd

Authorised Signature



Supplementary Estimate-1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 / Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0861/2021/ZK 4-Mar-22 GLORY 1 of 1 SMC 6242 J AUDI A5 2.0 TFSI	
Quantity	Description	Unit Price	Amount	
<u>Parts</u> 1	RADIATOR GRILLE INNER COVER	\$ 238.00	\$ 190.40	
		TOTAL	\$ 238.00	\$ 190.40

For Premium Automobiles Pte Ltd

Authorised Signature

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT