

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0861/2021/ZK
DATE : 20-Oct-21
WIP : 44486

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 22/10/2021

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR GHARIWALA AJAYKUMAR JASHVANTAL
ADDRESS : 9 SENGKANG SQUARE
#12-06
SINGAPORE 545075
TELEPHONE : HP +65 98427772
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 1800080689-03
VEHICLE NO : **SMC 6242 J**
MODEL CODE : A5 SPORTBACK 2.0 TFSI S
MODEL YEAR : 12/7/2018
ENGINE NO : CVK 061956
CHASSIS NO : WAUZZZF56JA101878
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 20-Oct-21
PLACE OF ACCIDENT : SLIP ROAD INTO CTE TO MOULMEIN ROAD

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMC 6242.1

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE,CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEDLIGHTS,HORNS,OUTSIDE TEMPERATURE SENSOR,HEADLIGHT WASHER ASSY AND FRONT PARKING AID	S/N \$ 480.00 /	
2	TO REMOVE AND TRANSFER RHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 400.00 250	
3	TO RENEW AND RENEW AIRCON CONDENSER , CHARGED AIR COOLER AND RADIATOR. TO RENEW ADDITIONAL RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM.TO CARRY OUT VACUUM AND REGAS.	S/N \$ 1,700.00 /	
4	TO REMOVE AND REINSTALL RHS FRONT DOOR PANEL TRIM. TO REMOVE AND REINSTALL RHS WING MIRROR ASSY TO FACILITATE RESPRAY OF RHS FRONT DOOR	S/N \$ 280.00 /	
5	TO DISMANTLE AND RENEW FRONT BUMPER , RHS FRONT FENDER , BONNET AND RHS HEADLIGHT. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION.RE-ORGANIZE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	\$ 5,600.00 3000	
		6 x 500	
	SUB LABOUR CHARGES	\$ 8,460.00	

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699


TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMC 6242 J

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
6	TO RESPRAY FRONT BUMPER, RHS FRONT FENDER, BONNET, HINGES AND RHS FRONT DOOR <i>4 X 350</i>	\$ 4,500.00	<i>2700</i> <i>22</i>
7	TO CARRY OUT PRE/POST DIAGNOSTIC CHECK	S/N \$ 384.00	<i>/</i>
8	HEADLIGHT STICKER	TBC	<i>? X</i>
TOTAL LABOUR CHARGES		: \$ 13,344.00	

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAJ@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMC 6242 J

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
			S/NETT		
1	FRONT BUMPER / BR	1	\$ 2,941.00	2352.80	
2	FRONT BUMPER GRILLE ? x nn	1	\$ 511.00		
3	FRONT BUMPER AIR GUIDE GRILLE - RH / MIS	1	\$ 519.00	NN	
4	FRONT BUMPER AIR GUIDE TRIM - RH ? x nn	1	\$ 48.00		
5	FRONT BUMPER SENSOR SUPPORT - RH ? x nn	1	\$ 51.00		
6	FRONT BUMPER AIR GUIDE - RH ? x nn	1	\$ 63.00		
7	FRONT RADIATOR GRILLE / BR	1	\$ 1194.4	1,493.00	
8	FRONT BUMPER SECURING STRIP (RH) / BR	1	\$ 28.16	71.00	28-16
9	FRONT BUMPER GUIDE SECTION - RH ? / BR	1	\$ 28.72	36.00	
10	FRONT BUMPER FOAM FILLER PIECE / BR	1	\$ 99.2	124.00	
11	FRONT BUMPER CARRIER / BR	1	\$ 675.6	845.00	
12	FRONT BUMPER BRACKET - RH ? / BT	1	\$ 171.2	214.00	
13	FRONT BUMPER TOP COVER / BR	1	\$ 101.6	127.00	
14	CAUTION STICKER / n/c	1	\$ 10.88	14.00	
15	AIR - CONDITIONER STICKER / n/c	1	\$ 5.68	8.00	
16	FRONT BUMPER LOCK CARRIER BRACKET / BR	1	\$ 109.6	137.00	
17	FRONT BUMPER SUPPORT - LH / RH / n/c	1	\$ 44.96	58.00	
18	FRONT PARKING AID SENSOR - INNER / OUTER ? x nn	2		TBC	
19	FRONT PARKING AID SENSOR SEAL / n/c	4	\$ 7.04	9.00	
20	HORN - RH ? x nn	1	\$ 126.00		
SUB TOTAL SPARE PARTS			\$ 7,395.00		

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAJ@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMC 6242 J

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
			S/NETT	REMARKS
21	HORN BRACKER - RH ? X nn	1	\$ 29.00	
22	FRONT FENDER - RH / 00	1	\$ 1,060.00	/ 848
23	FRONT FENDER ATTACHEMENT PART 1pc X nn	1	\$ 53.00	
24	FRONT FENDER CLOSING ELEMENT - RH / 1pc	1	\$ 74.00	/ 59.04
25	FRONT FENDER BRACKET - RH / 1pc	1	\$ 35.00	/ 27.92
26	FRONT FENDER BRACE - RH / 07	1	\$ 118.00	/ 94.4
27	FRONT FENDER CENTER BRACKET - RH ? X nn	1	\$ 49.00	
28	FRONT FENDER CHORME TRIM - RH / 1pc	1	\$ 164.00	/ 130.80
29	FRONT WHEEL HOUSING LINER - RH ? X nn	1	\$ 275.00	
30	FRONT WHEEL HOUSING LINER ATTACHMENT PARTS ? X nn	1	\$ 169.00	
31	FRONT WHEEL SPOILER ? X nn	1	\$ 73.00	
32	FRONT BUMPER SPOILER - RH ? X nn	1	\$ 36.00	
33	FRONT FENDER LEDGE COVER / 1pc	1	\$ 36.00	/ 28.24
34	FRONT FENDER COVER - RH / 1pc	1	\$ 16.00	/ 12.24
35	FRONT BONNET / 00	1	\$ 3,312.00	/ 2649.6
36	FRONT BONNET RETAINING CLIP / 1pc	3	\$ 4.00	/ 2.64
37	CAP NUT / 1pc	6	\$ 24.00	/ 19.2
38	FRONT BONNET ATTACHMENT PART ? X nn	1	\$ 123.00	
39	FRONT BONNET HINGE - LH / RH ? X nn	2	\$ 838.00	
40	FRONT BONNET IMPACT PROTECTION - CENTER / LH / RH / 1pc	3	\$ 84.00	/ 65.68
SUB TOTAL SPARE PARTS		:	\$ 6,572.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. 5MC 6242 J

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
41	FRONT BONNET INSULATION PAD / CR4	1	\$ 343.00 / 274.4	
42	FRONT BONNET STRICKER - RH / BT	1	\$ 50.00 / 39.92	
43	FRONT BONNET LOCK / BT	1	\$ 214.00 / 170.80	
44	FRONT BOWDEN CABLE ? / BT	2	\$ 116.00 / 92	
45	FRONT BOWDEN CABLE COVER ? X nn	1	\$ 10.00	
46	FRONT BONNET RELEASE LEVER ? / TN	1	\$ 14.00 / 10.48	
47	HEADLIGHT - RH / BR	1	\$ 7,902.00 / 6321.60	
48	HEADLIGHT POWER MODULE ? X nn	1	\$ 758.00	
49	HEADLIGHT CONTROL UNIT ? X nn	1	\$ 751.00	
50	HEADLIGHT HEAT SINK - RH / BR	1	\$ 1,153.00 / 922.4	
51	HEADLIGHT LIFT CYLINDER - RH / BR	1	\$ 198.00 / 158.4	
52	HEADLIGHT LIFT CYLINDER BRACKET - RH / BR	1	\$ 15.00 / 11.76	
53	HEADLIGHT CORRUGATED PIPE ? X nn	1	\$ 86.00	
54	FRONT RADIATOR LOCK CARRIER / BR	1	\$ 1,016.00 / 812.8	
55	FRONT RADIATOR CORE SUPPORT ? / BR	1	\$ 38.00 / 30.32	
56	FRONT TEMPERATURE SENSOR BRACKET / MC	1	\$ 19.00 / 14.56	
57	AIR COOLER ? X nn	1	\$ 587.00	
58	AIR COOLER SEAL ? X nn	1	\$ 92.00	
59	AIR COOLER PRESSURE HOSE ? X nn	1	\$ 357.00	
60	AIR CON CONDENSER / DJ	1	\$ 622.00 / 497.60	
SUB TOTAL SPARE PARTS			\$ 14,341.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMC 6242J

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
			S/NETT	REMARKS
61	FRONT RADIATOR / DO	1	\$ 904.00	✓ 722.8
62	COOLANT / MC	6	\$ 142.00	✓ 113.28
63	FAN RING ? / BR	1	\$ 267.00	✓ 213.2
64	RADIATOR FAN WITH CONTROL UNIT ? x nn	1	\$ 2,318.00	
65	FRONT RADIATOR AIR GUIDE - INNER RH / MIS	1	\$ 31.00	✓ 24.64
66	FRONT RADIATOR AIR GUIDE - OUTER RH / BR	1	\$ 16.00	✓ 12.8
67	FRONT RADIATOR AIR GUIDE - LOWER ? x nn	1	\$ 22.00	
68	INTAKE AIR DUCT - RH / BR	1	\$ 22.00	✓ 17.2
69	ENGINE AIR GUIDE / BR	1	\$ 53.00	✓ 42.4
70	AIR FILTER ? x nn	1	\$ 386.00	
71	AIR INTAKE HOSE ? x nn	1	\$ 95.00	
72	AIR MASS METER X nn	1	\$ 567.00	
73	NOISE INSULATION ? x nn	1	\$ 572.00	
74	FRONT DOOR CHROME TRIM - RH / MC	1	\$ 130.8	164.00 ✓
75	FRONT NO PLATE / BT	S/N	\$ 80	100.00 80/
76	SUNDRIES ? / nec		\$ 94.64	450.00 94.64/
TOTAL SPARE PARTS		:	\$ 34,417.00	
TOTAL LABOUR CHARGES		:	\$ 13,344.00	
GRAND TOTAL		:	\$ 47,761.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME
SURVEYED DATE
AUTHORISED DATE
EXCESS COST
LIABILITY
REMARKS

: Steve (LKK)
: 22/10/21, 11.10am

SD- M1 AL
EXCESS- ?
17 ~~th~~ dy
P/P
M BCL dy

PLEASE NOTE

: THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT

PREMIUM AUTOMOBILES

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg



Supplementary Estimate-1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 / Fax: 6256 4315

Estimate No.

Date

Service Advisor

Pages

Regn No

Model No

PA/OD/0861/2021/ZK

3-Nov-21

CHANG

1 of 1

SMC 6242 J

AUDI A5 2.0 TFSI

Quantity	Description	Unit Price	Amount
Labours			
1	TO REMOVE AND TRANSFER LHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE. S/N	\$ 400.00	250
2	TO REPAIR BOTH UPPER A-PILLAR.	\$ 800.00	250
3	TO RESPRAY BOTH UPPER A-PILLAR AND LHS FRONT DOOR.	\$ 2,400.00	1650
4	TO REMOVE AND REINSTALL LHS FRONT DOOR PILLAR TRIM. TO REMOVE AND REINSTALL LHS WING MIRROR ASSY TO FACILITATE RESPRAY OF LHS FRONT DOOR. S/N	\$ 280.00	2430
Parts			
1	FRONT BUMPER WIRING SET - TN	\$ 510.00	✓
2	BONNET STRIKER - LH - OT	\$ 50.00	✓
3	BONNET LOCK CABLE - TN	\$ 74.00	✓
4	FRONT REINFORCEMENT BEAM BRACKET - LH - OT	\$ 214.00	✓
5	RADIATOR AIR GUIDE - LH INNER - OR	\$ 32.00	✓
6	RADIATOR AIR GUIDE - LH OUTER - OR	\$ 16.00	✓
7	RADIATOR AIR GUIDE - CENTER - nn	\$ 16.00	✓
8	RADIATOR SUPPORT - LH - X nn	\$ 76.00	✓
9	LED HEADLIGHT - LH - OR	\$ 7,902.00	✓
10	BONNET LOCK - LH - OT	\$ 214.00	✓
11	HEADLIGHT COMPENSATING PIECE - mis (2)	\$ 80.00	✓
GRAND TOTAL		\$ 13,064.00	

For Premium Automobiles Pte Ltd

Steve
3/11/21

