

PREMIUM AUTOMOBILES

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183
Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg



Supplementary Estimate-1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Mr. Adrian Ling - Motor Claims Dept
Tel: 6841 0055 / Fax: 6256 4315

Estimate No.
Date
Service Advisor
Pages
Regn No
Model No

PA/OD/0861/2021/ZK
3-Nov-21
CHANG
1 of 1
SMC 6242 J
AUDI A5 2.0 TFSI

Quantity	Description	Unit Price	Amount
Labours			
1	TO REMOVE AND TRANSFER LHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE. S/N	\$ 400.00	250
2	TO REPAIR BOTH UPPER A-PILLAR.	\$ 800.00	250
3	TO RESPRAY BOTH UPPER A-PILLAR AND LHS FRONT DOOR.	\$ 2,400.00	1650
4	TO REMOVE AND REINSTALL LHS FRONT DOOR PILLAR TRIM. TO REMOVE AND REINSTALL LHS WING MIRROR ASSY TO FACILITATE RESPRAY OF LHS FRONT DOOR. S/N	\$ 280.00	/
Parts			
1	FRONT BUMPER WIRING SET / TN	\$ 510.00	
2	BONNET STRIKER - LH / OT	\$ 50.00	
3	BONNET LOCK CABLE / TN	\$ 74.00	
4	FRONT REINFORCEMENT BEAM BRACKET - LH / OT	\$ 214.00	
5	RADIATOR AIR GUIDE - LH INNER / OR	\$ 32.00	
6	RADIATOR AIR GUIDE - LH OUTER / OR	\$ 16.00	
7	RADIATOR AIR GUIDE - CENTER X	\$ 16.00	
8	RADIATOR SUPPORT - LH X	\$ 76.00	
9	LED HEADLIGHT - LH / OR	\$ 7,902.00	
10	BONNET LOCK - LH / OT	\$ 214.00	
11	HEADLIGHT COMPENSATING PIECE / MIS (2)	\$ 80.00	
GRAND TOTAL		\$ 13,064.00	

For Premium Automobiles Pte Ltd

Steve
3/11/21

Add 2 days

