



ComfortDelGro Engineering

205 Braddell Road S(579701)

**ACCIDENT REPAIR ESTIMATES**

Our Ref:

Type of Claim : ODVehicle No. : GBD4004TMake & Model : NISSAN NV200 1.5 MTYear of Manufacture : 2014 OCTChassis No. : VSKYBAM20Z0078084Ins Company : MSFCI

Engine No. : \_\_\_\_\_

Excess : \_\_\_\_\_

Policy No. : \_\_\_\_\_

Date of Accident : 12/10/2021

Time of Accident : \_\_\_\_\_

Suggested Days of Repair : \_\_\_\_\_

In-house Vehicle Assessor**Repair Estimates**Case Owner : PATRICK

Signature : \_\_\_\_\_

**Parts (a) Cost / List Price Items** \$ 1,047.00Plus/Less 10% \$ 104.70Total of Cost / List \$ 942.30(b) Nett Price Items \$ -

Less \_\_\_\_\_

Total of Nett Item \_\_\_\_\_

(c) Special Nett Items \$ -**Total Parts Cost (Appendix A)** \$ 942.30**Labour (Appendix B)** \$ 2,130.00**Total Repair Cost** \$ 3,072.30

Contact No

**Frt Counter Operation**

Brenda Tel: 63837730 email: brendang@sparkcarcare.com

Rohani tel: 63837890 email: rohanim@sparkcarcare.com

**Back-end Operation**

Ngo Toh Wee Tel: 63837656 email: ngotw@sparkcarcare.com

Patrick Tel: 63837441 email: patricktia@sparkcarcare.com

*The above total will be subjected to 7% G.S.T.*

Name of Surveyor : \_\_\_\_\_

Company : \_\_\_\_\_

Survey conducted on : \_\_\_\_\_ at \_\_\_\_\_

**Remarks By Surveyor**

(a) The repair of this vehicle is authorized / is not authorized until further notice.

(b) Recommended Days of Repair : \_\_\_\_\_ day(s)

(c) Resurvey : Required / Not Required

(d) Excess : \$ \_\_\_\_\_

(e) Signature of surveyor : \_\_\_\_\_ Date: \_\_\_\_\_

# Spark Car Care

ComfortDelGro Engineering Pte Ltd  
205 Braddell Road S (579701)  
Tel: 63837168 / 63837466 Fax:62815767

## Spare Parts

Vehicle No : GBD4004T Case Owner : PATRICK

Make & Model : NISSAN NV200 1.5 MT Year Manufacture : 2014 OCT

Chassis No : VSKYBAM20Z0078084 Engine No : 0

Sales Order : \_\_\_\_\_ Supplier : \_\_\_\_\_

Order By : \_\_\_\_\_ Type of Claim : OD

S/No	Part Description	QTY	Cost Price	List Price	Nett Price	S/N	Disposition By Surveyor
1	REAR BUMPER	1		\$ 701.00			
2	REAR BUMPER RETAINER RH	1		\$ 38.00			
3	RH TAILLAMP	1		\$ 308.00			
4	0	1					
5	0	1					
6	0	1					
7	0	1					
8	0	1					
9	0	1					
10	0	1					
11	0	1					
12	0	1					
13	0	1					
14	0	1					
15	0	1					
16	0	1					
17	0	1					
18	0	1					
19	0	1					
20	0	1					
21	0	1					
22	0	1					
23	0	1					
24	0	1					
25	0	1					
26	0	1					
27	0	1					
28	0	1					
29	0	1					
30	0	0					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

**ComfortDelGro Engineering Pte Ltd**  
205 Braddell Road S (579701)  
Tel: 63837168 / 63837466 Fax: 62815767

Vehicle No.	: <u><b>GBD4004T</b></u>	Case Owner	: <u><b>PATRICK</b></u>
Make & Model	: <b>NISSAN NV200 1.5 MT</b>	Year of Manufacture	: <b>2014 OCT</b>

*Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.*