



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBD 4004T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER	BUCKLED	701.00	632.70
1	REAR BUMPER RETAINER RH	DISTORTED	38.00	38.00
1	RH TAILLAMP	CRACKED	308.00	277.20
	LESS 10% DISCOUNT		-104.70	-94.79
			942.30	853.11
	<u>LABOUR</u>			
	TO PANEL BEAT ON RH REAR FENDER, RH BACK DOOR, REPLACE DAMAGE PART AND REALIGN AFFECTED AREAS.		700.00	480.00
	TO PUTTY, RESPRAY ON RH REAR FENDER, RH BACK DOOR, REAR END PANEL AND AFFECTED AREAS.		800.00	750.00
	CHECK LIGHTING AND WIRING.		30.00	20.00
	TO REDO ADVERTISEMENT STICKER ON RH REAR FENDER AND RH BACK DOOR.		600.00	400.00
			2,130.00	1,650.00
	GRAND TOTAL		3,072.30	2,503.11

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			2,000.00
LESS EXCESS			-500.00
NETT LIABILITY			1,500.00

Report Ref No. CS/FCI21010861/Ktf3e2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.