

Yew Tee Automobile Tech Pte Ltd (Co.Reg.No.200311009C)

Mega@Woodlands, 39 Woodlands Close #01-12

Singapore 737856

Tel: Fax: Email:

INSURER : AIG ASIA PACIFIC INSURANCE PTE LTD**PARTICULARS OF CLAIM**

Claim Type:	TP	Ref. No:	
Policy No:	5112928627-02	Date of Loss:	11/10/2021
Vehicle Reg. No.:	FBQ4145B	Driveable?	yes
Driver Age:	19/05/1995	Third Party Vehicle No.:	SDM693J
Any Injuries?	yes	Contact No:	91155045
Insured/Claimant:	MUHAMMAD FARHAN BIN SHADON	Driver:	MUHAMMAD FARHAN BIN SHADON

PARTS MODEL

Make/Model:	Yamaha, Sniper T150	Vehicle Reg. Date:	25/09/2019
Vehicle Colour:		Engine Number:	
Chassis No:	MH3UG0740K0153210	Odometer:	
Total Loss?		Est. Duration of Repair(Day)	

DESCRIPTION OF ACCIDENT/LOSS

Description of Accident/loss COLLISION - MAJOR/ MINOR RD
 Remarks:
 Present Location: Yew Tee Automobile Tech Pte Ltd (Mega)-YTMG

COST OF CLAIMS

	Amount
Parts	3,654.00
Miscellaneous Items	350.00
Labour	780.00
Paintwork Labour	350.00
Towing	0.00
Gross Total(\$\$):	5,134.00
GST 7.00%(\$\$):	359.38
Nett Amount(\$\$):	5,493.38

This claim is handled by: Sky Toh T C

REPAIR DETAILS**Estimates On Parts**

No.	Qty	Particulars	Amount	%Disc	After Disc	
1	1	FRONT FENDER	180.00	-10.00	162.00	m/s
2	1	FRONT FORK LH	220.00	-10.00	198.00	Rx scr
3	1	FRONT FORK RH	220.00	-10.00	198.00	SN 120.
4	1	FRONT TOP FAIRING	340.00	-10.00	306.00	m/s
5	1	FRONT LOWER INNER FAIRING	370.00	-10.00	333.00	dis
6	1	FRONT LOWER LAMP LH	130.00	-10.00	117.00	ing
7	1	FRONT LOWER LAMP RH	130.00	-10.00	117.00	cut ✓
8	1	FRONT HEADLAMP	430.00	-10.00	387.00	cut
9	1	FRONT HEADLAMP TOP FAIRING	120.00	-10.00	108.00	xnn
10	1	FRONT HEADLAMP LOWER FAIRING	170.00	-10.00	153.00	xnn
11	1	FRONT HEADLAMP LOWER INNER FAIRING	180.00	-10.00	162.00	xnn
12	1	FRONT SIDE FAIRING LH	330.00	-10.00	297.00	cut
13	1	FRONT SIDE FAIRING RH	330.00	-10.00	297.00	cut
14	1	FRONT SIDE FAIRING LAMP LH	210.00	-10.00	189.00	cut
15	1	FRONT SIDE FAIRING LAMP RH	210.00	-10.00	189.00	xnn
16	1	REAR FAIRING LH	280.00	-10.00	252.00	cut
17	1	FRONT SIDE MIRROR LH	75.00	-10.00	67.50	cut
18	1	FRONT CENTRE LOWER INNER SHIELD	135.00	-10.00	121.50	di

Total Parts (\$\$) 3,654.00

2766

Estimates of Miscellaneous Items

No.	Qty	Particulars	Amount	%Disc	After Disc	
1	1	REAR BOX	280.00	0.00	280.00	xnn
2	1	CENTRE INNER BASKET	70.00	0.00	70.00	de

Sub Total (\$\$) 350.00

70

Estimates On Labour

No.	Qty	Particulars	Amount	%Disc	After Disc	
1	1	To Dismantle and Refit Front Undercarriage.	220.00	0.00	220.00	60
2	1	To Disconnect and Reconnect, Check Electrical wiring Harness Wire, Sockets, Replace Damaged Parts.	30.00	0.00	30.00	✓
3	1	To Conduct Computer Wheel Alignment.	80.00	0.00	80.00	40
4	1	To Remove and Replace the above Damaged Parts, Straighten, Knock out, Realign and Repair including Cut and Weld body panels. To Re-adjust to the Original position using power tools.	450.00	0.00	450.00	200

Gross Labour Cost (\$\$) 780.00

330

Estimates On Paint Work Labour

No.	Qty	Particulars	Amount	%Disc	After Disc	
1	1	To Spray painting on the Replaced and Repair Parts, Prepare Spray Such as Masking Tape the unaffected areas with paper, Cleaning and Sanding of Surfaces, Final Polishing and	350.00	0.00	350.00	200

Estimates On Paint Work Labour

No.	Qty	Particulars	Amount	%Disc	After Disc
-----	-----	-------------	--------	-------	------------

Waxing are also available.

Gross Labour Cost (S\$) 350.00

200

< END OF ESTIMATES >

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Tanpin 97495749/62563561

WP' 22/10/21 @ 245

1/2 Resurvey after repair.

04 days

Tanpin @ lkkauto.com

Parts \$ 2766

S/N \$ 70

Labour \$ 330

Paint \$ 200

\$ 3366

- 20%

\$ 2692.80

4e \$2650/-

(pls confirm)