

Yew Tee Automobile Tech Pte Ltd (Co.Reg.No.200311009C)

Mega@Woodlands, 39 Woodlands Close #01-12

Singapore 737856

Tel: Fax: Email:

INSURER : AIG ASIA PACIFIC INSURANCE PTE LTD**PARTICULARS OF CLAIM**

Claim Type:	TP	Ref. No:	
Policy No:	5112928627-02	Date of Loss:	11/10/2021
Vehicle Reg. No.:	FBQ4145B	Driveable?	yes
Driver Age:	19/05/1995	Third Party Vehicle No.:	SDM693J
Any Injuries?	yes	Contact No:	91155045
Insured/Claimant:	MUHAMMAD FARHAN BIN SHADON	Driver:	MUHAMMAD FARHAN BIN SHADON

PARTS MODEL

Make/Model:	Yamaha, Sniper T150	Vehicle Reg. Date:	25/09/2019
Vehicle Colour:		Engine Number:	
Chassis No:	MH3UG0740K0153210	Odometer:	
Total Loss?		Est. Duration of Repair(Day)	

DESCRIPTION OF ACCIDENT/LOSS

Description of Accident/loss COLLISION - MAJOR/ MINOR RD
 Remarks:
 Present Location: Yew Tee Automobile Tech Pte Ltd (Mega)-YTMG

COST OF CLAIMS

	Amount
Parts	3,654.00
Miscellaneous Items	350.00
Labour	780.00
Paintwork Labour	350.00
Towing	0.00
Gross Total(\$\$):	5,134.00
GST 7.00%(\$\$):	359.38
Nett Amount(\$\$):	5,493.38

This claim is handled by: Sky Toh T C

REPAIR DETAILS**Estimates On Parts**

No.	Qty	Particulars	Amount	%Disc	After Disc
1	1	FRONT FENDER	180.00	-10.00	162.00 <i>m/s</i>
2	1	FRONT FORK LH	220.00	-10.00	198.00 <i>RY</i>
3	1	FRONT FORK RH	220.00	-10.00	198.00 <i>SW 120.</i>
4	1	FRONT TOP FAIRING	340.00	-10.00	306.00 <i>m/s</i>
5	1	FRONT LOWER INNER FAIRING	370.00	-10.00	333.00 <i>dis</i>
6	1	FRONT LOWER LAMP LH	130.00	-10.00	117.00 <i>ing</i>
7	1	FRONT LOWER LAMP RH	130.00	-10.00	117.00 <i>?</i>
8	1	FRONT HEADLAMP	430.00	-10.00	387.00 <i>cut</i>
9	1	FRONT HEADLAMP TOP FAIRING	120.00	-10.00	108.00 <i>?</i>
10	1	FRONT HEADLAMP LOWER FAIRING	170.00	-10.00	153.00 <i>?</i>
11	1	FRONT HEADLAMP LOWER INNER FAIRING	180.00	-10.00	162.00 <i>?</i>
12	1	FRONT SIDE FAIRING LH	330.00	-10.00	297.00 <i>car</i>
13	1	FRONT SIDE FAIRING RH	330.00	-10.00	297.00 <i>car</i>
14	1	FRONT SIDE FAIRING LAMP LH	210.00	-10.00	189.00 <i>cut</i>
15	1	FRONT SIDE FAIRING LAMP RH	210.00	-10.00	189.00 <i>X</i>
16	1	REAR FAIRING LH	280.00	-10.00	252.00 <i>cut</i>
17	1	FRONT SIDE MIRROR LH	75.00	-10.00	67.50 <i>cut</i>
18	1	FRONT CENTRE LOWER INNER SHIELD	135.00	-10.00	121.50 <i>di</i>

Total Parts (S\$) 3,654.00

Estimates of Miscellaneous Items

No.	Qty	Particulars	Amount	%Disc	After Disc
1	1	REAR BOX	280.00	0.00	280.00
2	1	CENTRE INNER BASKET	70.00	0.00	70.00 <i>de</i>

Sub Total (S\$) 350.00

Estimates On Labour

No.	Qty	Particulars	Amount	%Disc	After Disc
1	1	To Dismantle and Refit Front Undercarriage.	220.00	0.00	220.00 <i>60</i>
2	1	To Disconnect and Reconnect, Check Electrical wiring Harness Wire, Sockets, Replace Damaged Parts.	30.00	0.00	30.00 <i>✓</i>
3	1	To Conduct Computer Wheel Alignment.	80.00	0.00	80.00 <i>40</i>
4	1	To Remove and Replace the above Damaged Parts, Straighten, Knock out, Realign and Repair including Cut and Weld body panels. To Re-adjust to the Original position using power tools.	450.00	0.00	450.00 <i>200</i>

Gross Labour Cost (S\$) 780.00

Estimates On Paint Work Labour

No.	Qty	Particulars	Amount	%Disc	After Disc
1	1	To Spray painting on the Replaced and Repair Parts, Prepare Spray Such as Masking Tape the unaffected areas with paper, Cleaning and Sanding of Surfaces, Final Polishing and	350.00	0.00	350.00 <i>200</i>

Estimates On Paint Work Labour

No.	Qty	Particulars	Amount	%Disc	After Disc
-----	-----	-------------	--------	-------	------------

Waxing are also available.

Gross Labour Cost (S\$) 350.00

< END OF ESTIMATES >

Tanpin 97495749/62563561

WP' 22/10/21 @ 285

c/s Repair after repair.

04 days

Tanpin @ lkkauto.com

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

LKQ Auto Consultants hence notify the Repairer of the following: • To resurvey deteriorated spray painting • To respray damaged parts during resurvey • Parts prices are subject to confirmation • Third party survey is not a "Without Prejudice" basis • No legal modification is allowed • Supplemental consent must be reviewed and is subject to their review from manufacturer (if any)	Acknowledged by Repairer: Signature: Date:
--	---