

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/III21010865/KPA3Q2**Date:** 05/01/2023REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D20MFL0004693_01
Claimant Vehicle No : SMN6253U **Insured Vehicle No :** SNB5853X
 Date of Loss: 16/10/2021 Nature of Claim: TP Claim No: MFL2021D0004550

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMN6253U**
 Make & Model: TOYOTA PRIUS, 1.8 5DR HATCHBACK (A) Engine No: 2ZR2C57064
 Reg. Date: 22/08/2019 (Man. Year: 2018) Chassis No: JTDKB3FU903083702
 Colour: Metallic Pearl White/Red Odometer: 127648 km
 Engine Capacity: 1798 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15
 Front Left Side: 8 mm Rear Left Side: 8 mm
 Front Right Side: 8 mm Rear Right Side: 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,008.02	652.22	1,355.80	67.52
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,790.00	420.00	4,370.00	91.23
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	6,798.02	1,072.22	5,725.80	84.23
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment: 22/10/2021
 Date Inspected: 25/10/2021 Inspected At: Trans-cab Auto Services Pte Ltd
 No 2 Ang Mo Kio Street 63
 Singapore 569111
 Estimated Period of Repair: 1.5 days

Adjuster: KENNETH KONG**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 21 Oct 2022)
Parts:	144	TOYOTA PRIUS 1.8 5DR HATCHBACK (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMN6253U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COVER ,REAR BUMPER	Repair	442.60 FL	*- FL
2	1		*COVER ,REAR BUMPER ,LOWER	Serviceable	15.40 FL	*- FL
3	1		*FILLER REAR BUMPER EXTENSION ,RH	Serviceable	123.70 FL	*- FL
4	1		*GUARD ,REAR BUMPER CENTER	Dented / Cut	576.30 FL	*576.30 FL
5	1		*REINFORCEMENT SUB-ASSY ,REAR BUMPER	Repair	332.70 FL	*- FL
6	1		*SET PARKING AID	Dented / Cut	700.00 FS	*220.00 FS
7	1		*REAR BUMPER CLIP	Not Necessary	65.00 FS	*- FS
8	1		*END PANEL INNER TRIM CLIP	Not Necessary	60.00 FS	*- FS
9	1		*CLIP (FOR REAR DOOR TRIM BOARD)	Not Necessary	65.00 FS	*- FS
					Sub Total (\$\$)	2,380.70
					- List Item Discount on L Items 25.00/25.00% (\$\$)	372.68
					Total Parts (\$\$)	2,008.02
						652.22

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO RUST-PROOFING AND APPLY UNDERCOAT OF THE AFFECTED AREAS	New	250.00	0.00
2	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	1,800.00	220.00
3	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH,FITTINGS AND OTHER ,TO ENABLE REPAIR	New	380.00	0.00
4	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	0.00
5	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME	New	1,800.00	200.00
6	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
7	TO TRANSFER OF REAR FENDER PANEL FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
Gross Labour Cost (S\$)			4,790.00	420.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >