

ASS. REC. BY:

REF:

TH / 21010865/Kg

C

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

QD / TP / WS / TP RES / QD RES / EVA / INV / MY

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____


Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Rpt: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: _____

1 1/2 days

Res.: Yes or No

Lum Sum: _____

1.21 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____

Person Contacted: _____

Vehicle: IN / OUT

Date / Time Action / Instruction

9/11 81072.23 Conks

Veh No: _____

SMN 62534 Yr Regn: 08, 19

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: _____

Toy Pro

c.c

1788

Colour: _____

M.P. White / Red

A/C:

Insured / Std / NI / NA

Sp. Reading: _____

127648

T/Radio:

Insured / Std / NI / NA

Eng/No: _____

C/No: _____

JTOK B31FU 90-3083702

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD / R/Rim or

Tyre Size: _____

F: _____

195/65R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. _____

8

mm

R/Bal. _____

8

mm

L/Bal. _____

8

mm

L/Bal. _____

8

mm

D.O.A. _____

16/10/21

D.O.I. _____

25/10/2021

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

: Prel. Report

1)

Date/Time, File Return to?

☐

: Final Report

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

S + RS SI

Fees

Others

TOTAL

Add Fee: _____

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Report Format :

Lump Sum / I.B.I: (\$

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SMN6253U**LAD2110-006**

Not Authorized
Repair By paint
81072.23

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

25 OCT 2021**SMN6253U**

JTDKB3FU903083702

TOYOTA

PRIUS

16/10/2021

III

22/08/2019

PART

		LIST	
1	COVER, REAR BUMPER	\$ <i>R</i>	442.60 X
1	COVER, REAR BUMPER, LOWER	\$ <i>Sn</i>	15.40 X
1	FILLER, REAR BUMPER EXTENSION, RH	\$ <i>Sn</i>	123.70 X
1	GUARD, REAR BUMPER, CENTER	\$ <i>Null</i>	576.30 ✓
1	REINFORCEMENT SUB-ASSY, REAR BUMPER	\$ <i>R</i>	332.70 X
TOTAL		\$	1,490.70
25%		\$	372.68
		\$	1,118.03

Special Nett

1SET PARKING AID	\$ <i>Null</i>	700.00 <i>2205M</i>
1 REAR BUMPER CLIP	\$ <i>nn</i>	65.00 X
1 END PANEL INNER TRIM CLIP	\$ <i>nn</i>	60.00 X
1 CLIP(FOR REAR DOOR TRIM BOARD)	\$ <i>nn</i>	65.00 1
TOTAL	\$	190.00
TOTAL PARTS	\$	8,543.40

LABOUR

To Rust-Proofing and apply undercoat Of The Affected Areas.	\$ <i>nn</i>	250.00 X
Putty And Spray Painting Of The Affected Portion.	\$	1,800.00 <i>2202</i>
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$ <i>nn</i>	380.00 X
To Check Electrical Lighting Concerned.	\$ <i>nn</i>	170.00 X

Trans-cab Auto Services Pte Ltd

LAD2110-006

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SMN6253U

Panel Beating, Knocking And Straightening The Necessary
Portion, Remove And Renewal Of Parts, Adjust And Realign The
Same

\$ 1,800.00 *2001*

To check steering geometry and computer wheel alignment

\$ *nn* 220.00 *X*

To transfer of rear fender panel fittings, attachment and perform
water seepage test.

\$ *nn* 170.00 *X***TOTAL** \$ **4,790.00****Over All Total** \$ **14,451.43****(PART-BY-PART) Repair Days***10 Days**1 1/2 day*

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:

Owner ID:

Company

Vehicle Details

575K

Vehicle No.:

Vehicle to be Exported:

SMN6253U

Intended Deregistration Date:

Yes

Vehicle Make:

18 Oct 2021

Vehicle Model:

TOYOTA

Primary Colour:

PRIUS 5DR HATCHBACK (AUTO)

Manufacturing Year:

Red

Engine No.:

2018

Chassis No.:

22R2C57064

Maximum Power Output:

JTDKB3FU903083702

Open Market Value:

90.0 kW (120 bhp)

Original Registration Date:

\$26,605.00

First Registration Date:

22 Aug 2019

Transfer Count:

22 Aug 2019

Actual ARF Paid:

0

Intended PARF Rebate Details

\$19,247.00

PARF Eligibility:

Yes

PARF Eligibility Expiry Date:

21 Aug 2029

PARF Rebate Amount:

\$14,435.00

Intended COE Rebate Details

COE Expiry Date:

21 Aug 2029

COE Category:

B - Car above 1600cc or 97kW (130bhp)

COE Period(Years):

10

QP Paid:

\$43,102.00

COE Rebate Amount:

\$33,797.00

Total Rebate Amount:

\$48,232.00

The information contained herein is correct as at 18 Oct 2021

OK