

Our Job Ref No : 305490588
Date : 18/10/21

COMFORTDELGRO ENGINEERING

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508989
Fax: 6548 8156

FINALIZATION FORM

To : LKK

Fax :

Attn : Mr Thevan

Vehicle Reg No. : SHA8365U CCPL

14/10/2021

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: NTUC --- GBG1708A

2. The finalized amount shall be:

(a) Spare Parts after List discount \$1,563.18

(b) Labour Charges \$1,250.00

Total for Part-By-Part Repair Cost \$2,813.18

(c.) Lumpsum Repair (if applicable)

Total for Lumpsum repair cost after Less: _____

Final Lumpsum Repair cost _____

3. Estimated normal period for repairs: 3 working days.

4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : _____

Signature : _____

Name : MS. LOKE YY

Name : Thevan

Tel : 62148355

Date : 22/10/21

Fax : 65468156

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		NO		
3. Survey Fees				
4. LTA Search Fee	\$7.49 / \$2.00			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

COMFORT TRANSPORTATION PTE LTD

REPAIR ESTIMATE

Vehicle No. : SHA8365U

Make : HYUNDAI

Model : IONIQ(G3)

Date: 14/10/2021

Insurance: NTUC

MVA: MS. LOKE YY

Qty	Parts Description / Labour	Type	Unit Price	Amount
1	REAR BUMPER COVER			\$459.40
10	REAR BUMPER CLIPS			\$22.00
1	REAR BUMPER CENTRE MOULDING ASSY			\$451.25
1	REAR BUMPER REINFORCEMENT			\$394.80
1	REAR BUMPER REINFORCEMENT BRACKET LH RH		\$138.10	\$276.20
1	REAR BUMPER LOWER CTR MOULDING			\$155.00
1	REAR BUMPER TOWING COVER			\$98.80
1	REAR BUMPER FOG LAMP			\$201.50
1	LICENCE LAMP			\$85.30
1	ANTHENNA SMARTKEY			\$40.50
1	BOOTLID			\$2,480.40
1	BOOTLID HYUNDAI PLATE			\$24.30
1	EMBLEM HYBRID			\$24.30
1	EMBLEM - IONIQ			\$31.30
1	REAR PANEL			\$532.00
1	REAR PANEL GARNISH			\$346.80
SUB TOTAL				\$5,623.85
LESS 20%				\$1,124.77
DISCOUNTED TOTAL				\$4,499.08
1	REAR BUMPER RUBBER MAT			\$50.00
1	REAR NUMBER PLATE WITH TRIM COVER	-10.00%		\$55.00
1	BOOTLID COMFORT TEL NO STICKER			\$35.00
1	BOOTLID COMFORT LOGO STICKER			\$30.00
1	BOOTLID COMFORT APP STICKER			\$30.00
1	REAR BUMPER REVERSE SENSOR			\$180.00
Labour Charge				
PANEL BEATING				\$1,100.00
SPRAY PAINTING CHARGE				\$750.00
CHK ALL LIGHTING				\$50.00
REMOVE/REFIX REVERSE SENSOR				\$80.00
TOTAL LABOUR				\$1,980.00
ESTIMATE TOTAL				\$6,859.08

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

COMFORTDELGRO ENGINEERING PTE LTD
REPAIR ESTIMATE

Date: 18.10.2021
Time: 14:21:54
Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010070
ADDRESS : CITYCAB PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65551188

JOB NO : 305490588
REGN NO : SHA8365U
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : IONIQ(G3)
DATE OF REGN : 22.10.2019
DATE/TIME IN : 14.10.2021 14:35
ACCIDENT DATE : 14.10.2021

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001	28-01-0104-2029-A	VEHICLE NUMBER PLATE REAR	1	55.00	10.00	49.50
0002	04-01-0104-2282-G	COVER-RR BUMPER#	1	459.40	20.00	367.52
0003	04-01-0101-0111-G	BUMPER COVER CLIP REAR	10	22.00	20.00	17.60
0004	04-01-0104-2533-G	MOULDING ASSY-RR BUMPER C	1	451.25	20.00	361.00
0005	04-01-0104-2270-G	EMBLEM-HYBRID	1	24.30	20.00	19.44
0006	04-01-0104-2271-G	EMBLEM-IONIQ	1	31.30	20.00	25.04
0007	04-01-0104-2175-G	SYMBOL MARK-H	1	24.30	20.00	19.44
0008	04-01-0104-1150-A	PROTECTOR MAT	1	50.00	2.00-	50.00
0009	04-01-0104-2544-G	CAP-RR HOOK	1	98.80	20.00	79.04
0010	04-01-0104-2370-G	LAMP ASSY-REAR FOG	1	201.50	20.00	161.20
0011	09-01-0104-2133-G	ANTENNA ASSY-SMARTKEY	1	40.50	20.00	32.40
0012	09-01-9999-0068-A	REVERSE SENSOR ASSY*	1	180.00	10.00	162.00
0013	28-01-0103-0009-A	REAR BOOT LOGO CCTPL	1	30.00	1.00-	30.00

REPAIR ESTIMATE

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010070
 ADDRESS : CITYCAB PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65551188

JOB NO : 305490588
 REGN NO : SHA8365U
 MILEAGE : 0000000000
 MAKE : HYUNDAI
 MODEL : IONIQ(G3)
 DATE OF REGN : 22.10.2019
 DATE/TIME IN : 14.10.2021 14:3
 ACCIDENT DATE : 14.10.2021

JOB / PARTS DESCRIPTION	QTY IND UNIT-PRICE DISC% AMOUNT			
0014 28-01-0103-0010-A REAR BOOT TEL NUMBER CCTP	1	35.00	0.10	35.00
0015 28-01-9999-2025-A APP LOGO REAR BONNET CTPL	1	30.00	0.01-	30.00
0016 04-01-0104-2545-G MOULDING-REAR BUMPER LWR	1	155.00	20.00	124.00
SUB-TOTAL :				1,563.18

JOB NATURE

0000 PB	PANEL BEATING SHA8365U	700.00
0001 SP	SPRAYPAINT CHARGE	500.00
0002 17-01	CHECK ALL LIGHTING	20.00
0003 L	REMOVE/REFIX REVERSE SENSOR	30.00
SUB-TOTAL :		1,250.00

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010070
ADDRESS : CITYCAB PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65551188

JOB NO : 305490588
REGN NO : SHA8365U
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : IONIQ(G3)
DATE OF REGN : 22.10.2019
DATE/TIME IN : 14.10.2021 14:3
ACCIDENT DATE : 14.10.2021

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

TOTAL : 2,813.18

MVA NAME & SIGNATURE

DATE :

Lore Wei Yeng

AUTHORISED : YES / NO

SURVEYOR NAME & SIGNATURE

DATE :