



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHA 8365U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BUMPER COVER	CUT	459.40	459.40
10	REAR BUMPER CLIPS	NECESSARY	22.00	22.00
1	REAR BUMPER CENTRE MOULDING ASSY	SCRATCHED	451.25	451.25
1	REAR BUMPER REINFORCEMENT	SERVICEABLE	394.80	-
2	REAR BUMPER REINFORCEMENT BRACKET LH/RH @ \$138.10	SERVICEABLE	276.20	-
1	REAR BUMPER LOWER CTR MOULDING	CUT	155.00	155.00
1	REAR BUMPER TOWING COVER	SCRATCHED	98.80	98.80
1	REAR BUMPER FOG LAMP	CUT	201.50	201.50
1	LICENCE LAMP	SERVICEABLE	85.30	-
1	ANTHENNA SMARTKEY	CUT	40.50	40.50
1	BOOTLID	TO REPAIR SEE LABOUR	2,480.40	-
1	BOOTLID HYUNDAI PLATE	NECESSARY	24.30	24.30
1	EMBLEM HYBRID	NECESSARY	24.30	24.30
1	EMBLEM-IONIQ	NECESSARY	31.30	31.30
1	REAR PANEL	TO REPAIR SEE LABOUR	532.00	-
1	REAR PANEL GARNISH	SERVICEABLE	346.80	-
	LESS 20% DISCOUNT		-1,124.77	-301.67
			4,499.08	1,206.68
<u>NETT ITEMS</u>				
1	REAR NUMBER PLATE WITH TRIM COVER (N)	MISSING / CRACKED	55.00	55.00
1	REAR BUMPER REVERSE SENSOR (N)	CUT	180.00	180.00
	LESS 10% DISCOUNT		-	-23.50
			235.00	211.50
<u>SPECIAL NETT ITEMS</u>				
1	REAR BUMPER RUBBER MAT (SN)	NECESSARY	50.00	50.00
1	BOOTLID COMFORT TEL NO STICKER (SN)	NECESSARY	35.00	35.00

Report Ref No. NS/INC21010866/Vucn2



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	BOOTLID COMFORT LOGO STICKER (SN)	NECESSARY	30.00	30.00
1	BOOTLID COMFORT APP STICKER (SN)	NECESSARY	30.00	30.00
			145.00	145.00
	<u>LABOUR</u>			
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF BOOTLID AND REAR PANEL.		1,100.00	700.00
	SPRAY PAINTING CHARGE.		750.00	500.00
	CHK ALL LIGHTING.		50.00	20.00
	REMOVE/REFIX REVERSE SENSOR.		80.00	30.00
			1,980.00	1,250.00
GRAND TOTAL			6,859.08	2,813.18
RECOMMENDED COST OF REPAIRS (CONFIRMED)				2,813.18

Report Ref No. NS/INC21010866/Vucn2

THEVAN THOMAS KARTHIKESAVAN

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.