

Our Job Ref No : 305490583
Date : 15/10/21

ENGINEERING

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508989
Fax: 6546 8156

FINALIZATION FORM

To : LKK

Fax :

Attn : THEVAN

Vehicle Reg No. : SHD3223M

Date of Accident : 13.10.21

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: NTUC --- FBF1692R

2. The finalized amount shall be:

(a) Spare Parts after List discount

(b) Labour Charges

Total for Part-By-Part Repair Cost

(c) Lumpsum Repair (if applicable)

Total for Lumpsum repair cost after Less: 20%

Final Lumpsum Repair cost

\$1,100.00

\$1,100.00

3. Estimated normal period for repairs: 2 working days.

4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : 

Signature : 

Name : LIM T S

Name : THEVAN

Tel : 62148398

Date : 22/10/21

Fax : 65468156

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid	---	N		
3. Survey Fees	-----	--		
4. LTA Search Fee	\$7.49 /\$2.00			
5. Medical Fees (on behalf of driver, if applicable)				
6 Overrun				

Remarks:

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

LKK -

DATE: 14.10.21

3P INSURANCE: NTUC (45)

MODEL: HYUNDAI I40

SURVEYOR: NA

VEH NO.: SHD3223M ✓

MVA: LIM T S

PART NO.	DESCRIPTION	QTY	LIST PRICE	REMARKS
	Rear Bumper	1		\$553.00 (4)
	Rear Bumper Reinforcement	1		\$428.40 X SVC
	Rear Bumper Clip (10 pcs)	10	\$2.20	\$22.00 / NIC
	Rear Bumper Side Bracket RH/LH	2	\$80.30	\$160.60 X SVC
	Rear Bumper Sponge	1		\$119.50 X SVC
	Rear Bumper Under Cover	1		\$228.00 / SVC
SPARE PARTS SUB TOTAL				\$1,511.50
LESS 20%				\$302.30
DISCOUNTED SPARE PARTS TOTAL				\$1,209.20
	Reverse Sensor	1		\$135.70 (4)
S/NETT SUB				\$135.70
LESS 10%				\$13.57
S/NETT TOTAL				\$122.13
	Rear Bumper Mat	1		\$50.00 NIC
NETT TOTAL				\$50.00
SPARE PARTS & OTHERS TOTAL				\$1,381.33
	Panel Beating			\$300.00 280
	Spray Painting Charge			\$300.00 250
	Remove/Refix Reverse Sensor			\$120.00 30
LABOUR TOTAL				\$720.00
ESTIMATE TOTAL				\$2,101.33

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Thuan @ Lkhauto.com
82235769

14/10/21 1615

2 days wP

45 after repair photo

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: