

## ESTIMATE OF REPAIR

Veh# SMD5955L

Model: TOYOTA VIOS

Accident Date 22/10/2021

10/6/2009- 31/5/2024

Location BLK172 ANG MO KIO AVE 4 CARPARK

3P: GBB2498A (III)

S/Nos.	Qty	Description	List \$	S/Nett \$	Nett \$
1	1 pc	Rear bumper	560.00		
2	10 pcs	Rear bumper clips		30.00	
3	2 pcs	Rear bumper o/s & n/s retainer	80.00		
4	1 pc	Rear bumper o/s & n/s reflector	90.00		
5	1 pc	Rear n/s tail-lamp	386.50		
6	1 pc	Rear n/s tail-lamp clips		8.00	
7	1 pc	Rear n/s fender	928.00		
8	1 pc	Rear n/s fender inner trim	113.20		
9	1 set	Rear windscreen moulding		120.00	
10	1 pc	Rear windscreen sealant		80.00	
11	1 set	Rear reverse sensor		200.00	
12	1 pc	Rear n/s hub	345.60		
13	1 pc	Rear n/s bearing	195.40		
14	1 pc	Rear n/s suspension	310.50		
15	1 pc	Rear n/s rim		600.00	
		Sub-Total:	3,009.20	1,038.00	0.00
			25%	0%	0%
		After Less %:	<b>2,256.90</b>	<b>1038.00</b>	0.00

<u>Labour</u>		
1	To dismantle rear portion damaged parts, straighten & welding.	800.00
2	To spray painting.	600.00
3	To check alignment	160.00
4	To remove and replace rear n/s under carridge	120.00
5	To remove & replace rear reverse sensor.	30.00
6	To remove and refit rear windscreen	120.00
7	To check wiring.	50.00
8	To re-seal anti-rust.	50.00
	Sub-Total:	<b>1,930.00</b>
	<b>Total:</b>	<b>5,224.90</b>
	After Less 20%:	<b>4,179.92</b>



Chan San Choon  
Director  
DipEng, AAE MIMI,MSAE(Aust)

