



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### TAX INVOICE

LONPAC INSURANCE BHD

300 BEACH ROAD  
#17-04/07 THE CONCOURSE  
SINGAPORE 199555

INV No. AC2200862

INV Date 16/02/2022

Reference CC4/LPC21010881/Kgs3q2

Code LPC2

### PROFESSIONAL SERVICE FEE

Vehicle No. SMR 3754P  
Insured Veh. GBD 4484R  
Claim No. 20/21/21/VC00/025012  
Policy No. Z/20/VC00/108910  
Accident Date 05/10/2021  
Inspection Date 25/10/2021

Description	Total
Third Party Express Settlement	400.00
<b>Subtotal</b>	<b>400.00</b>
<b>GST (7%)</b>	<b>28.00</b>
<b>Grand Total</b>	<b>428.00</b>

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

**LKM**



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Ref: CC4/LPC21010881/Kgs3q2 Date: 16/02/2022 Code: LPC2	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	GBD 4484R	Veh. Inspected	SMR 3754P	
Policy No.	Z/20/VC00/108910	Coverage (\$)	0.00	
Claim No.	20/21/21/VC00/025012	Excess (\$)	0.00	
Assign From	ONG LI LI	Assign Date	22/10/2021	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	AUDI A1 (A)	c.c	999	
Engine No.	HIDDEN	Year of Reg.	2019	
Chassis No.	WAUZZZGB4LR006129	Colour	MULTI COLOUR	
Odometer	36635 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	195/55 R16	YOKOHAMA	9 mm	
L/H Front Tyre	195/55 R16	YOKOHAMA	9 mm	
R/H Rear Tyre	195/55 R16	BRIDGESTONE	9 mm	
L/H Rear Tyre	195/55 R16	BRIDGESTONE	9 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	05/10/2021	Inspection Date	25/10/2021	
Survey held at	OPTIMA WERKZ PTE LTD 6, KUNG CHONG ROAD SINGAPORE 159143			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:			5 Working Days	



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMR 3754P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	HEADLAMP RH	CRACKED	2,900.00	2,900.00
1	HEADLAMP BRACKET RH	SERVICEABLE	100.00	-
1	FRONT BUMPER	TO REPAIR SEE LABOUR	1,160.00	-
1	FRONT SIDE BRACKET RH	SERVICEABLE	75.00	-
1	FRONT FENDER RH	BUCKLED	720.00	720.00
1	FRONT DOOR RH	TO REPAIR SEE LABOUR	2,150.00	-
1	BONNET (NPA)	TO REPAIR SEE LABOUR	-	-
	LESS 10% DISCOUNT		-710.50	-362.00
			6,394.50	3,258.00
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	FRONT BUMPER VINYL WRAP (SN)	NECESSARY	400.00	300.00
1	BONNET VINYL WRAP (SN)	NECESSARY	450.00	300.00
1	FRONT FENDER RH VINYL WRAP (SN)	NECESSARY	350.00	300.00
1	FRONT DOOR RH VINYL WRAP (SN)	NECESSARY	450.00	300.00
1	FRONT BUMPER CLIPS (SN)	NOT NECESSARY	80.00	-
			1,730.00	1,200.00
	<b><u>LABOUR</u></b>			
	LABOUR CHARGES TO REMOVE ,REFIX ,REPAIR & READJUST ACCIDENT AREA.INCLUSIVE OF THE REPAIR OF FRONT DOOR RH ,FRONT BUMPER AND BONNET.		1,000.00	400.00
	LABOUR CHARGES TO SUPPLY PAINT & FURNISHING MATERIALS AT ACCIDENT AREA.		1,200.00	600.00
	TO CONDUCT WHEEL ALIGNMENT.	NOT NECESSARY	100.00	-
	TO TUFF KOTE & UNDERSEAL MATERIALS.		120.00	30.00
	TO CHECK WIRING & ELECTRICAL SYSTEM & ETC.		150.00	20.00
	TO DIAGNOSE & RESET FAULT CODE.		150.00	60.00
			2,720.00	1,110.00
	<b>GRAND TOTAL</b>		<b>10,844.50</b>	<b>5,568.00</b>

Report Ref No. CC4/LPC21010881/Kgs3q2



RECOMMENDED COST OF REPAIRS			<b>5,568.00</b>
-----------------------------	--	--	-----------------

Report Ref No. CC4/LPC21010881/Kgs3q2

A handwritten signature in black ink, appearing to be 'KSC'.

**KONG SENG CHEONG**

**Licensed Appraiser**

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.**

**No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.**



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### PHOTOGRAPHS FOR VEHICLE NO. SMR 3754P

### INSPECTION








## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### PHOTOGRAPHS FOR VEHICLE NO. SMR 3754P

### RE-INSPECTION

