

Date: 13.10.2021
 Vehicle No: SMR3754P
 Model: AUDI A1 SB 1.0 TFSI
 Chassis: WAUZZZGB4LR006129
 Reg.Year: 2019

Third Party Insurer: LONPAC
 Third Party Veh No: GBD4484R
 Date of Accident: 05.10.2021
 Estimate: VICTOR
 Surveyor:

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	HEADLAMP RH			\$2,900.00
2	HEADLAMP BRACKET RH			\$100.00
3	FRONT BUMPER			\$1,160.00
4	FRONT SIDE BRACKET RH			\$75.00
5	FRONT FENDER RH			\$720.00
6	FRONT DOOR RH			\$2,150.00
7	BONNET			REPAIR
SUB TOTAL				\$7,105.00
LESS 10%				-\$710.50
PARTS TOTAL				\$6,394.50

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	FRONT BUMPER VINYL WRAP	1		\$400.00
2	BONNET VINYL WRAP	1		\$450.00
3	FRONT FENDER RH VINYL WRAP	1		\$350.00
4	FRONT DOOR RH VINYL WRAP	1		\$450.00
5	FRONT BUMPER CLIPS	1		\$80.00
S/N TOTAL				\$1,730.00

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REFIX, REPAIR & READJUST ACCIDENT AREA. \$1,000.00

LABOUR CHARGES TO SUPPLY PAINT & FURNISHING MATERIALS AT ACCIDENT AREA. \$1,200.00

TO CONDUCT WHEEL ALIGNMENT \$100.00

TO TUFF KOTE & UNDERSEAL MATERIALS. \$120.00

TO CHECK WIRING & ELECTRICAL SYSTEM & ETC. \$150.00

TO DIAGNOSE & RESET FAULT CODE. \$150.00

LABOUR TOTAL \$2,720.00

TOTAL \$10,844.50

Head office

6 Kung Chong Road Singapore 169143
 Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
 Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 569047
 Tel: (+65) 6481 1622 | Fax: (+65) 6481 1011

