



新福德車廠私人有限公司

NEW HOCK TECK MOTOR PTE. LTD.

1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit, Singapore 417883

Email: admin@nhtmotor.com Website: www.nhtmotor.com

Tel: 6747 9241 Fax: 6741 7276

UEN: 201718370K GST Reg No.: 201718370K

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

Accident date : 22/10/2021

Estimated repair cost for vehicle no : SGN1292K HONDA MOBILIO SV 1.5 CVT

CHASSIS: MRHDD4870FP000003 (2015)

23/10/2021

TP Ching.
Asher.

S/N	Qty	Items	U/price	Amount
1	1	RH FRONT DOOR <i>Distorted</i>	\$928.60	\$928.60 ✓
2	1	RH FRONT DOOR INNER TRIM BOARD <i>Cracked</i>	\$401.80	\$401.80 ✓
3	1	RH FRONT DOOR HANDLER <i>New</i>	\$141.30	\$141.30 +
4	1	RH FRONT DOOR WEATHER STRIPE <i>Cut</i>	\$78.10	\$78.10 ✓
5	1	RH FRONT DOOR GLASS <i>Cracked</i>	\$384.90	\$384.90 ✓
6	1	RH FRONT DOOR GLASS INNER LOULDING <i>New</i>	\$35.20	\$35.20 +
7	1	RH FRONT DOOR OUTER CHANNEL MOULDING <i>Cracked</i>	\$48.50	\$48.50 ✓
8	1	RH FRONT DOOR BLACK STICKER <i>New</i>	\$40.20	\$40.20 ✓
9	1	RH FRONT DOOR POWER WINDOW MOTOR <i>New</i>	\$172.30	\$172.30 +
10	1	RH FRONT DOOR POWER WINDOW REGULATOR GEAR <i>Cracked</i>	\$296.40	\$296.40 ✓
11	1	RH FRONT DOOR LOCK <i>Cracked</i>	\$240.80	\$240.80 ✓
12	2	RH FRONT DOOR HINGE <i>New</i>	\$40.80	\$81.60 +
13	1	RH FRONT DOOR CHECKER <i>New</i>	\$45.30	\$45.30 +
14	1	RH FRONT QUARTER GARNISH <i>New Cut</i>	\$65.80	\$65.80 ✓
15	1	RH FRONT DOOR WIND MIRROR <i>Cracked</i>	\$572.80	\$572.80 ✓
16	1	RH FRONT DOOR WIND MIRROR COVER <i>Cracked</i>	\$81.20	\$81.20 ✓
17	1	RH FRONT FENDER <i>New</i>	\$348.30	\$348.30 +
18	1	FRONT BUMPER <i>New</i>	\$459.80	\$459.80 +
19	1	RH FRONT BUMPER SIDE RETAINER <i>New</i>	\$17.60	\$17.60 +
20	1	RH ROCKER PANEL <i>New</i>	\$528.70	\$528.70 +
21	1	RH ROCKER PANEL GARNISH <i>Cracked</i>	\$414.10	\$414.10 ✓

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

3533.20

2826.86.

TOTAL :	\$4,753.80
LESS 20 %	\$950.76
SUB-TOTAL :	\$3,803.04

S/N	Qty	ITEMS / SPECIAL NETT	U/price	Amount
1	1	FRONT BUMPER CLIPS <i>see u</i>	\$80.00	\$80.00 <i>+</i>
2	1	RH ROCKER PANEL GARNISH CLIPS <i>see</i>	\$60.00	\$60.00 <i>-30</i>
3	1	RH FRONT QUARTER GARNISH <i>see clips see</i>	\$30.00	\$30.00 <i>-10</i>
4	2	RH FRONT DOOR INNER TRIM BOARD CLIPS <i>see</i>	\$60.00	\$60.00 <i>-30</i>

70

TOTAL: \$230.00

TOTAL PARTS: \$4,033.04

Labour charges

1	LABOUR FOR PANEL BEATING	\$1,800.00 <i>450</i>
2	LABOUR FOR SPRAYPAINTING	\$1,300.00 <i>500</i>
3	WIRING CHECK	\$80.00 <i>-30</i>
4	TO APPLY RUST PROOF / TUFF COAT ON ACCIDENT AREAS	\$300.00 <i>-40</i>
5	LABOUR FOR REMOVE & TRANSFER ALL RH FRONT DOOR FITTING	\$250.00 <i>80</i>
6	LABOUR FOR REMOVE & REFIX RH FRONT CARPET/UPHOLSTERY/FRONT SEAT ROOF LINING TO FACILITATE THE REPAIR OF RH FRONT DOOR PANEL /PILLAR	\$300.00 <i>+</i>

Subtotal :- \$4,030.00

Total:- \$8,063.04

Adrian Lj
h/s 25/10/21
04 Pays

total: 3996.56
h/s 3.2K

3.2K