

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG21010883/AQCE2

Date: 26/01/2022

REFERENCE

Insured/Claimant:	LIANG LIT HOW	Policy No:	1700053632-04		
Date of Loss:	20/10/2021	Nature of Claim:	OD	Claim No:	4551654791SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLS2977B		
Make & Model:	AUDI A3, 999cc TFSI S TRONIC (LED) (A)	Engine No:	CHZ509771
Reg. Date:	18/09/2017 (Man. Year: 2017)	Chassis No:	WAUZZZ8V0J1006102
Colour:	Grey	Odometer:	71167 km
Engine Capacity:	999 cc		
Market Value/New Car Price:	S\$78,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,224.00	2,739.60	1,484.40	35.14
Miscellaneous Items	0.00	0.00	0.00	
Labour	9,032.00	3,112.00	5,920.00	65.54
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	13,256.00	5,851.60	7,404.40	55.86
- Excess (S\$)	600.00	600.00	0.00	0.00
(S\$)	12,656.00	5,251.60	7,404.40	58.51
+ GST 7.00/7.00% (S\$)	885.92	367.61	518.31	58.51
Nett Amount (S\$)	13,541.92	5,619.21	7,922.71	58.51

INSPECTION

Date of Assignment:	25/10/2021		
Date Inspected:	22/10/2021	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	5.0 days		

Adjuster: ADRIAN LING

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR DOOR - LH	Dented	3,039.00 FS	*2,431.20 FS
2	1		*REAR DOOR OUTER SEAL - LH	Necessary	161.00 FS	*128.40 FS
3	1		*BONDING AGENT	Not Necessary	49.00 FS	*- FS
4	1		*CLEANING SOLUTION	Not Necessary	68.00 FS	*- FS
5	1		*APPLICATOR	Not Necessary	8.00 FS	*- FS
6	1		*REAR DOOR CATCH - LH	Not Necessary	94.00 FS	*- FS
7	1		*REAR WHEEL HOUSING LINER - LH	Not Necessary	240.00 FS	*- FS
8	1		*REAR WHEEL SPOILER - LH	Not Necessary	35.00 FS	*- FS
9	1		*STONE CHIP	Necessary	180.00 FS	*180.00 FS
10	1		*REAR TYRE - LH (NPA)	Not Necessary	0.00 FS	*- FS
11	1		*SUNDRIES	Not Necessary	350.00 FS	*- FS
F=Franchise part. S=SpcNett.						
Total Parts (S\$)					4,224.00	2,739.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REINSTALL REAR PARKING AID. CHECK FUNCTION	New	280.00	0.00
2	TO REMOVE AND REINSTALL LHS FRONT DOOR PANEL TRIM. TO REMOVE AND REINSTALL LHS WING MIRROR ASSY TO FACILITATE RESPRAY OF LHS FRONT DOOR	New	280.00	0.00
3	TO REMOVE AND TRANSFER LHS REAR DOORS MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES	New	350.00	280.00
4	TO DISMANTLE AND REINSTALL REAR BUMPER. TO RENEW LHS REAR DOOR. TO REPAIR LHS REAR FENDER, LHS FRONT DOOR AND LHS SILL PANEL. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	3,150.00	750.00
5	TO RESPRAY LHS REAR DOOR, LHS FRONT DOOR, DOOR HANDLE, LHS REAR FENDER, REAR BUMPER AND LHS SILL PANEL	New	4,500.00	1,650.00
6	TO RENEW LHS REAR TYRE AND CARRY OUT WHEEL ALIGNMENT	New	280.00	240.00
7	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$\$)			9,032.00	3,112.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >