

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0443/2021/HR
DATE : 24-May-21
WIP : 28042

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE SURVEY ON 22/10/2021

YOUR INSURED VEH NO : SMZ 3280 Y

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR ENG KWANG CHIANG
ADDRESS : 52B WAK HASSAN DRIVE
SINGAPORE 757135
TELEPHONE : HP +65 92760636
TYPE OF CLAIM : CLAIM OWN INSURANCE
POLICY NO : 7210023697
VEHICLE NO : **SMZ 3280 Y**
MODEL CODE : A3 SEDAN 1.0 TFSI 8V
MODEL YEAR : 8/3/2021
ENGINE NO : CHZ C34586
CHASSIS NO : WAUZZZ8V5LA007331
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 7-May-21
PLACE OF ACCIDENT : NEAR 52B WAK HASSAN DRIVE.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL : NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMZ 3280 Y

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND REINSTALL REAR PARKING AID. CHECK FUNCTION.	S/N \$	280.00	✓
2	TO RENEW REAR WINDSCREEN AND LHS 1/4 GLASS TO FACILLITATE FENDER RENEWAL.	S/N \$	600.00	✓
3	TO INSTALL SOLAR FILM FOR REAR WINDSCREEN AND LHS 1/4 GLASS.	S/N \$	400.00	✓
4	TO CARRY OUT WATER SEEPAGE TEST FOR REAR WINDSCREEN AND 1/4 GLASS.	S/N \$	200.00	150
5	TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT. INSPECT FOR DAMAGE AND RENFW WHERE NECESSARY	S/N \$	1,400.00	✓
6	TO REMOVE AND REINSTALL REAR SEAT, BACK REST, HAT TRAY, ABCD PILLAR TRIMS, LUGGAGE COMPARTMENT TRIMS. DISLODGE ROOF LINER AND DISENGAGE CURTAIN ATRRAC, FTC	S/N \$	1,400.00	✓
SUB TOTAL LABOUR CHARGES		:	\$ 4,280.00	

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMZ 3280 Y

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
7	TO DISMANTLE AND RENEW REAR BUMPER. TO CUT OUT AND WELD LHS REAR FENDER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 4,900.00	3000
8	TO RESPRAY REAR BUMPER, LHS REAR FENDER, LHS SILL PANEL, ROOF CHANNEL, DRAIN CHANNEL, DOOR ENTRANCE AND REAR END PANELLING.	\$ 4,650.00	$3.5 + 1 = 4.5$ $4.5 \times 550 = 2475$
9	TO RENEW LHS REAR RIM. TO CARRY OUT WHEEL ALIGNMENT TEST.	S/N \$ 280.00	X
10	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ 14,302.00	

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMZ 3280 Y

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
1	REAR BUMPER <i>Dehd</i>	1	\$ 1,944.00	✓	
2	REAR BUMPER FIXING PARTS <i>new</i>	1	\$ 193.00	+	
3	REAR BUMPER GUIDE SECTION - LH / RH <i>LH new</i>	2	\$ 32.00 <i>th</i>	X	
4	REAR BUMPER LOCKING MECHNAISM <i>?</i>	1	\$ 30.00	✓	
5	REAR WHEEL HOUSING LINER ADAPTER - LH <i>?</i>	1	\$ 38.00	✓	
6	REAR BUMPER SPOILER <i>new</i>	1	\$ 237.00	+	
7	REAR BUMPER LIGHT REFLECTOR - LH <i>new</i>	1	\$ 41.00	+	
8	LED TAIL LIGHT - LH <i>new</i>	1	\$ 877.00	+	
9	LED TAIL LIGHT TRIM - LH <i>new</i>	1	\$ 30.00	X	
10	REAR BUMPER GUIDE SECTION - LH <i>new</i>	1	\$ 67.00	✓	
11	REAR SIDE PANEL SECTIONAL PART - LH <i>Distorted</i>	1	\$ 4,140.00	✓	
12	REAR WINDOW <i>new</i>	1	\$ 814.00	✓	
13	REAR SIDE WINDOW - LH <i>new</i>	1	\$ 570.00	✓	
14	REAR WINDOW PRIMER <i>new</i>	1	\$ 20.00	✓	
15	REAR ALUMINIUM RIM - LH <i>new</i>	1	\$ 1,166.00	+	
16	REAR WHEEL HOUSING LINER - LH <i>?</i>	1	\$ 240.00	?	
17	REAR WHEEL HOUSING LINER ATTACHMENT PARTS <i>new</i>	1	\$ 89.00	+	
18	REAR WHEEL SPOILER - LH <i>new</i>	1	\$ 35.00	+	
19	1/4 GLASS SEALANT <i>new</i>	S/N	\$ 100.00	✓	
20	ACRYLIC SEALANT <i>new</i>	S/N	\$ 180.00	✓	
SUB TOTAL SPARE PARTS		:	\$ 10,843.00		

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMZ 3280 Y

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	CAVITY WAX	S/N	\$ 140.00	✓
22	STONE CHIP	S/N	\$ 180.00	✓
23	METAL FILLER POWDER	S/N	\$ 280.00	✓
24	REAR WINDSCREEN SEALANT	S/N	\$ 200.00	✓
25	SUNDRIES		\$ 300.00	?
TOTAL SPARE PARTS		:	\$ 11,943.00	
TOTAL LABOUR CHARGES		:	\$ 14,302.00	
GRAND TOTAL		:	\$ 26,245.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : *Adrian L*
SURVEYED DATE : *22/10/21*
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : *Not Authorised, 12 Days*

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT