

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile						
	LONPAC INSURAI	NCE BHD	Re	ef:	CS3/LPC21006283/T1tf3e2-1	
	300 BEACH ROAD SINGAPORE 1995	#17-04/07 THE CONCOURSE 55	Da	ate:	24/12/2021	
			Co	ode:	LPC2	
1.	Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	GBC 561H	Veh. Inspected		SKG 1543B	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	21/21/21/VC05/024609	Excess (\$)		0.00	
	Assign From	GERALD POH	Assign Date		25/10/2021	
2. Vehicle Particulars & Condition						
	Make & Model	TOYOTA WISH	c.c		1794	
	Engine No.	HIDDEN	Year of Reg.		2006	
	Chassis No.	ZNE100289762	Colour		SILVER	
	Odometer	343947 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	GOOD				
3.	3. Conditions of Tyres					
		Size	Make		Balance	
	R/H Front Tyre	195/65 R15	TOURADOR		6 mm	
	L/H Front Tyre	195/65 R15	TOURADOR		6 mm	
	R/H Rear Tyre	195/65 R15	TOURADOR		6 mm	
	L/H Rear Tyre	195/65 R15	TOURADOR		6 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	29/05/2021	Inspection Date		01/06/2021	
	Survey held at	333 AUTO GARAGE PTE LTD				
	15 KAKI BUKIT ROAD 4, #01-36, BARTLEY BIZ CENTRE, SINGAPORE 417808					
5a.	Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 7 Working Days					