

TSL Auto Garage
Blk 4 Joo Chiat Complex
#12-1171 Joo Chiat Road
Singapore 420004

SKR3500D Audi A6

No	Qty	Parts Description	Estimated Parts Price	
1	1	Front bumper assy	\$ 3,183.80	de - 2800
2	1	Front bumper right bracket	\$ 125.50	xm.
3	1	Front bumper right retainer	\$ 124.50	ca
4	1	Front right fender	\$ 1,156.20	df - 780
5	1	Front right fender inner cowl	\$ 425.30	xm
6	1	Front right door panel assy	\$ 2,458.50	bt - 1800
7	1	Front right door inner trim board complete assy	\$ 1,506.20	xm - 1100.
8	1	Front right door lock mechanism	\$ 371.60	bt
9	1	Front right door lock catch	\$ 82.80	x
10	1	Front right door upper hinge	\$ 96.20	x
11	1	Front right door lower hinge	\$ 88.20	x
12	1	Front right door window regulator linkage	\$ 368.30	x
13	1	Front right door window regulator motor	\$ 513.20	x
14	1	Front right door window door chrome frame	\$ 1,035.60	x
15	1	Front right door weatherstrip	\$ 298.30	x
16	1	Front right door checker linkage	\$ 181.30	x
17	1	Front right door outer handle	\$ 489.10	x
18	1	Front right wing mirror complete assy	\$ 1,637.80	dis - 1160
19	1	Front right suspension damper	\$ 1,153.60	x
20	1	Front right knuckle arm	\$ 1,228.60	x
21	1	Front right wheel hub bearing	\$ 388.70	x
22	1	Front right lower control arm	\$ 1,134.80	x
23	1	Front right upper link	\$ 588.60	x
24	1	Front right lower link	\$ 576.80	x
25	1	Front right upper control arm	\$ 1,167.80	x
26	1	Front right 'B' pillar	\$ 1,643.50	x
27	1	Front Headlamp RH	\$ 22,024.80	# 3880 (CHID) ca
		less 5%	\$ 1,101.24	2100
			\$ 20,923.56	10236.10
				9724.30

Special Nett Items

1	12	Front bumper clips	\$ 60.00	30 ea
2	1	Front right sports rim	\$ 1,250.00	ent - 1000
3	1	Front right tyre	\$ 600.00	x
4	1	Front no plate with garnish	\$ 100.00	x
5	4	Front right fender cowl clips	\$ 30.00	x
6	10	Front right door inner trim board clips	\$ 50.00	x
7	1	Front right 'B' pillar sealant	\$ 100.00	*
8	1	Front right door sticker	\$ 150.00	ea - 100
9	1	Front right door fender sticker	\$ 150.00	ea - 100
			\$ 2,490.00	

Total parts

\$ 23,413.56

1230.

TSL Auto Garage
Blk 4 Joo Chiat Complex
#12-1171 Joo Chiat Road
Singapore 420004

SKR3500D Audi A6

No	Qty	Parts Description	Estimated Parts Price	
1	1	Rear bumper assy	\$ 2,998.30	xR
2	1	Rear bumper right bracket	\$ 118.30	xm
3	1	Rear bumper right side retainer	\$ 186.30	xm
4	1	Rear right fender assy	\$ 2,356.20	Rx
5	1	Rear right fender inner cowling	\$ 425.30	xm
6	1	Rear right door panel assy	\$ 2,023.30	bb
7	1	Rear right door outer handle	\$ 489.10	x7
8	1	Rear right door lock mechanism	\$ 372.60	x
9	1	Rear right door lock catch	\$ 82.80	x
10	1	Rear right door upper hinge	\$ 96.30	x
11	1	Rear right door lower hinge	\$ 88.20	x
12	1	Rear right door window regulator linkage	\$ 368.30	x
13	1	Rear right door window regulator motor	\$ 513.20	x
14	1	Rear right door window door chrome frame	\$ 935.60	x
15	1	Rear right door checker linkage	\$ 181.30	x
16	1	Rear right door inner trim board complete assy	\$ 1,206.20	x
17	1	Rear right door weatherstrip	\$ 298.30	cut /
18	1	Rear right taillamp	\$ 767.90	x7
19	1	Rear windscreen glass moulding	\$ 288.80	x
20	1	Rear right quarter glass moulding	\$ 186.30	x
			\$ 13,982.60	2321.60
		less 5%	\$ 699.13	
			\$ 13,283.47	2205.52
<u>Special Nett Items</u>				
1	12	Rear bumper clips	\$ 60.00	xm
2	1	Rear right sport rim	\$ 1,250.00	cut / 1000
3	1	Rear right tyre	\$ 600.00	x
4	1	Rear right fender sealant	\$ 100.00	x
5	6	Rear right fender inner cowling clips	\$ 30.00	x
6	1	Rear right quarter glass sealant	\$ 80.00	x
7	1	Rear windscreen glass sealant	\$ 100.00	x
8	8	Rear right door inner trim board clips	\$ 40.00	x
			\$ 2,260.00	
		Total parts	\$ 15,543.47	(000)

TSL Auto Garage
Blk 4 Joo Chiat Complex
#12-1171 Joo Chiat Road
Singapore 420004

SKR3500D Audi A6

No	Description	Labour Charges
1	Labour for panel beating, cut, weld, straighten front right affected area and replace front right damaged parts.	\$ 1,400.00 800 600
2	To putty and spray painting front right portion.	\$ 1,400.00 2000 600
3	To apply anti rust proofing to front right affected area.	\$ 140.00 30
4	Labour for panel beating, cut, weld, straighten rear right affected area and replace rear right damaged parts.	\$ 1,400.00 600
5	To putty and spray painting rear right portion.	\$ 1,400.00 600
6	To check rear lighting and wiring.	\$ 50.00 30
7	To remove and install rear fuel tank to facilitate the repair.	\$ 180.00 X m
8	To remove and install rear inner garnish and trim to facilitate the repair.	\$ 140.00 60
9	To apply anti rust proofing to rear right affected area.	\$ 140.00 40
10	To remove and install rear windscreen glass to facilitate the repair.	\$ 140.00 X }
11	To remove and install rear right quarter glass.	\$ 80.00 X } m
12	To remove and install front right undercarriage parts.	\$ 350.00 X }
13	To balance front right wheel.	\$ 50.00 30
14	To balance rear right wheel.	\$ 50.00 30
15	To conduct wheel alignment.	\$ 120.00 80
16	To synchronise front right wing mirror for function.	\$ 120.00 30
17	To remove and install front right door lock mechanism.	\$ 80.00 60
18	To remove and install rear right door lock mechanism.	\$ 80.00 60
19	To check front right and rear right door central locking for function.	\$ 80.00 30
20	To transfer front right door glass to new door.	\$ 80.00 } m
21	To transfer rear right door glass to new door.	\$ 80.00 } m
22	To remove and install front right door regulator with motor assy.	\$ 80.00 } X m
23	To remove and install rear right door regulator with motor assy.	\$ 80.00 } X m
24	Towing service.	\$ 100.00 X m
Total labour :		\$ 7,820.00 2880

Tanpoh 97495449
 'wp' 27/10/21 @ 1615
 4/5 Resurvey before paint.
 07 days

Total parts : \$ 38,957.03 9724.30
Total labour : \$ 7,820.00 1230
Total repair cost : \$ 46,777.03 2205.52

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

1000
 2880
 17039.82
 4/5 @ 13,600
 7 days