

ASS. REC. BY: Tanglin REF: CS/CTI 21010889/TIVYS.

**ASSIGNMENT**

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: SJG 6489D

Policy No. DMPCSNW00139442000

Claims No. SNM21D205927/C02/THAMYL

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \$67K.

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: \_\_\_\_\_ days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS WMP'

Vehicle: IN / OUT

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Veh No: SLR3500D Yr Regn: 2015, Jan

Type:  M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or \_\_\_\_\_

Make: Audi A6 C.C. 1984

Colour: Grey A/C: Insured / Std / NI / NA

Sp. Reading: 20917 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: WVAUZZZ4G1FN137822

Gen. Cond:  Good / Fair / Poor / Burnt

Steering:  In order / Jammed / Leaked / Burnt or

Brake:  In order / Jammed / Leaked / Burnt or

Modl: NI / S/Rim / STD A/Rim or

Tyre Size: F: 225/55R17

R: 2 -

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU /  PIR / SUMI /

TOYO / YOKO or \_\_\_\_\_

Front: \_\_\_\_\_ Rear: \_\_\_\_\_

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 15/10/2021 D.O.I. 26/10/21 @ 2pm

Survey held at TSL Auto

Des. of Damages: Frt / Rear /  O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
17/3/22	LS \$13,600 confirmed by email (Red 36,863.03, 73%)

Date/Time, File Pass to?  : Prell. Report  
 : Final Report

Days Of Repair: 7  
 Resurvey No. of Trip: 2

Date/Time, File Return to?  
 2) 4/4/22-typist

Add Fee:  : Site Insp (\$ \_\_\_\_\_)  
 : Interview (\$ \_\_\_\_\_)  
 : Tech. Invs (\$ \_\_\_\_\_)  
 : Weekend (\$ \_\_\_\_\_)

Survey Fee:	_____
Transportation:	_____
S + RS	_____
Photos	_____
Others	_____
TOTAL	_____

Rep. Format: Merimen  
 Lump Sum H.E.A. (\$ 13,600)

**TSL Auto Garage**  
**Blk 4 Joo Chiat Complex**  
**#12-1171 Joo Chiat Road**  
**Singapore 420004**

**SKR3500D Audi A6**

No	Qty	Parts Description	Estimated Parts Price
1	1	Front bumper assy	\$ 3,183.80 <i>de</i>
2	1	Front bumper right bracket	\$ 125.50 <i>x</i>
3	1	Front bumper right retainer	\$ 124.50 <i>ca</i>
4	1	Front right fender	\$ 1,156.20 <i>df</i>
5	1	Front right fender inner cowling	\$ 425.30 <i>x</i>
6	1	Front right door panel assy	\$ 2,458.50 <i>bt</i>
7	1	Front right door inner trim board complete assy	\$ 1,506.20 <i>ca</i>
8	1	Front right door lock mechanism	\$ 371.60 <i>bt</i>
9	1	Front right door lock catch	\$ 82.80 <i>x</i>
10	1	Front right door upper hinge	\$ 96.20 <i>x</i>
11	1	Front right door lower hinge	\$ 88.20 <i>x</i>
12	1	Front right door window regulator linkage	\$ 368.30 <i>x</i>
13	1	Front right door window regulator motor	\$ 513.20 <i>x</i>
14	1	Front right door window door chrome frame	\$ 1,035.60 <i>x</i>
15	1	Front right door weatherstrip	\$ 298.30 <i>x</i>
16	1	Front right door checker linkage	\$ 181.30 <i>x</i>
17	1	Front right door outer handle	\$ 489.10 <i>x</i>
18	1	Front right wing mirror complete assy	\$ 1,637.80 <i>dis</i>
19	1	Front right suspension damper	\$ 1,153.60 <i>x</i>
20	1	Front right kunckle arm	\$ 1,228.60 <i>x</i>
21	1	Front right wheel hub bearing	\$ 388.70 <i>x</i>
22	1	Front right lower control arm	\$ 1,134.80 <i>x</i>
23	1	Front right upper link	\$ 588.60 <i>x</i>
24	1	Front right lower link	\$ 576.80 <i>x</i>
25	1	Front right upper control arm	\$ 1,167.80 <i>x</i>
26	1	Front right 'B' pillar	\$ 1,643.50 <i>x</i>
27	1	Front Headlamp RH <i># 3880 (H1D) ca</i>	\$ 22,024.80
		less 5%	\$ 1,101.24
			<u>\$ 20,923.56</u>

Special Nett Items

1	12	Front bumper clips	\$ 60.00 <i>sona</i>
2	1	Front right sports rim	\$ 1,250.00 <i>cut</i>
3	1	Front right tyre	\$ 600.00 <i>x</i>
4	1	Front no plate with garnish	\$ 100.00 <i>x</i>
5	4	Front right fender cowling clips	\$ 30.00 <i>x</i>
6	10	Front right door inner trim board clips	\$ 50.00 <i>x</i>
7	1	Front right 'B' pillar sealant	\$ 100.00 <i>x</i>
8	1	Front right door sticker	\$ 150.00 <i>ca</i>
9	1	Front right door fender sticker	\$ 150.00 <i>ca</i>
			<u>\$ 2,490.00</u>

**Total parts**

**\$ 23,413.56**

**TSL Auto Garage**  
**Blk 4 Joo Chiat Complex**  
**#12-1171 Joo Chiat Road**  
**Singapore 420004**

**SKR3500D Audi A6**

No	Qty	Parts Description	Estimated Parts Price
1	1	Rear bumper assy	\$ 2,998.30 <del>X</del> R
2	1	Rear bumper right bracket	\$ 118.30 <del>X</del>
3	1	Rear bumper right side retainer	\$ 186.30 <del>X</del>
4	1	Rear right fender assy	\$ 2,356.20 <del>R</del> R
5	1	Rear right fender inner cowling	\$ 425.30 <del>X</del>
6	1	Rear right door panel assy	\$ 2,023.30 <del>bb</del>
7	1	Rear right door outer handle	\$ 489.10 <del>X</del>
8	1	Rear right door lock mechanism	\$ 372.60 <del>X</del>
9	1	Rear right door lock catch	\$ 82.80 <del>X</del>
10	1	Rear right door upper hinge	\$ 96.30 <del>X</del>
11	1	Rear right door lower hinge	\$ 88.20 <del>X</del>
12	1	Rear right door window regulator linkage	\$ 368.30 <del>X</del>
13	1	Rear right door window regulator motor	\$ 513.20 <del>X</del>
14	1	Rear right door window door chrome frame	\$ 935.60 <del>X</del>
15	1	Rear right door checker linkage	\$ 181.30 <del>X</del>
16	1	Rear right door inner trim board complete assy	\$ 1,206.20 <del>X</del>
17	1	Rear right door weatherstrip	\$ 298.30 <del>cut</del> ✓
18	1	Rear right taillamp	\$ 767.90 <del>X</del>
19	1	Rear windscreen glass moulding	\$ 288.80 <del>X</del>
20	1	Rear right quarter glass moulding	\$ 186.30 <del>X</del>
			<hr/>
			\$ 13,982.60
		less 5%	\$ 699.13
			<hr/>
			\$ 13,283.47
		<u>Special Nett Items</u>	
1	12	Rear bumper clips	\$ 60.00 <del>X</del>
2	1	Rear right sport rim	\$ 1,250.00 <del>cut</del> ✓
3	1	Rear right tyre	\$ 600.00 <del>X</del>
4	1	Rear right fender sealant	\$ 100.00 <del>X</del>
5	6	Rear right fender inner cowling clips	\$ 30.00 <del>X</del>
6	1	Rear right quarter glass sealant	\$ 80.00 <del>X</del>
7	1	Rear windscreen glass sealant	\$ 100.00 <del>X</del>
8	8	Rear right door inner trim board clips	\$ 40.00 <del>X</del>
			<hr/>
			\$ 2,260.00
		<b>Total parts</b>	<hr/>
			\$ 15,543.47

**TSL Auto Garage**  
**Blk 4 Joo Chiat Complex**  
**#12-1171 Joo Chiat Road**  
**Singapore 420004**

**SKR3500D Audi A6**

No	Description	Labour Charges
1	Labour for panel beating, cut, weld, straighten front right affected area and replace front right damaged parts.	\$ 1,400.00 <sup>600</sup>
2	To putty and spray painting front right portion.	\$ 1,400.00 <del>1400</del> <sup>600</sup>
3	To apply anti rust proofing to front right affected area.	\$ 140.00 <sup>30</sup>
4	Labour for panel beating, cut, weld, straighten rear right affected area and replace rear right damaged parts.	\$ 1,400.00 <sup>600</sup>
5	To putty and spray painting rear right portion.	\$ 1,400.00 <sup>600</sup>
6	To check rear lighting and wiring.	\$ 50.00 <sup>30</sup>
7	To remove and install rear fuel tank to facilitate the repair.	\$ 180.00 X
8	To remove and install rear inner garnish and trim to facilitate the repair.	\$ 140.00 <sup>60</sup>
9	To apply anti rust proofing to rear right affected area.	\$ 140.00 <sup>40</sup>
10	To remove and install rear windscreen glass to facilitate the repair.	\$ 140.00 X
11	To remove and install rear right quarter glass.	\$ 80.00 X
12	To remove and install front right undercarriage parts.	\$ 350.00 X
13	To balance front right wheel.	\$ 50.00 <sup>30</sup>
14	To balance rear right wheel.	\$ 50.00 <sup>30</sup>
15	To conduct wheel alignment.	\$ 120.00 <sup>80</sup>
16	To synchronise front right wing mirror for function.	\$ 120.00 <sup>30</sup>
17	To remove and install front right door lock mechanism.	\$ 80.00 <sup>60</sup>
18	To remove and install rear right door lock mechanism.	\$ 80.00 <sup>60</sup>
19	To check front right and rear right door central locking for function.	\$ 80.00 <sup>30</sup>
20	To transfer front right door glass to new door.	\$ 80.00 } X
21	To transfer rear right door glass to new door.	\$ 80.00 } X
22	To remove and install front right door regulator with motor assy.	\$ 80.00 } X
23	To remove and install rear right door regulator with motor assy.	\$ 80.00 } X
24	Towing service.	\$ 100.00
<b>Total labour :</b>		<b>\$ 7,820.00</b>

*Tanpikun 97495449*  
*'WP' 27/10/21 @ 1615*  
*1/3 Resurvey before paint.*  
*07 days*

**Total parts : \$ 38,957.03**

**Total labour : \$ 7,820.00**

**Total repair cost : \$ 46,777.03**

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date: