

⏪	<	1	of 2 ?	>	⏩	↺	↻	100%	⏴	⏵	Find Next
---	---	---	--------	---	---	---	---	------	---	---	-------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AIG ASIA PACIFIC INSURANCE PTE LTD		Ref: CS/AIG21010890/Auf3	
78 SHENTON WAY #09-16		Date: 25/10/2021	
AIG BUILDING			
SINGAPORE 079120		Code: AIG	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	GBH 9900C	Veh. Inspected	GBF 2065U
Policy No.	1800028890	Coverage (\$)	0.00
Claim No.	2075813676SG	Excess (\$)	0.00
Assign From	DIVYASHNI SUBRAMANIAM	Assign Date	25/10/2021
2. Vehicle Particulars & Condition			
Make & Model	c.c		0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.	Colour		
Odometer	-	Steering	
Brakes	Modification		
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	20/10/2021	Inspection Date	26/10/2021
Survey held at	CHENG MOTOR WORK CO. NO.1 KAKI BUKIT AVE 6 #01-83 SINGAPORE 417883		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.			