

# CHENG MOTOR WORK CO

1 KAKI BUKIT AVE.6 #01-83  
 SINGAPORE 417883  
 Tel:65551185/6 Fax:65551184  
 H/P: 96713335  
 E-mail:chengmotor27@yahoo.com

JNIMCJ2620006333

AIIG Asia Pacific Insurance Pte. Ltd.  
 78 Shenton Way,09-16  
 AIIG Building  
 Singapore 079120  
 Attn: motor claims Dept

25/10/2021

Hui Zhen.

Estimate cost of repair vehicle no: GBF2065U

Net items

Booth lid <i>Dented</i>	1998.30	<del>1816.</del>
Booth lid rubber <i>cut</i>	134.30	-
Emblem NV350 URVAN <i>New</i>	110.00	-
Booth lid Logo <i>New</i>	64.90	-
2pcs Booth lid side lock \$197.80x2 <i>Green</i>	395.60	+
2pcs booth lid side lock cap \$21.50x2	43.00	x
2pcs booth lid side lock stopper \$10.20x2 <i>New</i>	20.40	x
2pcs booth lid absorber \$239.15 <i>New</i>	478.30	+
2pcs number Plate lamp \$94.10x2 <i>New</i>	188.20	+
Booth lid inner lock <i>Dented</i>	287.10	-
Booth lid lower lock <i>New</i>	198.30	+
Booth lid center chrome <i>Crushed</i>	613.70	+
Booth lid key lock <i>New</i>	85.20	+
Booth lid inner trim board <i>New</i>	226.80	x
Rear bumper <i>Dented</i>	667.20	-
2set bumper side retainer \$65.50x2 <i>New</i>	131.00	-
Rear bumper center step Panel <i>Dented</i>	208.00	✓
1set rear bumper Clip <i>New</i>	65.00	-30
Rear end panel outer <i>Dented</i>	174.10	✓
Rear end Panel inner Panel <i>Rep's</i>	494.15	+
End panel top chrome <i>Best</i>	147.40	✓
Tail lamp L/h <i>Crushed</i>	247.30	✓
Tail lamp R/h <i>New</i>	247.30	x
Rear exhaust pipe	934.70	+
Rear exhaust pipe mounting <i>Green</i>	36.50	+

\$ 4466.30

Less 10%

Less 10%: 4019.67

70 km sticker } *me*  
 8 Pax Sticker } *me*  
 Windscreen Sealant *new*  
 Rear number Plate *new*  
 1set Reserve SENSOR *dayd*

290

~~20.00~~ 15  
~~20.00~~ 15  
 60.00 ✓  
 40.00 +  
 280.00 *2w.*

Labor Charge  
 Check wire  
 To remove/renew reserve SENSOR  
 To remove/refit rear windscreen glass  
 To remove/transfer booth lid mechanical  
 To apply rust-proofing  
 To remove/renew exhaust silencer box  
 To knocking, welding, cutting, repairer and replaced of Parts  
 To spray Paint on the damage Portion

1720

~~60.00~~ 30  
~~100.00~~ 50  
~~150.00~~ 120  
~~150.00~~ 60  
~~200.00~~ 60  
 120.00 +  
~~1000.00~~ 700  
~~1200.00~~ 700

Total \$

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

*Adrian G*  
*L/S 26/10/21*

*06 Days.*

*total: 6029.67*

*L/S: 4.8K.*