



QUOTATION

Customer :

UNITED OVERSEAS INSURANCE LTD
3 ANSON ROAD
#28-01 SPRINGLEAF TOWER
SINGAPORE 079909

*Not Authorized
dhu
25/10/21
2/5
Emp. ph. Attorney
3 days*

NO. : 39355

DATE : 22/10/2021
CLAIM NO. : 11809
POLICY NO. : MC/00914553
FROM : RAYMOND

VEHICLE NO : FBN3461K
MAKE/MODEL : YAM / YBR125

(Page 1 of 3)

S/N	Description	Action	Qty	Unit Price	Amount
1	BAR HANDLE P/N: 42062 - (REPORTED BY MECHANIC)	<i>sent</i> REPLACE	1.00	\$70.00 ✓	70.00
2	COVER TAIL (BLACK) P/N: 61281 <i>LH</i> - (REPORTED BY MECHANIC)	<i>cu)</i> REPLACE	1.00	\$82.00 ✓	82.00
3	COWLING FRONT (BLACK) P/N: 57992 - (REPORTED BY MECHANIC)	<i>cu)</i> REPLACE	1.00	\$149.00 ✓	149.00
4	CRASH BAR P/N: 35878 - (REPORTED BY MECHANIC)	<i>R</i> REPLACE	1.00	\$203.00 X	203.00
5	GASKET EXHAUST PIPE P/N: 24836 - (REPORTED BY MECHANIC)	<i>new</i> REPLACE	1.00	\$6.00 ✓	6.00
6	HEADLAMP ASSY P/N: 43129 - (REPORTED BY MECHANIC)	<i>one</i> REPLACE	1.00	\$147.00 ✓	147.00
7	LABOUR P/N: 06766 - LABOUR QUOTED FOR DISMANTLING AND INSTALLATION OF PARTS.	Supply/Install	5.00	\$63.00 <i>280</i>	315.00
8	LAMP SIGNAL REAR LH P/N: 44190 - (REPORTED BY MECHANIC)	<i>cu)</i> REPLACE	1.00	\$16.00 ✓	16.00
9	LEVER CLUTCH P/N: 52644 - (REPORTED BY MECHANIC)	<i>502</i> REPLACE	1.00	\$19.00 ✓	19.00

*39355 *

bizSAFE₃



S/N	Description	Action	Qty	Unit Price	Amount
10	MIRROR LH P/N: 58099 - (REPORTED BY MECHANIC)	cu) REPLACE	1.00	\$35.00 ✓	35.00
11	MUDUGARD FRONT (BLACK) P/N: 66958 - (REPORTED BY MECHANIC)	cu) REPLACE	1.00	\$119.00 ✓	119.00
12	PIPE EXHAUST ASSY P/N: 50025 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$1,540.00 ?	1,540.00
13	PLATE NUMBER REAR (6.5 INCH X 9 INCH) P/N: 26951 - (REPORTED BY MECHANIC)	Surf REPLACE	1.00	\$28.00 14 s/w	28.00
14	PROTECTOR EXHAUST P/N: 68051 - (REPORTED BY MECHANIC)	cu) REPLACE	1.00	\$77.00 ✓	77.00
15	PROTECTOR EXHAUST CAP P/N: 68052 - (REPORTED BY MECHANIC)	cu) REPLACE	1.00	\$49.00 ✓	49.00
16	RUBBER FOOTREST FRONT P/N: 26136 - (REPORTED BY MECHANIC)	To in REPLACE	1.00	\$14.00 ✓	14.00
17	STAY HEADLAMP P/N: 45750 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$68.00 ?	68.00
18	STICKER (MCDONALDS) SIDE COVER / WINDSHIELD P/N: 56222 - (REPORTED BY MECHANIC)	Replace ✓ neu	1.00	\$16.00 ✓	16.00
19	STICKER NUMBER PLATE FRONT (BLACK) STRAIGHT P/N: 32921 - (REPORTED BY MECHANIC)	✓ Replace neu	1.00	\$20.00 10 s/w	20.00
20	TRANSPORT CHARGES P/N: 07169 - BIKE TOWED BACK TO BHH		1.00	\$56.00 35	56.00

SUB TOTAL	\$3,029.00
GST @ 7 %	\$212.03
GRAND TOTAL (SGD)	\$3,241.03

50% deposit required before ordering of parts.

Validity: 30 days

For & on Behalf of
BAN HOCK HIN CO PTE LTD

*39355 *

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before silver spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:

Acknowledge & Accepted By



> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	288K
Vehicle Details	
Vehicle No.:	FBN3461K
Vehicle to be Exported:	No
Intended Deregistration Date:	25 Oct 2021
Vehicle Make:	YAMAHA
Vehicle Model:	YBR125
Primary Colour:	Black
Manufacturing Year:	2017
Engine No.:	E3F5ED44699
Chassis No.:	LBPRE101000059580
Maximum Power Output:	-
Open Market Value:	\$1,878.00
Original Registration Date:	17 Sep 2018
First Registration Date:	17 Sep 2018
Transfer Count:	0
Actual ARF Paid:	\$282.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	16 Sep 2028
COE Category:	D - Motorcycle
COE Period(Years):	10
QP Paid:	\$4,390.00
COE Rebate Amount:	\$3,026.00
Total Rebate Amount:	\$3,026.00

The information contained herein is correct as at 25 Oct 2021

OK