


ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: SME 8735E
at Workshop m/s 81
of SHF184B
Insured: _____
Policy No. _____
Claims No. TAX/10/21/2056
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

Veh No: SME 8735E Yr Regn: 12/3/15
Type: M.Cat / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or CA1
Make: Honda Vezel c.c. 1496
Colour: 3/466 A/C: Insured / Std / NI / NA
Sp. Reading: 148838 T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: 2411017955
Gen. Cond: Good / Fair / Poor / Burnt
Steering: Inorder / Jammed / Leaked / Burnt or
Brake: Inorder / Jammed / Leaked / Burnt or
Modi: Nil / SRim / STD ARim or
Tyre Size: F: 225/45R17
R: _____



(Policy Condition)
Remark: The veh had commenced its repair at the time of inspection.

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or
Front Rear
R/Bal. 7 mm R/Bal. 7 mm
L/Bal. 7 mm L/Bal. 7 mm
D.O.A. 22/10/21 D.O.I. 25/10/21
Survey held at _____

Bal. or Market Value: \$38k.
IDAC Accident Rport: Consistent? : Yes or No
GIA / PR Seen: Consistent? : Yes or No
Est. Repairs: 5 days Res.: Yes or No
Lum Sum: 20 % 3 Val.: Yes or No
CA / REV / REP. / 24 HRS 578E
Date: _____ Person Contacted: _____
Vehicle: IN / OUT

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
015 Body 2
The U/C Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction Dep 8:50
LTA # 24865 Sel 3 yrs. 4m
NOTY 8/13/15 have video of R/d
have G.A
11/17 d/s \$ 7000 confirmed with AGen. 5 repair days
(RED \$13658.20; 66%)

Date/Time, File Pass to? Preli. Report Final Report
1) 2/11 TYPIST
Date/Time, File Return to?
2)
Report Format : TP
Lump Sum / ~~TP~~ (\$ 7000)
Days Of Repair: 5
Resurvey No. of Trip: 2
Survey Fee: _____
Transportation: _____
Add Fee: Site Insp (\$) S + RS, SI
 Interview (\$) Photos
 Tech. Invs (\$) Others
 Weekend (\$)
TOTAL

FASTECH AUTO PTE LTD

1 Kaki Bukit Ave 6 #01-48 Autobay

Singapore 417883

Tel No: 67452063/ 67467158 Fax No: 67458520

Tax Reg No : 200006262D

* Submit to us alone.

Not Authorized

then

25/10/11

5 days.

1/5 @ 7000

check the other copy.

VEHICLE No: SME 8735E

1PC	FRONT DOOR O/S	1066.30	body DD	\$1,109.20	---
1PC	FRONT DOOR GLASS OUTER Moulding O/S	138.50	net	\$188.50	---
1PC	FRONT DOOR GLASS REGULATOR O/S	292.30	surf/bm	\$305.10	---
1PC	FRONT DOOR GLASS REGULATOR MOTOR O/S	366.40	shroud	\$566.10	---
1PC	FRONT DOOR INNER LOCK O/S	388.10	dayed	\$399.20	---
1PC	FRONT DOOR INNER TRIM BOARD O/S	408.30	de/lor	\$645.10	---
1SET	FRONT DOOR INNER TRIM BOARD CLIPS O/S		net	\$50.00	---
1PC	FRONT DOOR INNER RUBBER O/S	166.50	net	\$185.50	---
1PC	FRONT DOOR MIRROR ASSY O/S		11	\$950.00	X
1PC	FRONT DOOR OUTER HANDLE O/S		11	\$252.20	X
1SET	FRONT DOOR FRAME BLACK STICKER O/S		net	\$80.00	---
1PC	REAR DOOR O/S	966.30	body no	\$1,099.20	---
1PC	REAR DOOR GLASS OUTER Moulding O/S	138.20	net	\$188.50	---
1PC	REAR DOOR GLASS REGULATOR O/S		11	\$305.10	X
1PC	REAR DOOR GLASS REGULATOR MOTOR O/S		11	\$550.00	X
1PC	REAR DOOR INNER LOCK O/S		11	\$399.20	X
1PC	REAR DOOR INNER RUBBER O/S	160.80	net	\$185.50	---
1PC	REAR DOOR INNER TRIM BOARD O/S		11	\$645.10	X
1SET	REAR DOOR FRAME BLACK STICKER O/S		net	\$80.00	---
1PC	REAR DOOR INNER FRT RUBBER STRIP O/S		cut	\$122.00	---
1SET	REAR DOOR LOWER STICKER O/S		net	\$68.00	---
1PC	ROCKER PANEL GARNISH O/S	688.20	ground	\$745.20	---
1SET	ROCKER PANEL GARNISH CLIPS O/S		net	\$48.00	---
1PC	REAR FENDER O/S		R	\$845.80	X
1PC	REAR FENDER OUTER PROTECTOR O/S	246.30	ground	\$299.50	---
1PC	REAR BUMPER	588.20	ground	\$761.00	---
1PC	REAR BUMPER SIDE RH	195.00	de/wood	\$299.50	---
1SET	REAR BUMPER CLIPS		net	\$50.00	---
1PC	REAR SHOCK ABSORBER O/S	246.50	twi	\$282.50	---
1PC	REAR WHEEL HUP BEARING O/S	499.20	dayed	\$650.00	---
1PC	REAR AXLE BEAM		11	\$1,299.30	X
1PC	REAR WHEEL HOUSING PANEL O/S		R	\$781.10	X
1PC	CENTRE PILLAR PANEL O/S		R	\$642.80	X
				\$15,078.20	

S.NETT

1SET	FRONT & REAR DOOR VISOR O/S		net	\$150.00	80 s/n
1PC	REAR SPORT RIM O/S		cut cut	\$900.00	680 s/n
1PC	REAR TYRE O/S		su	\$200.00	X

2%

TO CHECK WIRING	\$50.00	20
TO DISMANTLE & REFIX REAR REVERSE SENSOR	\$80.00	50
TO TRANSFER O/S DOOR MECHANISM	\$150.00	120
TO DISMANTLE & REFIX CUSHION UPHOLSTERY	\$120.00	80
TO DISMANTLE & REFIX FUEL TANK	\$100.00	X
TO DISMANTLE & REPLACED REAR UNDER CARRIAGE	\$380.00	120
TO SPRAY RUST PROOFING	\$150.00	60
TO CONDUCT WHEEL ALIGNMENT	\$120.00	80
TO RESET & REPROGRAMME DIAGNOSIS SYSTEM	\$180.00	80
LABOUR FOR PANEL BEATING & REPLACED PARTS	\$1,200.00	680
TO PUTTY & SPRAY PAINTING	\$1,800.00	1080
TOTAL	\$20,658.20	

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

7-7046.2
 202
 3-563696
 S.N-760
 L-2370
 876696
 2017