



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLM 524U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	FRONT BONNET	TO REPAIR SEE LABOUR	2,774.00	-
1	FRONT BONNET LOCK	TO REPAIR SEE LABOUR	188.00	-
1	FRONT BONNET LOCK CABLE	SERVICEABLE	62.00	-
1	FRONT BONNET LOCK COVER	SERVICEABLE	67.00	-
1	FRONT BONNET LOCK CATCH	TO REPAIR SEE LABOUR	166.00	-
1	FRONT BONNET SEAL	SERVICEABLE	59.00	-
1	FRONT BUMPER	MTG CRACKED	1,882.00	1,882.00
1	FRONT BUMPER REINFORCEMENT	TO REPAIR SEE LABOUR	924.00	-
1	FRONT BUMPER INNER FOAM	SERVICEABLE	122.00	-
2	FRONT BUMPER SIDE RETAINER @\$66.00	SERVICEABLE	132.00	-
1	FRONT BUMPER LOWER LIP	MTG CRACKED	391.00	266.00
2	FRONT FOG LAMP COVER @\$99.00	SERVICEABLE	198.00	-
2	FRONT FOG LAMP INNER COVER @\$92.00	SERVICEABLE	184.00	-
1	FRONT GRILLE	CRACKED	813.00	813.00
1	FRONT GRILLE SIDE COVER	SERVICEABLE	74.00	-
2	HEADLAMP ASSY @\$1670.00	SERVICEABLE	3,340.00	-
1	FRONT FOG LAMP-LH (CRACKED)	NOT CONSISTENT WITH THE IMPACT	266.00	-
	LESS 10% DISCOUNT		-1,164.20	-296.10
			10,477.80	2,664.90
<b><u>SPECIAL NETT ITEMS</u></b>				
1	SET FRONT BONNET INSULATOR CLIP (SN)	NOT NECESSARY	50.00	-
1	SET FRONT BUMPER CLIP (SN)	NECESSARY	50.00	50.00
1	SET FRONT NUMBER PLATE WITH CASING (SN)	DENTED	60.00	45.00
			160.00	95.00
<b><u>LABOUR</u></b>				
	WIRING CHECK AND RECTIFY WHERE NECESSARY.		180.00	20.00

Report Ref No. CS/SMR21010898/Kuf3n2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REMOVE ACCIDENT DAMAGED PARTS IN ORDER RO FACILITATE REPAIRS INCLUDING PANEL BEAT,STRAIGHTEN FRONT CHASSIS AND FRONT SUPPORT PANEL WHERE NECESSARY AND REPLACE ABOVE PARTS.INCLUSIVE OF THE REPAIR OF FRONT BONNET,FRONT BONNET LOCK,FRONT BONNET LOCK CATCH AND FRONT BUMPER REINFORCEMENT.		1,000.00	200.00
	PUTTY AND SPRAY PAINT ACCIDENT AFFECTED AREAS.		1,000.00	500.00
			2,180.00	720.00
<b>GRAND TOTAL</b>			<b>12,817.80</b>	<b>3,479.90</b>
<b>RECOMMENDED COST OF REPAIRS</b>				<b>3,479.90</b>

Report Ref No. CS/SMR21010898/Kuf3n2

**KONG SENG CHEONG**

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.