

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 6214 5151

CO. REG:200707743D GST REG:200707743D

25-Oct-21

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6891 U

Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- This party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

\$ 1,028.00

1 pc	Front ^{n/s} head lamp cr ✓	
1 pc	Bonnet grille XM ✓	
1 pc	Front bumper cr ✓	
1 pc	Front bumper emblem XM ✓	
2 pcs	Front bumper n/s & o/s side retainer @ \$16.00 (1pc) ? XM ✓	
1 pc	Front bumper n/s upper bracket ? XM ✓	
1 pc	Front bumper n/s support bracket ? XM ✓	
1 pc	Front bumper n/s protector XM ✓	
1 pc	Front bumper n/s fog light cover XM ✓	
1 pc	Front door LH XM ✓	
1 pc	n/s door mirror XM ✓	
1 pc	Front n/s wheel cover cr ✓	
1 pc	Front n/s fender repair ✓	
1 pc	Front n/s fender inner shield sur ✓	

\$	385.00	X
\$	531.00	
\$	44.00	X
\$	32.00	X
\$	16.00	X
\$	16.00	X
\$	51.00	X
\$	66.00	X
\$	-	
\$	590.00	X
\$	116.00	
\$	384.00	XR
\$	120.00	
\$	3,379.00	
\$	337.90	
\$	3,041.10	

Repair
4 days
4/5
25/10/21 @ 15:00 hrs
Ready after repair
Less 10%

S/NETT

1 set	Front bumper clips cr ✓	
1 pc	Front n/s fender sticker XM ✓	
1 set	Front n/s fender inner shield clips cr ✓	

\$	48.00	30
\$	30.00	XM
\$	28.00	20

Sundry	
To focus and adjust front n/s & o/s head lamps	
Towing fee	
To check front wheel alignment	
To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the same, etc	
To putty and spray painting on front bumper, front n/s fender, front door LH, side mirror LH	
To apply rustproofing on the repaired and replaced panels.	

\$	50.00	20
\$	60.00	30
\$	50.00	? receipt ✓
\$	80.00	60
\$	650.00	400
\$	800.00	400
\$	80.00	XM
\$	4,917.10	

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511

CO. REG:200707743D GST REG:200707743D

1-Nov-21

SUPPLEMENTARY ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6891 U

2 pcs	Front n/s & o/s Shock absorber @\$330.00 <i>5t</i>	\$	660.00
1 pc	Front n/s stabilizer link <i>5t</i>	\$	86.00
1 pc	Front n/s engine under cover <i>cm</i>	\$	174.00
1 pc	Front o/s engine under cover <i>cm</i>	\$	144.00
		\$	1,064.00
	Less 10%	\$	106.40
		\$	<u>957.60</u>

To dismantle and replace the front n/s undercarriage

\$ ~~150.00~~ *80*

To dismantle and replace the front o/s undercarriage

\$ ~~150.00~~ *80*

160

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT
INCLUDE ANY UNFORESEEN DAMAGES.



1615.50

50.00

960.00

957.60

160.00

3743.10

20%

2,994.48

4s \$3,000

4 days