



INVOICE

TO : AUTOGRAND PTE LTD
C/O: ALPHA PERFORMANCE SINGAPORE PTE. LTD.
48 TOH GUAN ROAD EAST,
#04-126 ENTERPRISE HUB,
SINGAPORE 608586

Invoice No.: 0621/AP990
Date: 15-Jul-2021

PARTICULARS

Vehicle Registration No.: SJR 4474 B
Date of Loss: 24-Jun-2021
Date of Assessment: 29-Jun-2021

SERVICES

FEES

1. Assessment with report Photographs -
Including films, developing, storage and Transport. \$400.00

TOTAL \$400.00

SINGAPORE DOLLARS FOUR HUNDRED ONLY

We would appreciate your cheque crossed and made payable to:
"AEON AUTO CONSULTANTS LLP" with our invoice no. written on the back of the cheque.

AEON AUTO CONSULTANTS LLP



AEON AUTO CONSULTANTS LLP

50 Chin Swee Road #09-04 Thong Chai Building Singapore 169874
Tel: +65 97687958 Fax +65 68264112 Email amas@aeonac.com.sg/amasopm@gmail.com
Reg. No. T07LL1273E (registered with limited liability)

AUTOMOBILE ASSESSMENT REPORT

TO: AUTOGRAND PTE LTD
C/O: ALPHA PERFORMANCE SINGAPORE PTE. LTD.
48 TOH GUAN ROAD EAST,
#04-126 ENTERPRISE HUB,
SINGAPORE 608586

Our Reference: 0621/AP990
Date: 15-Jul-2021

ASSESSMENT OF VEHICLE NO. SJR 4474 B

DATE OF LOSS: 24-Jun-2021

We have carried out a physical assessment at ALPHA PERFORMANCE SINGAPORE PTE. LTD. ,
48 Toh Guan Road East, #04-126 Enterprise Hub, Singapore 608586, according to your instruction
on 29-Jun-2021 and are pleased to submit our report herewith.

1. VEHICLE PARTICULARS

Registration No.: SJR 4474 B
Make & Model: MITSUBISHI LANCER 1.5 MIVEC GLX AT ABS D/AB 2WD 4DR
Year of Registration: 2009
Engine Capacity: 1499
Chassis No.: JMYSRCY2A9U004318
Engine No.: A4910126309
Colour: SILVER
Mileage (km): 158195

2. VEHICLE CONDITION

Exterior Paint: GOOD
Steering: SERVICEABLE
Foot Brake: SERVICEABLE
Parking Brake: SERVICEABLE
Modification: NIL

3. TYRE PARTICULARS & CONDITION

Front
RH Make/Size/Thread: FIRENZA 205/60R16 – 70%
LH Make/Size/Thread: FIRENZA 205/60R16 – 70%

Rear
RH Make/Size/Thread: YOKOHAMA 205/60R16 – 70%
LH Make/Size/Thread: YOKOHAMA 205/60R16 – 70%


4. DESCRIPTION OF DAMAGE

At the time of the inspection, the vehicle sustained damages to the REAR portion.

5. REMARKS

Market Value: Na
Salvage Value: Na
Repair Limit: Na

Estimated Amount: \$5,708.50
Adjusted Amount: \$3,543.00
Loss Sum: \$3,000.00
Estimated Repair Days: 5 days



Pursuant to your instruction, we have **NOT AUTHORISED** repair.

The assessment was conducted on a **"Without Prejudice"** basis.

If we are not notified of anything to the contrary within **14 days** from the date hereof, this report shall be treated as correct.

Disclaimer

This report is intended for the exclusive use of the addressee solely in relation to the loss occurrence in which the assessed vehicle is involved. No liability or responsibility whatsoever shall be held by Aeon Auto Consultants LLP for any reliance on this report by any third party.

ASSESSMENT REPORT FOR VEHICLE NO. SJR 4474 B

PARTS (LIST ITEMS)

Qty	Description	Condition	Workshop's Estimate	Our Assessment
1	REAR BOOTLID	Repair	557.00	nn - +
1	REAR BOOTLID LOCK STRIKER	Bent	28.00	nn 28.00 x
1	REAR BOOTLID MECHANISM LOCK	Bent	58.00	nn 58.00 x
2	REAR TAILLAMP L/R	Repair	508.00	nn - x
2	REAR FENDER INNER SHIELD L/R	Reuse	64.00	m - x
1	REAR BUMPER	Cracked	731.00	731.00 -
1	REAR BUMPER CENTER BEAM	Bent	68.00	nn 68.00 x
2	REAR BUMPER REFLECTOR L/R	Necessary	40.00	40.00 -
1	REAR BUMPER REINFORCEMENT	Bent	169.00	169.00 -
1	REAR BUMPER SIDE RETAINER L/R	Bent	40.00	40.00 -
1	REAR BUMPER TOW COVER	Necessary	20.00	20.00 -
1	REAR END PANEL INNER TOP GARNISH	Cracked	140.00	140.00 -
4	REAR END PANEL INNER TOP GARNISH CLIPS	Necessary	26.00	15 - 26.00
1	REAR END PANEL	Repair	407.00	R - x
1	REAR EXHAUST SILENCER BOX	Repair	359.00	nn - x
			3,215.00	1,320.00
Less 10% discount			321.50	132.00
Parts Total:			2,893.50	1,188.00

ASSESSMENT REPORT FOR VEHICLE NO. SJR 4474 B

SPECIAL NETT ITEMS

2	REAR FENDER INNER SHIELD CLIPS L/R - SET	Necessary	60.00	nn	60.00	x
1	REAR BUMPER CLIPS - SET	Necessary	30.00		30.00	-
1	REAR BUMPER REVERSE SENSOR - SET	Cracked	350.00	200-	350.00	
1	REAR BUMPER NUMBER PLATE	Bent	25.00	20-	25.00	
1	REAR BUMPER NUMBER PLATE HOLDER	Cracked	50.00	30-	50.00	
Special Nett Total :			515.00		515.00	

LABOUR

S/N	Description	Workshop's Estimate	Our Assessment
1	To remove, reinstall electrical wiring harness, check lighting and rewire for parking sensor.	120.00	30- 100.00
2	To remove, reinstall top trim upholstery, cushion seat, trim garnish, trim liner carpet.	80.00	30- 60.00
3	To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.	1,000.00	400- 800.00
4	To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.	1,000.00	400- 800.00
5	To apply anti-rust chemical on repaired and replaced panel.	100.00	30- 80.00
Labour Total :		2,300.00	1,840.00
TOTAL (PARTS & LABOUR) \$		5,708.50	3,543.00

The workshop has agreed to undertake the repair on a Lump Sum basis.

final adjusted Lump Sum contract amount is
\$3,000.00 (SINGAPORE DOLLARS THREE THOUSAND ONLY)

L/S \$1750 4 days



Amas Ong
Automobile Assessor

ALPHA PERFORMANCE SINGAPORE PTE. LTD.

CO.REF: 202035804E
NO 48 TOH GUAN ROAD EAST
#04-130 ENTERPRISE HUB
SINGAPORE 608586
DIRECT LINE: 96472568
TEL: 64683096
FAX: 65155434

Attn: Motor Claims Department
First Capital Insurance Ltd
#10-01 / 02 Robinson Tower
Singapore 048546

Final Bill: APS-14-4474
Date: 03/09/2021
Vehicle No: SJR4474B
Make & Model: Mitsubishi Lancer 1.5
Accident Date: 24/06/2021
Third Party Vehicle: SHC4559T

S/N	DESCRIPTION	AMOUNT
1	REPAIR COST (LUMPSUM)	\$3,000.00

GRAND TOTAL \$3,000.00

Kindly make payment to : ALPHA PERFORMANCE SINGAPORE PTE. LTD.



ALPHA PERFORMANCE SINGAPORE PTE. LTD.