



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile  |   |  |                |
|--|---|--|----------------|
| UNITED OVERSEAS INSURANCE LTD<br>146 ROBINSON ROAD<br>#02-01 UOI BUILDINGSINGAPORE 068909  |   | Ref: CS/UOI21010912/Aqf3e2<br>Date: 31/03/2022<br>Code: UOI2 |                |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM</b>  |   |  |                |
| <b>Insured Veh.</b>  | GBE 361H  | <b>Veh. Inspected</b>  | SLQ 2177D      |
| <b>Policy No.</b>  |   | <b>Coverage (\$)</b>   | 0.00           |
| <b>Claim No.</b>   | M11D13992111  | <b>Excess (\$)</b>   | 0.00           |
| <b>Assign From</b>   | KATIE LEE   | <b>Assign Date</b>   | 25/10/2021     |
| <b>2. Vehicle Particulars &amp; Condition</b>  |   |  |                |
| <b>Make &amp; Model</b>  | MAZDA 6   | <b>c.c</b>   | 1998           |
| <b>Engine No.</b>  | HIDDEN  | <b>Year of Reg.</b>  | 2017           |
| <b>Chassis No.</b>   | JM6GL1071H0118464   | <b>Colour</b>  | GREY           |
| <b>Odometer</b>  | 80461 KM  | <b>Steering</b>  | IN ORDER       |
| <b>Brakes</b>  | IN ORDER  | <b>Modification</b>  | SPORTS RIM     |
| <b>General</b>   | GOOD  |  |                |
| <b>3. Conditions of Tyres</b>  |   |  |                |
|  | <b>Size</b>   | <b>Make</b>  | <b>Balance</b> |
| <b>R/H Front Tyre</b>  | 225/55 R17  | BRIDGESTONE  | 6 mm           |
| <b>L/H Front Tyre</b>  | 225/55 R17  | BRIDGESTONE  | 6 mm           |
| <b>R/H Rear Tyre</b>   | 225/55 R17  | BRIDGESTONE  | 6 mm           |
| <b>L/H Rear Tyre</b>   | 225/55 R17  | BRIDGESTONE  | 6 mm           |
| <b>4. Description of Damages</b>   |   |  |                |
| THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION.<br>DAMAGES SEE DETAILS.  |   |  |                |
| <b>5. General Information</b>  |   |  |                |
| <b>Accident Date</b>   | 22/10/2021  | <b>Inspection Date</b>                                       | 26/10/2021     |
| <b>Survey held at</b>  | XIN HUA WORKSHOP PTE LTD<br>23 KAKI BUKIT AVENUE 4 #04-01 (SOUTH WING) SINGAPORE 415933 |  |                |
| <b>5a. Remarks</b>   |   |  |                |
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |   |  |                |
| <b>5b. Estimate Days of Repair</b>   |   |  |                |
| ESTIMATED NORMAL PERIOD FOR REPAIR:  |   | <b>4 Working Days</b>  |                |