

XIN HUA WORKSHOP PTE LTD

23 Kaki Bukit Avenue 4, #04-01 (South Wing) Singapore 415933

Reg : 201838521G

TPU01

Xiao Chen

Vehicle Number : SLQ2177D
 Vehicle Model : MAZDA 6
 Accident Date : 22.10.2021
 Original Reg Date : 30.06.2017

Date : 25.10.2021
 Chassis : JM6GJ1071H0118464
 TP Ins. : UOI

ESTIMATE

3209

1	1 pc	Headlamp RH <i>cracked</i>		3,369.80	
2	1 set	Headlamp Clips <i>new</i>		30.00	+
3	1 pc	Front Bumper <i>torn</i>		1,245.30	1151
4	1 pc	Front Bumper Side Retainers <i>new</i>		68.90	+
5	1 set	Front Bumper Clips <i>new</i>		50.00	30
6	1 pc	Front Bumper Top Pad		492.50	+
7	1 pc	Front Bumper Top Garnish		158.30	+
8	1 pc	Front Bumper Reinforcement		552.30	+
9	1 pc	Front Bumper Sponge <i>cracked</i>		185.90	+
10	1 pc	Front Bumper Lower Grille		138.50	+
11	1 pc	Front Bumper engine undercover		158.30	+
12	1 pc	Front Bumper Lower reinforcement		98.50	+
13	1 pc	Front Bumper Fog Lamp RH		701.00	+
14	1 pc	Front Bumper Fog Lamp Bracket RH		56.00	+
15	1 pc	Front Bumper Fog Lamp Cover RH		59.60	+
16	1 pc	Front Bumper Fog Lamp Cover Chrome RH <i>new</i>		108.20	+
17	2 pc	Front parking sensors RH	285.60	571.20	+
18	2 pc	Front parking sensors holders RH	45.20	90.40	+
19	1 pc	Front Grille <i>cracked</i>		648.00	517
20	1 pc	Front Grille Badge <i>new</i>		58.20	+
21	1 pc	Front Grille centre bracket		98.30	+
22	2 pcs	Front Grille Outer Chrome Moulding	176.30	352.60	+
23	1 set	Front Grille Clip		30.00	+
24	2 pcs	Front lower grille side bracket	85.90	171.80	+
25	1 pc	Front Fender Inner Shield RH		145.30	+
26	1 pc	Front Fender RH <i>new</i>		398.50	+
27	1 set	Front Fender Inner Shield Clips <i>new</i>		30.00	+
28	1 pc	Front bonnet <i>dented</i>		1,268.50	+
29	1 pc	Front bonnet lock		186.50	+
30	2 pc	Front bonnet hinges	65.20	130.40	+
31	1 pc	Front bonnet inner seal		108.50	+
32	1 pc	Front Support panel		578.30	+

6419.60

12,339.60

5135.68

Less 20%

2,467.92

subtotal

9,871.68

Special Nett

1	1 pc	Front Number Plate with Cover <i>new</i>	50.00	+
---	------	--	-------	---

Labour charge

Panel Beating	1,200.00	400
Spray painting	1,200.00	400
Check Wiring on headlamp	120.00	30
To remove / top up gas	120.00	+
Anti rust	100.00	+
Remove and install front sensor	120.00	50
Total	\$ 12,781.68	

880

*Adrian G
E/S 26/10/21.*

04 Days

*total: 6015.68
E/S: A.81C*

(A.81C)

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: